

To: All Engineering Department, CAMO Department & Operators.

From: CAMO

CC: Quality Assurance Department

Issue: 17 June 2019

Subject: TMI 139-471 Rev C - Tail boom frame STA 8701.6 P/N 3G5350A04353 – Specific Repair  
Procedure

---

Dear All,

Temporary maintenance instruction for AW139 has been published through Leonardo Portal. Kindly refer TMI 139-471 revision C for your acknowledgement. For your information, this TMI not applicable for our aircraft serial number.

Thank You.

  
Shamsul Kamar Bin Samsudin  
Acting Continuing Airworthiness Manager  
17 June 2019