GalaxyAerospace**	
maintenance penair overheul	

Galaxy Aerospace (M) Sdn. Bhd, (1040262-D) No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling Jaya, Selangor Darul Ehsan, Malaysia.

HIRARC REGISTER

 Document No.:
 GALAXY-HSE-SMS

 Release date:
 06 June 2018

 SMS Page:
 APPENDIX C

maintenance, repair, overhaul			Jaya, Selangor Darul Ehsan, Malaysia.			HIRARC REGISTER				SMS Page:	APPENDIX C	
HIRARC NO.:		GAM/SMS/H-33(18)		Date conducted:	06 June 2018	Conducted by:			Nizam (SM)	Approved by:	Mohammad Nizam Jaafar	
Process/ Location:		Additional CAMO office facilities (MIAT)		Revision:	0	F	Received By:		Salman (QAM)	Signature:	Dign	
	Hazard Id		entification			Risk Asses				Risk Control		
No.		Workplace/ Activity	ŀ	Hazard	Consequences/ Effects	Likeli- hood	Severity	Risk Rating	Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks
1	Insert picture here	An additional CAMO office facilities at UniKL MIAT Subang campus to cater of extended CAMO operation	Transition of capability upgraded will implicate interest of the company with non-compliance with authority regulation		The company can't achieve their business opportunities and commercial values	4	D	4D	Admin. Control: Refer to SMS Manual Part 14.2 (Process of management of change MOC)	Admin. Control: Identify gaps and weaknesses to ensure the achievement	SM	Risk reduced to 3D after additional control measure and found on acceptable level
2	Insert picture here	A proper storage and safe facilities for aircraft record and documentation	The unsafe or poor storage facilities will expose to unsafe working environment which lead to affected the documentation		Documentation will exposed to environmental deterioration, theft and fire	5	Е	5E	Admin. Control: Refer to MOE Part 2.14.2 (Technical record control)	Admin. Control: Identify gaps and weaknesses to ensure the documentation is well kept	QAM SM	Risk reduced to 3E after additional control measure and found on acceptable level
3	Insert picture here	New staff has been employed to support the operation	perform function d adequate	n of ability to a prescribed lue to lack and training as per quired	Difficulty to perform a task as per job assigned	4	E	4E	Admin. Control: Refer to MOE Part 3.4.5 (Training and continuation training)	Admin. Control: Adequate training required: #CAME	QAM	Risk reduced to 1E after an additional control measure and found on acceptable level
4	Insert picture here	The office facility will be at MIAT Subang Campus that be at a former technoputra office facilities	the standa requiremer be an un	es do not meet ird of authority nt which lead to isafe working ronment	Improper office facilities will lead to impact on security concern of company interests (assets/important documentation)	4	С	4C	Admin. Control: Refer to SMS Manual Part 13.2 (Safety audits)	Admin. Control: To do an observation for identification of areas for improvement		Risk reduced to 1C after an additional control measure and found was on acceptable level