



MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
<p align="center">*EXTRACTED REPETITIVE/OPEN AIRWORTHINESS DIRECTIVE FROM LEONARDO HELICOPTER MALAYSIA EASA AIRWORTHINESS DIRECTIVE (AIRFRAME) COMPLIANCE SUMMARY. *CONTINUED FROM LEONARDO HELICOPTER MALAYSIA EASA AIRWORTHINESS DIRECTIVE (AIRFRAME) COMPLIANCE SUMMARY LIST SINCE LAST C OF A RENEWAL.</p>					
1	2013-0275R1 DATE: 2013-12-04	AGUSTA BT 139-321 & 139-354	ATA 25 - EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT	-	SUPERSEDED BY EASA AD 2014-0201
2	2013-0298 DATE: 2013-12-30	AGUSTA BT 139-324 REV. A, 139-330, 139-339 & 139-340	ATA 30 -ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM / CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	-	SUPERSEDED BY EASA AD 2014-0028
3	2014-0019 DATE: 17.01.2014	-	EQUIPMENT / FURNISHING - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT	-	SUPERSEDED BY EASA AD 2014-0095
4	2014-0028 DATE: 2014-02-06	AGUSTA BT 139-324 OR REV. A, 139-330, 139-339 OR REV. A & 139-340 REV. A OR REV. B	ATA 30 -ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM / CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	-	SUPERSEDED BY EASA AD 2014-0172
5	2012-0076R2 DATE: 2014-02-27	AGUSTA BT 139-265	TAIL ROTOR - TAIL ROTOR BLADES - INSPECTION / REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	NOT APPLICABLE BY T/R BLADES P/N FITTED. A/C FITTED WITH T/R BLADE P/N 3G6410A00133.
6	2014-0048 DATE: 2014-03-18	AGUSTA BT 139-311	FUSELAGE - SUBFLOOR FRAME STA 2105 - INSPECTION / MODIFICATION	LEONARDO HELICOPTER AD STATUS LIST	NOT APPLICABLE BY A/C SN.
7	2014-0073-E DATE: 2014-03-24	AGUSTA BT 139-368	ATA 62 - MAIN ROTOR - ROTATING CONTROLS - LOWER HALF SCISSOR SPHERICAL BEARING - INSPECTION / REPLACEMENT	-	SUPERSEDED BY EASA EAD 2014-0215-E

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE: EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE: AW139	A/C REGN: 9M-YTL	A/C S/N: 41358	APU TYPE: -
		ENG. TYPE PT6C-67C	ENG #1 S/N: PCE-KB1443	ENG #2 S/N: PCE-KB1457	APU S/N: -


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
8	2014-0172 DATE: 2014-07-31	AGUSTA BT 139-324 OR REV. A, 139-330, 139-339 OR REV. A OR REV. B & 139-340 REV. A OR REV. B	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM / CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	NOT APPLICABLE. KIT FIPS NOT INSTALLED.
9	2014-0201 DATE: 2014-09-19	AGUSTA BT 139-390	ATA 25 - EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	-	SUPERSEDED BY EASA AD 2014-0254
10	2014-0215-E DATE: 2014-09-26	AGUSTA BT 139-392	ATA 62 - MAIN ROTOR - ROTATING SCISSORS - INSPECTION / MODIFICATION	-	SUPERSEDED BY EASA AD 2017-0028-E
11	2014-0254 DATE: 2014-11-24	AGUSTA BT 139-390 REV. A	ATA 25 - EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	-	SUPERSEDED BY EASA AD 2015-0069
12	2006-0357R2 DATE: 2015-05-19	AGUSTA BT 139-018 & 139-089	ATA 53 - FUSELAGE - FRAME 5700 MIDDLE SECTION - INSPECTION	-	SUPERSEDED BY EASA AD 2017-0124R1
13	2015-0155 DATE: 2015-08-11	AGUSTA BT 139404	ICE AND RAIN PROTECTION- FULL ICE PROTECTION SYSTEM TAIL ROTOR SLIP RING - INSPECTION / REPLACEMENT	TIC-AW139-19-052-YTLPG-1	NOT APPLICABLE. KIT FIPS NOT INSTALLED.
14	2016-0077 DATE: 2016-05-03	AGUSTA BT 139-397	LANDING GEAR - MAIN LANDING GEAR SHOCK ABSORBER SCREWS - REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	NOT APPLICABLE. KIT "INCREASED GROSS WEIGHT 6800 Kg" PART NUMBER 4G0000F00111 NOT INSTALLED.
15	2016-0087 DATE: 2016-05-10	FHD BT 139-410 REV A, 139-446 & 139-450	ATA 62 - MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	-	SUPERSEDED BY EASA AD 2016-0140
16	2016-0140 DATE: 2016-07-28	AGUSTA BT 139-450 REV.A & 139-452	ATA 62 - MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	-	SUPERSEDED BY EASA AD 2017-0160

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE: EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE: AW139	A/C REGN: 9M-YTL	A/C S/N: 41358	APU TYPE: -
		ENG. TYPE: PT6C-67C	ENG #1 S/N: PCE-KB1443	ENG #2 S/N: PCE-KB1457	APU S/N: -


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
17	2016-0246 DATE: 2016-12-20	AGUSTA BT 139-274	TAIL ROTOR DRIVE - TAIL GEARBOX CENTRAL HOUSING - DIMENSIONAL CHECK / REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	PARA I: TO BE COMPLIED AT THE FIRST RETURN TO SHOP OR SERVICE STATION FOR TGB OVERHAUL OR REPAIR BUT NOT LATER THAN 7 500 FH ACCUMULATED BY THE TGB. PART II: NOT APPLICABLE DUE TGB NOT YET ACCUMULATED 7 500 FH.
18	2016-0255R1 DATE: 2017-01-24	-	MAIN ROTOR DRIVE - MAIN GEARBOX INPUT MODULE - REPLACEMENT	TIC-AW139-19-052-YTLPG-2	NOT APPLICABLE. COMPONENT NOT AFFECTED.
19	2017-0011 DATE: 2017-02-01	-	TAIL ROTOR - TAIL ROTOR DRIVE SHAFT - INSPECTION / MODIFICATION	TIC-AW139-19-052-YTLPG-3	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER
20	2011-0205R1 DATE: 2017-01-30	AGUSTA BT 139-020	ATA 55 - STABILIZERS - TAIL FIN ASSEMBLY - INSPECTION / REPLACEMENT	-	SUPERSEDED BY EASA AD 2017-0124R1
21	2017-0083 DATE: 2017-05-17	-	MAIN ROTOR - MAIN ROTOR SLIP RING - INSPECTION / REPLACEMENT	TIC-AW139-19-052-YTLPG-4	NOT APPLICABLE. KIT FIPS NOT INSTALLED.
22	2017-0160 DATE: 2017-09-11	AGUSTA BT 139-410, 139-446, 139-450 & 139-452	ATA 62 - MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	-	SUPERSEDED BY EASA AD 2018-0112
23	2017-0175-E DATE: 2017-09-15	AGUSTA BT 139-508	MAIN ROTOR - MAIN ROTOR BLADES - INSPECTION / REPLACEMENT	TIC-AW139-19-052-YTLPG-5	NOT APPLICABLE. MAIN ROTOR BLADES NOT AFFECTED BY SERIAL NUMBER.
24	2017-0124R1 DATE: 2017-12-20	-	ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION	-	SUPERSEDED BY EASA AD 2018-0132
25	2018-0002 DATE: 2018-01-18	AGUSTA SB 139-500	INFORMATION SYSTEMS - PRIMUS EPIC" SYSTEM SOFTWARE - SOFTWARE UPDATE"	WP-YTL-19-571 & DATED 29 AUG 2019	COMPLIED WITH. INSTALLED WITH PRIMUS EPIC FLIGHT SOFTWARE RELEASE 7.14.

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
26	2018-0112R1 DATE: 2018-06-05	AGUSTA BT 139-410, 139-446, 139-450 & 139-452	MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT (cont)	YTL/16-036, DR NO: 358-183 ON 13/7/16 @93:36FH.	PART A, PARA 1: COMPLIED WITH.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 2: TO BE COMPLY BEFORE MR DAMPER EXCEEDING 300 FH.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 3: TO BE COMPLY WITHIN 300 FH AFTER INSTALLATION MR DAMPER ROD END WHICH IS NOT MARKED AS PER FHD BT 139-450 PART II.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 4: TO BE COMPLY ONCE MR DAMPER ROD END REACHING 300 FH OR MORE. (REPETITIVE EVERY PRE OR POST FLT)
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 5: TO BE COMPLY ONCE MR DAMPER ROD END REACHING 300 FH BUT NOT MORE THAN 1200 FH. (REPETITIVE EVERY PRE OR POST FLT)
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 6: FOR INFO ONLY. EDDY CURRENT INSPECTION IS ACCEPTABLE ALTERNATIVE MATHOD TO AN INSPECTION FOR PARA 2, 3, 4, AND 5.
				YTL/16-048, DR NO: 358-206 ON 11 NOV 2016 @ 115:36FH.	PART B, PARA 7: INITIAL COMPLIANCE WITHIN 30FH CARRIED OUT. REPETITIVE INSP EVERY 10FH: COMPLIED WITH. FORECASTED ON AERONET

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
26	2018-0112R1 DATE: 2018-06-05	AGUSTA BT 139-410, 139-446, 139-450 & 139-452	MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	YTL/16-048, DR NO: 358-207 ON 11 NOV 2016 @ 115:36FH.	PART B, PARA 8: INITIAL COMPLIANCE WITHIN 30FH CARRIED OUT, REPETITIVE EVERY 20 FH UNTIL REACHING 600 FH. COMPLIED WITH. FORECASTED ON AERONET.
				2017/YTL/021-02 ON 21 MAR 2017 @ 135:01FH.	PART B, PARA 9: COMPLIED WITH WITHIN 50FH. REPETITIVE EVERY 100FH. FORECASTED ON AERONET
				2017/YTL/021-03 ON 21 MAR 2017 @135:01FH.	PART B, PARA 10: COMPLIED WITH.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 11, 12, 13: CORRECTIVE ACTION FOR PARA 2, 3, 4, 5, 7, 8, 9 AND 10.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 14: BEFORE EXCEEDING 1200 FH, REPLACE MR DAMPER EQUIPED WITH BODY END PN M006-01H002-041 OR M006-01H002-047 WITH MR DAMPER PN 3G6220V01353.
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 15: FOR INFO ONLY
				LEONARDO HELICOPTER AD STATUS LIST	PART B, PARA 16: TERMINATING ACTION FOR ALL REPETITIVE INSPECTION BY REPLACING MR DAMPER 3G6220V01351 OR 3G6220V01352 WITH 3G6220V01353.
				LEONARDO HELICOPTER AD STATUS LIST	PART C, PARA 17: FOR INFO ONLY.

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
27	2018-0130 DATE: 2018-06-25	AGUSTA BT 139-520	MAIN ROTOR - MAIN ROTOR BLADES - INSPECTION	TIC-AW139-19-052- YTLPG-6	NOT APPLICABLE BY MAIN ROTOR BLADES SERIAL NUMBER.
28	2018-0132 DATE: 2018-07-05	AW139 MM CHAPTER IV	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION	TIC-AW139-19-052- YTLPG-7	COMPLIED WITH. CURRENT AMP ALREADY INCORPORATED WITH LATEST AMPI.
29	2018-0208 DATE: 2018-09-27	AGUSTA SB 139-533	EMERGENCY FLOTATION SYSTEM - AFT FLOAT ASSEMBLY INFLATION SYSTEM - REMOVAL / INSTALLATION	TIC-AW139-19-052- YTLPG-8	NOT APPLICABLE. INSTALL WITH DIFFERENCE EMERGENCY FLOAT SYSTEM PART NUMBER.
30	2018-0292 DATE: 2019-01-11	AGUSTA SB 139-569	TAIL ROTOR - TAIL ROTOR SLIDER ASSEMBLY - INSPECTION	TIC-YPG-18-014	APPLICABLE. TO BE CARRIED OUT WHEN AC REACH 2400 FH.
31	2019-0022 DATE: 2019-02-05	AGUSTA SB 139-571	[CORRECTION] TAIL ROTOR - DUPLEX BEARINGS - REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	NOT APPLICABLE. COMPONENT FITTED WITH SN 13146 NOT AFFECTED BY THIS AD.
32	2019-0036 DATE: 2019-03-01	AGUSTA SB 139-567	ATA 63 - MAIN ROTOR DRIVE - MAIN GEARBOX BEARING LOCK NUT - REPLACEMENT	-	SUPERSEDED BY EASA AD 2019-0174
33	2019-0073 DATE: 2019-04-11	AGUSTA ASB 139-580	TAIL ROTOR - FULL ICE PROTECTION SYSTEM TAIL ROTOR BLADES - INSPECTION / REPLACEMENT	TIC-YPG-19-021	NOT APPLICABLE. KIT FIPS NOT INSTALLED.
34	2015-0226 REV. 4 DATE: 2019-06-11	AGUSTA BT 139-443	EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	TIC-AW139-19-012	NOT APPLICABLE. AC NOT FITTED WITH HOIST KIT.
35	2019-0149 DATE: 2019-07-01	AGUSTA SB 139-593	POWERPLANT - ENGINE MOUNTING RODS - REPLACEMENT	TIC-AW139-19-029	NOT APPLICABLE TO ENGINE MOUNTING ROD SERIAL NUMBER.
36	2019-0174 DATE: 2019-08-01	AGUSTA SB 139-567	MAIN ROTOR DRIVE - MAIN GEARBOX BEARING LOCK-NUT - REPLACEMENT	LEONARDO HELICOPTER AD STATUS LIST	APPLICABLE. TO BE PERFORMED WITHIN 2000 LANDINGS UPON REACHING 28000 LANDINGS OR AT NEXT OVERHAUL, WHICHEVER OCCURS FIRST. FOCASTED ON AERONET. DUE ON 38264 LANDING OR DURING OVERHAUL.

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE: EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE: AW139	A/C REGN: 9M-YTL	A/C S/N: 41358	APU TYPE: -
		ENG. TYPE PT6C-67C	ENG #1 S/N: PCE-KB1443	ENG #2 S/N: PCE-KB1457	APU S/N: -


NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
37	2019-0235 DATE: 2019-09-20	ARTEX ELT SYSTEM SB – SB1000	ATA 25 – EQUIPMENT / FURNISHINGS – EMERGENCY LOCATOR TRANSMITTER – INSPECTION / MODIFICATION / REPLACEMENT	REFER: WP-YTL-20-133-001 DATE: 03.02.2020 AT 212:15 FH	ELT REPLACEMENT FOR TERMINATING ACTION FOR REPETITIVE EASA AD 2019-0235.
38	2019-0311 DATE: 2020-01-01	ASB 139-610 SAFRAN SB 025-69-19	ATA 25, 95 - EQUIPMENT/FURNISHINGS, EMERGENCY FLOTATION SYSTEM -INFLATION HOSES - INSPECTION.	REFER: WP-YTL-20-2238-001 DATE: 10.12.2020 AT 239:00 FH	COMPLIED WITH.
39	2020-0011 DATE: 2020-01-29	-	ATA 63 - MAIN GEAR BOX - BEARING LOCK NUT - REPLACEMENT	TIC-AW139-20-006 DATED: 29.01.2020	APPLICABLE DUE TO COMPONENT MGB P/N 3G6320A00135 FITTED ON AIRCRAFT.
40	2020-0013 DATE: 2020-01-29	-	ATA 26 - FIRE PROTECTION - HAND-HELD FRE EXTINGUISHERS - REPLACEMENT	TIC-AW139-20-007 DATED: 30.01.2020	NOT APPLICABLE DUE TO DIFFERENT COMPONENT P/N.
41	2020-0131 DATE: 2020-06-05	-	ATA 25 - EQUIPMENT / FURNISHINGS - HOIST CABLE CUTTER FRAME - MODIFICATION	TIC-AW139-20-094 DATED: 06.06.2020	NOT APPLICABLE DUE TO COMPONENT P/N 3G291V02351 NOT FITTED TO AIRCRAFT.
42	2015-0226 REV. 5 DATE: 2020-07-23	-	ATA 25 - EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	TIC-AW139-20-116 DATED: 25.07.2020	NOT APPLICABLE DUE TO COMPONENT NOT FITTED TO AIRCRAFT.
43	2020-0185 DATE: 2020-08-19	-	ATA 25 – EQUIPMENT / FURNISHINGS – LIFE RAFT RESERVOIR AND ACTUATOR CABLE – REPLACEMENT / INSPECTION	TIC-AW139-20-127 DATED: 21.08.2020	NOT APPLICABLE DUE TO AFFECTED FLOTATION SYSTEM (P/N) 4G9560F00111 OR P/N 4G9560F00211 NOT INSTALLED ON RESPECTIVE AIRCRAFT.

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE: EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE: AW139	A/C REGN: 9M-YTL	A/C S/N: 41358	APU TYPE: -
		ENG. TYPE: PT6C-67C	ENG #1 S/N: PCE-KB1443	ENG #2 S/N: PCE-KB1457	APU S/N: -

NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
44	2020-0191 DATE: 04.09.2020	139-633 REV A	ATA 25 - EQUIPMENT / FURNISHINGS - FORWARD FACING CENTRAL SEAT(S) - REMOVAL	TIC-AW139-20-132 DATED: 07.09.2020	NOT APPLICABLE DUE TO AIRCRAFT SEAT CONFIGURATION NOT INSTALLED FACING FWD.
45	2020-0011 REV. 1 DATE: 20.11.2020	-	ATA 63 - MAIN ROTOR DRIVE - MAIN GEARBOX BEARING LOCK NUT - REPLACEMENT	TIC-AW139-20-193 DATED: 21.11.2020	APPLICABLE DUE TO COMPONENT MGB P/N 3G6320A00135 FITTED ON AIRCRAFT. COMPLIANCE WITHIN 2000 LANDINGS AFTER ACCUMULATING 26000 LANDINGS, OR DURING THE NEXT MGB OVERHAUL, WHICHEVER OCCURS FIRST AFTER THE EFFECTIVE DATE OF THIS AD.
46	2020-0271 DATE: 08.12.2020	SB 139-654	ATA 62 - MAIN ROTOR - SWASHPLATE BOOT - INSPECTION	REFER: WP-YTL-20-2721-001 DATE: 11.01.2021 AT 253:08 FH	COMPLIED WITH.
47	2021-0044 DATE: 05.02.2021	SB 139-661	ATA 24 - ELECTRICAL POWER - OVERHEAD PANEL - INSPECTION	REFER: 9M-YTL-5825-001 DATE: 07.04.2021 AT 255:15 FH	COMPLIED WITH.
48	2021-0054 DATE: 25.02.2021	-	ATA 25 - EQUIPMENT / FURNISHINGS - LIFE RAFT RESERVOIR AND ACTUATOR CABLE - REPLACEMENT / INSPECTION	TIC-AW139-21-0032 DATED: 26.02.2021	NOT APPLICABLE DUE TO COMPONENT EMERGENCY FLOATATION KIT P/N 4G9560F00111 OR P/N 4G9560F00211 NOT FITTED ON AIRCRAFT


MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-

NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
49	2021-0095 DATE: 01.04.2021	-	ATA 11 - PLACARDS AND MARKINGS - STRETCHER UNIT/PLACARD - INSTALLATION	TIC-AW139-21-0209 DATED: 01.04.2021	NOT APPLICABLE DUE TO COMPONENT 3-STRETCHER KIT P/N 139084-5001 NOT EQUIPPED ON AIRCRAFT.
50	2021-0121 DATE: 04.05.2021	-	ATA 63 - MAIN ROTOR DRIVE - MAIN GEARBOX BEARING LOCK NUT - REPLACEMENT	TIC-AW139-21-0228 DATED: 05.05.2021	APPLICABLE DUE TO AFFECTED MGB PN 3G6320A00135 FITTED ON AIRCRAFT. COMPLIANCE WITHIN 2000 LANDING UPON REACHING 26000 LANDINGS OR AT NEXT OVERHAUL, WHICH OCCURS FIRST.
51	2021-0186-E DATE: 06.08.2021	-	ATA 25 - EQUIPMENT/FURNISHINGS - EXTERNAL HOIST ASSEMBLY - RATED LOAD CHECK	TIC-AW139-21-0268 DATED: 07.08.2021	NOT APPLICABLE AIRCRAFT NOT FITTED WITH HOIST.
52	2021-0186 REV. 1 DATE: 18.08.2021	-	ATA 25 - EQUIPMENT/FURNISHINGS - EXTERNAL HOIST ASSEMBLY - RATED LOAD CHECK	TIC-AW139-21-0271 DATED: 19.08.2021	NOT APPLICABLE AIRCRAFT NOT FITTED WITH HOIST.
53	2021-0186 REV. 1 (CORRECTION) DATE: 23.08.2021	-	ATA 25 - EQUIPMENT/FURNISHINGS - EXTERNAL HOIST ASSEMBLY - RATED LOAD CHECK	TIC-AW139-21-0272 DATED: 24.08.2021	NOT APPLICABLE AIRCRAFT NOT FITTED WITH HOIST.

- END OF PAGE -

MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE

	DOCUMENT TITLE:	EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE:	AW139	A/C REGN:	9M-YTL	A/C S/N:	41358	APU TYPE:	-
			ENG. TYPE	PT6C-67C	ENG #1 S/N:	PCE-KB1443	ENG #2 S/N:	PCE-KB1457	APU S/N:	-

NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
-----	--------	---------	-------------	------------------------	---------

PREPARED BY : **NORSHAHEERA IDAYU BINTI MUSTAFA**
Senior Technical Record
Galaxy Aerospace (M) Sdn Bhd
(1040262-D)

DATE : 22 SEP 2021

SIGN & STAMP :

VERIFIED BY :

ZATY NADHIRA BINTI MOHAMED ZUHARI
Continuing Airworthiness Management Manager
Galaxy Aerospace (M) Sdn Bhd
(1040262-D)

DATE :

22/09/2021

SIGN & STAMP :