

MAY 2022

NO	SERVICE BULLETIN NO	ISSUE/REVISION	ISSUE/REVISION DATE	SUBJECT	SERVICE BULLETIN CLASSIFICATION/CATEGORIES	COMPLIANCE TIME	TIC NO.	AIRCRAFT REGN. & COMPLIANCE									REMARKS
								M72-01(31307)			M72-02(31315)			M72-03(31316)			
								NO.1 ENGINE (PCE-KB0175)			NO.1 ENGINE (PCE-KB0740)			NO.1 ENGINE (PCE-KB0742)			
								NO.2 ENGINE (PCE-KB0707)			NO.2 ENGINE (PCE-KB0732)			NO.2 ENGINE (PCE-KB0739)			
								APPLICABILITY	STATUS	WORKPACK REF NO	APPLICABILITY	STATUS	WORKPACK REF NO	APPLICABILITY	STATUS	WORKPACK REF NO	
<b>SERVICE BULLETIN (AIRFRAME)</b>																	
1	139-651	ISSUE	6-May-2022	ATA 34 - Enhanced Ground Proximity Warning System (EGPWS) Computer Conversion to P/N 965-1595-034.	OPTIONAL	CUSTOMER'S OPTION	TIC-M720X-22-0043	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE. COMPONENT NOT FITTED ON AIRCRAFT
2	139-600	ISSUE	6-May-2022	ATA 46 - 'PRIMUS EPIC®' Flight Software Release 8 Upgrade.	OPTIONAL	CUSTOMER'S OPTION	TIC-M720X-22-0024	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH PRIMUS EPIC 5.2.1
3	139-661	REV B	9-May-2022	ATA 24 - OVERHEAD PANEL INSPECTION	ALERT SERVICE BULLETIN	PART I: 25 FH FROM FIRST ISSUE DATE OF SERVICE BULLETIN PART II: REPETITIVE EVERY 300 FH / 1 YEAR	TIC-M720X-22-0021	APPLICABLE	PART I: CLOSED PART II: OPEN	PART I: M72-01-1823-001	APPLICABLE	PART I: CLOSED PART II: OPEN	PART I: M72-02-1800-001	APPLICABLE	PART I: CLOSED PART II: OPEN	PART I: M72-03-1805-001	NIL
4	139-647	ISSUE	10-May-2022	ATA 53 - INTERSEAT CONSOLE CONNECTORS REPOSITIONING	OPTIONAL	CUSTOMER'S OPTION	TIC-M720X-22-0027	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER
5	139-601	REV A	11-May-2022	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	RECOMMENDED	PART I: WITHIN 100 FH OR 3 MONTHS AFTER ISSUE OF SERVICE BULLETIN PART II: WITHIN 200 FH OR 6 MONTHS AFTER ISSUE OF SERVICE BULLETIN	TIC-M720X-22-0028	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE DUE TO AFFECTED COMPONENT PART NUMBER NOT INSTALLED ON AIRCRAFT
6	139-715	ISSUE	16-May-2022	ATA 62 - Main Rotor Blade S/N Marking.	RECOMMENDED	PART I: WITHIN 1 MONTH AFTER ISSUE OF SERVICE BULLETIN PART II: AFTER MRB TIP CAP REPLACEMENT	TIC-M720X-22-0044	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE TO COMPONENT SERIAL NUMBER
7	139-360	REV B	23-May-2022	ATA 24 - Kit Battery Start In Parallel 44 Ah AND 27 Ah.	OPTIONAL	CUSTOMER'S OPTION	TIC-M720X-22-0031	PART I : NOT APPLICABLE PART I : APPLICABLE	CLOSED	-	PART I : NOT APPLICABLE PART I : APPLICABLE	CLOSED	-	PART I : NOT APPLICABLE PART I : APPLICABLE	CLOSED	-	PART I: NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER PART II: NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER PART III: TO BE CARRIED OUT IF REQUIRED IN FUTURE
8	139-669	ISSUE	31-May-2022	ATA 23 - Satcom Flightcell DZMX Electrical Variant Installation.	OPTIONAL	CUSTOMER'S OPTION	TIC-M720X-22-0034	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER