

CIVIL AVIATION AUTHORITY OF MALAYSIA

SAFETY REPORTING FORM

MANDATORY OCCURRENCE REPORTING (MOR)

Final Report

Report No:

MOR180/24

GENERAL INFORMATION

NAME OMAR BIN AHMAD

E-MAIL omar@galaxyaerospace.my

REPORT STATUS CLOSED

OCCURRENCE DATA

RISK GRADE

| Safety Risk Index Range | Safety Risk Description | Recommended Action |
|--|----------------------------|--|
| 5A, 5B, 5C, 4A, 4B, 3A | INTOLERABLE | Take immediate action to mitigate the risk or stop the activity. Perform priority safety risk mitigation to ensure additional or enhanced preventative controls are in place to bring down the safety risk index to tolerable. |
| 5D, 5E, 4C, 4D, 4E, 3B, 3C, 3D, 2A, 2B, 2C, 1A | TOLERABLE | Can be tolerated based on the safety risk mitigation. It may require management decision to accept the risk. |
| 3E, 2D, 2E, 1B, 1C, 1D, 1E | ACCEPTABLE | Acceptable as is. No further safety risk mitigation required. |

1E

| CORRECTIVE | ACTION | TAKEN | (CAT) |
|------------|--------|-------|-------|

| CORRECTIVE ACTION PLAN (CAP) / TEMPORARY MEASURES | | | |
|---|--|--|--|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| ADDITIONAL CORRECTIVE ACTION TAKEN (ADDITIONAL FROM PREVIOUS CAP IF ANY) | | | |
| ADDITIONAL CONNECTIVE ACTION TAKEN (ADDITIONAL TROMT NEVICOS CAL II ANT) | | | |
| Technical Query rasied to OEM for information. | | | |
| 2. Unschedule work package Ref UMC-PMD-24-014 issued for main rotor blade replacement. Replacement | | | |
| carried out satisfactory. | | | |
| SN OFF - AW4236E / SN ON - Q1294E 3. Risk assessment carried out by GAM SMS (Ref GAM/SMS/HRC-003-01/21R1)) with regards to the incident. | | | |
| 5. This Rassessment carried out by GAWI GIVIO (INCI GAWI GIVIO) INTO-005-0 1/2 11(1)) with regards to the incident. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| FINAL DEPOSITS | | | |
| FINAL REPORTS | | | |
| Briefing to be conducted among maintenance crew before towing the aircraft. | | | |
| Aircraft parking arrangement inside the hangar to ensure sufficient space for parking. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |