




DOCUMENT REVISION AMENDMENT FORM

DOCUMENT TITLE & REV.	GADING AIR SERVICES SDN. BHD. AIRCRAFT MAINTENANCE PROGRAMME GASSB/CAMO/AMP/EC120B ISSUE 1 REV 0 DATED 01 MARCH 2022	AMENDMENT REV. & DATE	TEMPORARY REVISION 2, 06 JULY 2023
ITEM	AMENDMENT DESCRIPTION	REASON	
1	Chapter 20, page 17-17: Replace AD 2021-0046 by AD 2023-0036. EASA AD 2021-0046 is superseded by AD 2023-0036.	Repetitive AD Requirements EASA AD 2021-0046 is superseded by EASA AD 2023-0036.	
Prepared by:		Verified by:	Approved By:
			
Name	MUHAMMAD IHSAN BIN MASRI	Name	ZATY NADHIRA BINTI MOHAMED ZUHARI
Designation	TECHNICAL SERVICES ENGINEER	Designation	CONTINUING AIRWORTHINESS MANAGEMENT MANAGER
Date	06 th JULY 2023	Date	06 th JULY 2023
Name		Name	DATO SHAMSUL KAMAR BIN SAMSUDIN
Designation		Designation	QUALITY ASSURANCE MANAGER (ACTING)
Date		Date	06 th JULY 2023
Name		Name	ZULFAIKAR BIN ALANG AHMAD.
Designation		Designation	CONTINUING AIRWORTHINESS MANAGEMENT MANAGER
Date		Date	06 JULY 2023

GADING AIR SERVICES SDN BHD

DOCUMENT TITLE:	AIRCRAFT MAINTENANCE PROGRAMME	AIRCRAFT TYPE:	AIRBUS HELICOPTER EC120B				
PAGE TITLE:	DAILY INSPECTION	REFERENCE:	GASSB/CAMO/AMP/EC120B	ISSUE:	1	REVISION:	0
CHAPTER:	20.0	PAGE:	17 of 17	DATE:	01 MARCH 2022		

AD 2023-0036 – 15 FH / 7D

1.	Attachment bolts of the rotating and stationary scissors.	Visual inspection making sure that the bolts of the rotating and non-rotating scissors do not rotate.	15 FH / 7D
----	---	---	------------

AD 2021-0069 – 15 FH / 7D

1.	Tail rotor hub body	Visual inspection to check for cracks.	15 FH / 7D
----	---------------------	--	------------

TEMPORARY REVISION 2
06.07.2023