
 <b>Galaxy Aerospace</b> maintenance . repair . overhaul	<b>Audit Report</b>	
	Report No.	IAR-2022/044
	Area / Scope	GAM – AMO MIAT
Date of audit		28- 29 Sep 2022

Attachment 3

**MYCAS** MYCOPTER AVIATION SERVICES SDN. BHD. [766012-K]  
 Lot 10, Helicopter Centre, Malaysia International Aerospace Centre (MIAC)  
 Sultan Abdul Aziz Shah Airport,  
 47200 Subang, Selangor, Malaysia.  
 Tel: +603 7496 6499 | www.mycasaviation.com.my

**WORKSHEET**

AIRCRAFT TYPE : AS350 B2 ENGINE : ARRIEL 1D1 WORKSHEET NUMBER : WS-TSL-001  
 MSN : 4532 SN : 19227  
 HOURS : 6210.30 WORK ORDER NUMBER : WO-TSL-001  
 LANDING : 8376 NG/N1 : 7258.10 AIRCRAFT REGISTRATION : 9M-TSL  
 NF/N2 : 7071.80 SHEET : 1 of 1

ISSUED BY : IZWAN SIGN & APPROVAL :  ISSUE DATE : 01.09.2022

DESCRIPTION / WORK TO BE CARRIED OUT	CORRECTIVE ACTION TAKEN / REMARKS
600FH//24 MONTHS AIRFRAME INSPECTION	<input type="checkbox"/> SATISFACTORY <input type="checkbox"/> UNSATISFACTORY

WORK CARD HAS BEEN RAISED AND ATTACHED  SUPPLEMENTARY WORKSHEET/WORK CARD HAS BEEN RAISED AND ATTACHED



MAINTENANCE DATA  
 AIRCRAFT MAINTENANCE PROGRAMME (AMP) : MYCAS/AMP/AS350B2/TSL ISSUE 1, REV 1, 17.08.2022  
 AIRCRAFT MAINTENANCE MANUAL (AMM) : AS350 B2, NRO21, 23.05.2022  
 ENGINE MAINTENANCE MANUAL : ARRIEL 1D1, UPDATE NO. 27, 28.02.2022

PARTS USED LIST / COMPONENT CHANGE RECORD (IF APPLICABLE)							
TASK NO.	DESCRIPTION	PART NO.	REMOVED		INSTALLED		RELEASE DOCUMENT
			SERIAL NO.	TSN/TSO	SERIAL NO.	TSN/TSO	
16	ORING	145 28775-015	-	-	-	-	145 1171-0862
14	C RING	145 28775-127	-	-	-	-	145 1494-10313
62	END BALL	350A33215001	MA115975	-	MA122671	-	MY 1500-10336
62	WASHER/LOCK	23358AC080LE	-	-	-	-	MY 1500-10337
39	BOLT	350A31185421	796369	-	51216	-	MY 1498-10327
39	BOLT	350A31185421	79889	-	57415	-	MY 1498-10328

ADDITIONAL PARTS USED LIST / COMPONENT CHANGE RECORD HAVE BEEN RAISED AND ATTACHED

**MAINTENANCE RELEASE STATEMENT**

\* THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH REQUIREMENTS OF THE MALAYSIAN CIVIL AVIATION REGULATION FOR THE TIME BEING IN FORCE AND IN RESPECT THE AIRCRAFT / EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE.  
 \* THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH REQUIREMENTS OF THE MALAYSIAN CIVIL AVIATION REGULATION FOR THE TIME BEING IN FORCE AND IN RESPECT THE AIRCRAFT / EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE.  
 \* THE AIRCRAFT OR COMPONENT IS CLEAR OF ALL TOOLS, EQUIPMENT AND ANY EXTRANEOUS PARTS OR MATERIAL, AND THAT ALL ACCESS PANELS REMOVED HAVE BEEN FITTED.


INSPECTOR	*CERTIFYING STAFF	COMPLETION DATE
 / MOHD KAMAL		12 SEPT 2022

FORM: MYCAS-CA-037 1 REV.0 01.08.2022

**MYCAS** MYCOPTER AVIATION SERVICES SDN. BHD. [766012-K]  
 Lot 10, Helicopter Centre, Malaysia International Aerospace Centre (MIAC)  
 Sultan Abdul Aziz Shah Airport,  
 47200 Subang, Selangor, Malaysia.  
 Tel: +603 7496 6499 | www.mycasaviation.com.my

**WORKSHEET**

AIRCRAFT TYPE : AS350 B2 ENGINE : ARRIEL 1D1 WORKSHEET NUMBER : WS-TSL-035  
 MSN : 4532 SN : 19227  
 HOURS : 6210.30 WORK ORDER NUMBER : WO-TSL-004  
 LANDING : 8376 NG/N1 : 7258.10 AIRCRAFT REGISTRATION : 9M-TSL  
 NF/N2 : 7071.80 SHEET : 1 of 1

ISSUED BY : IZWAN SIGN & APPROVAL :  ISSUE DATE : 09.09.2022

DESCRIPTION / WORK TO BE CARRIED OUT	CORRECTIVE ACTION TAKEN / REMARKS
TAIL ROTOR HALF LAMINATED BEARING FOUND TORN BEYOND LIMIT DURING 600 HOURS INSPECTION (4 E.A.)	<input checked="" type="checkbox"/> SATISFACTORY <input type="checkbox"/> UNSATISFACTORY
TO PERFORM TAIL ROTOR HALF LAMINATED BEARING REPLACEMENT I.A.W. AMM 64-10-00.A.3 AND AMM 64-10-00.A.4	
OFF PN: 70A433-6333-03 OFF SN: 2119F203, 2119F184, 2119F236, 2119F286	

WORK CARD HAS BEEN RAISED AND ATTACHED  SUPPLEMENTARY WORKSHEET/WORK CARD HAS BEEN RAISED AND ATTACHED



MAINTENANCE DATA  
 AIRCRAFT MAINTENANCE PROGRAMME (AMP) : MYCAS/AMP/AS350B2/TSL ISSUE 1, REV 1, 17.08.2022  
 AIRCRAFT MAINTENANCE MANUAL (AMM) : AS350 B2, NRO21, 23.05.2022  
 ENGINE MAINTENANCE MANUAL : ARRIEL 1D1, UPDATE NO. 27, 28.02.2022

PARTS USED LIST / COMPONENT CHANGE RECORD (IF APPLICABLE)							
TASK NO.	DESCRIPTION	PART NO.	REMOVED		INSTALLED		RELEASE DOCUMENT
			SERIAL NO.	TSN/TSO	SERIAL NO.	TSN/TSO	
CR	BEARING LAMINATED	70A433-6333-03	2119F203	-	4721F087	-	MY 1500-10335
CR	BEARING LAMINATED	70A433-6333-03	2119F184	-	4721F087	-	MY 1500-10334
SR	BEARING LAMINATED	70A433-6333-03	2119F236	-	4721F064	-	MY 1500-10332
SR	BEARING LAMINATED	70A433-6333-03	2119F286	-	4721F066	-	MY 1500-10333

ADDITIONAL PARTS USED LIST / COMPONENT CHANGE RECORD HAVE BEEN RAISED AND ATTACHED

**MAINTENANCE RELEASE STATEMENT**

\* THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH REQUIREMENTS OF THE MALAYSIAN CIVIL AVIATION REGULATION FOR THE TIME BEING IN FORCE AND IN RESPECT THE AIRCRAFT / EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE.  
 \* THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH REQUIREMENTS OF THE MALAYSIAN CIVIL AVIATION REGULATION FOR THE TIME BEING IN FORCE AND IN RESPECT THE AIRCRAFT / EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE.  
 \* THE AIRCRAFT OR COMPONENT IS CLEAR OF ALL TOOLS, EQUIPMENT AND ANY EXTRANEOUS PARTS OR MATERIAL, AND THAT ALL ACCESS PANELS REMOVED HAVE BEEN FITTED.

INSPECTOR	*CERTIFYING STAFF	COMPLETION DATE
 8350		7/9/2022

FORM: MYCAS-CA-037 1 REV.0 01.08.2022

Inconsistent data entered in "Inspector" column. Inspector column on Worksheet Ref No WS-TSL-001 had been entered with the name whereas Worksheet Ref No WS-TSL-035 the column had been signed and printed ID No.