CIVIL AVIATION AUTHORITY OF MALAYSIA

AIRWORTHINESS DIVISION

NON COMPLIANCE	RECORD	Reference No. : NCR/AW/AS/ARS/2021/11/SURV 2022/03
Organisation Area	: GALAXY AEROSPACE MALAYSIA : AIRWORTHINESS REVIEW	NCR level :
1. Requirement: CAD 6802 para 9.1.1		
2. Encountered Condition.		
During ARS surveillance to an approved signatory Mohamad Syafiq (CAAM/AW/AS/ARS/2021/11) at Galaxy Aerospace Malaysia on 1 August 2022, found a discrepancy in ARR ref no: GAM/PSR/PMB/22/08 on the physical survey report. As stated in the physical survey report, checking Tail Boom Exterior for the condition was part of the checklist and it was noted with found satisfactory and nil findings. However, during the surveillance, it was found out, evidence of corrosion build-up on the lower surface of the tail boom area and signs of turning into corrosion powder.		
Airworthiness CAAM Airworthiness CAAM		
Auditor name & Signature: AZ AFZAN ZUHAIRI BIN MOHAMED AZHAR Date: 02 August 2022 3. Corrective Action.(see note #1)		
Auditee name & Sig	gnature:	Date:
4.The corrective act (see notes #2 & #3)	tion has been reviewed, verified and found to	ACCEPTABLE / UNACCEPTABLE
If unacceptable, rea	son for rejecting the corrective action:	
Auditor Name & Sig	nature:	Date :

AWD/002 030303

- Notes: 1. Auditee to respond to this NCR form stating the intended corrective action return to CAAM within 14 days after receiving this report.
 - 2. If the corrective action is not acceptable raise a revised NCR using the same reference number suffixed with revision number.
 - 3. If the corrective action is acceptable, the NCR is closed.