From:	<u>flight ops</u>
To:	Ismail Sulaiman (GAM/CTOO)
Cc:	<u>Shamsul Kamar Samsudin; hasnan@galaxyaerospace.my; emri@galaxyaerospace.my; azlizan; Admin</u> Department
Subject:	AW139 REGN 9M-YTL SN 41358 FUEL TANK CAP LANYARD
Subject.	AWISS REGN SMETTE SN 41550 TOLE TANK CAP LANTARD
Date:	Sunday, 28 November, 2021 9:33:13 PM

Dear Ismail,

With reference to the above, we regret to have not received any defect, replacement or rectification report of **Fuel tank cap lanyard** on 9M-YTL. Today, during refuelling we noticed an unusual lanyard attached to the fuel cap with abnormal wirelock at the inner end.

So far no one from GAM has responded with knowledge of what had been done. The aircraft has just been released after 8Y Insp by GAM Engineering on Friday. Aren't there any more qualified/trained GAM personnel?

Please investigate. We look forward to receiving your report and remedial action soonest.

Capt Dato' Zainal Mat Zain Flight Operations Manager







