

ITEM 9

DEFECT: Qty ; 17 screw missing on lower RH float cover

ACTION PLAN: new screw required



ITEM 12

DEFECT: Missing screw on RH fwd removable panel of control rod access QTY ; 05

ACTION PLAN: new screw required



ITEM 13

DEFECT: missing screw on RH control rod panel inside cabin QTY; 07

ACTION PLAN: new screw required

