

# LOG CARD

## Section 1

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter ..... 35 .....

DESCRIPTION (1)  LIFERAFT RH	P/N (2) 342560V00432	S/N (3) 231	MANUFACTURER NAME (4) AEROSEKUR	ASSEMBLY/MANUFACTURING DATE (5)	RETIREMENT LIFE / TIME LIMITS (6)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTES

### ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL						
DATE (12)	A/C		ASSY		ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON FOR REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
	R. MARKS (13)	TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)			TOTAL FLIGHT HOURS (20)	ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)		
	S/N (14)	TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDINGS SINCE OH (17)			TOTAL LANDINGS (20)	ACTUAL TOTAL LANDINGS (21)	TOTAL LANDINGS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)		
		TOTAL LIFTS/CYCLES (15)	TOTAL LIFTS/CYCLES (16)	LIFTS/CYCLES SINCE OH (17)		TOTAL LIFTS/CYCLES (20)	ACTUAL TOTAL LIFTS/CYCLES (21)		LIFTS/CYCLES SINCE OH (23)			
23-04-2021	M72-02 31315	3373.0 3926	1695.9	1067.1	GAM <i>[Signature]</i> GAM N003 DGTA	23-08-2021	3500.5 3939	1823.4		1194.6	TO SERVICE M72-03	GAM <i>[Signature]</i> GAM N003 DGTA
23-08-21	M72-03 31316	2591.8 3957	1823.4	1194.6	GAM <i>[Signature]</i> GAM N003 DGTA	22-04-22	2699.1 4136	1930.7		1301.9	DUE FOR ANNUAL INSPECTION	GAM <i>[Signature]</i> GAM N010 DGTA
09-05-22	M72-01 31307	4111.5 4536	1930.7	1301.9	GAM <i>[Signature]</i> GAM N010 DGTA	03-06-22	4142.9	1962.1		1333.3	REMOVED FOR PAINTING	GAM <i>[Signature]</i> GAM N010 DGTA
05-06-22	M72-03 31316	2736.2	1962.1	1333.3	GAM <i>[Signature]</i> GAM N010 DGTA	26-09-22	2797.7	2023.6		1374.8	REMOVED TO SERVICE M72-00	GAM
<del>M72-02</del> 26-09-22	<del>M72-02</del> 31315	3969.7	2023.6	1374.8	GAM							



**HRD Aero Systems, Sdn Bhd**  
 Lot# 16683, Jalan Delima 1  
 Kawasan Perindustrian Nilai 3  
 Nilai, Negeri Sembilan Malaysia 71800

FAA CRS# 3HYY536C  
 DCAM AMO/2017/22  
 EASA.145.0732

**TEARDOWN REPORT**

CUSTOMER NAME: GALAXY AEROSPACE		CUSTOMER PO#: PO-21-2685	
HRD WO#: ML 820	MFG P/N: 303017A	S/N: 231	DOM: 05/2010
Reservoir Assy P/N: 45521003	S/N: OL 43265	D.O.M.: 02/2014	Hydrostatic Test Date: 02/2019

**SECTION 1, REMOVAL REPORT.**

Reason for Removal: ANNUAL INSPECTION  Confirmed  Unconfirmed  
 See Section 3  Unit received deployed  Warranty Requested

**SECTION 2, STANDARD TASKS PERFORMED IAW CMM.**

- |   |  |
|---|--|
| <input type="checkbox"/> Functional Test                      | <input checked="" type="checkbox"/> 1 Bottle <input type="checkbox"/> 2 Bottles <input type="checkbox"/> N/A |
| <input checked="" type="checkbox"/> PRV Test                  | <input type="checkbox"/> Hydro Test  |
| <input type="checkbox"/> Proof Pressure Test / Bulk Head Test | <input type="checkbox"/> Valve Overhaul  |
| <input checked="" type="checkbox"/> Air Retention Test        | <input type="checkbox"/> Valve Flow Test   |
| <input checked="" type="checkbox"/> Survival Kit Insp / OH    | <input type="checkbox"/> Hose Pressure Test  |

**SECTION 3, DETAILS OF WORK PERFORMED BELOW**

	PARTS REPLACED	QUANTITY
SPONGE VISCOSE (expanded) -replaced- / FIRST AID (expired) -replaced-	306006A / 306000A	2 / 1
SCREW (used) -replaced- / SCREW (used) -replaced-	V-GB0008 / V-GL0008	4 / 4
WASHER (used) -replaced- / CARD CONTENT (damaged) -replaced-	G-H10038 / 305999A	1 / 1
CLOSING BELT (used) -replaced- / SEAL (used) -replaced-	J-E30003 / 202387A	4 / 1
ANTI SKID (torn) -replaced- / ANTI-SEASICKNESS (expired) -replaced-	A-E70001 / 306014A	1 / 1
RIGHT MECH (broken) -replaced / BREAKING PIN (broken) -replaced-	202905A / 11053009	1 / 1
SCREW (used) -replaced- / SCREW (used) -replaced-	V-GL0005 / V-GB0007	8 / 1
RIGHT FRONTAL PLATE (corroded) -replaced-	314686A	1
AGUSTAWESTLAND P/N: 3G2560V00432, S/N: 231, D.O.M: 05/2010	N/A	N/A
NEXT INSPECTION DUE: 04/2022	N/A	N/A

**SECTION 4, LIFE LIMITED COMPONENTS INSTALLED ON ASSEMBLY**

DESCRIPTION	P/N	S/N	DATE OF MFG	EXP. DATE
CYLINDER / ELT BATT.	L62M / A0696Y	OL 43265 / 118361	(02/14) / (06/18)	(02/29) / (06/23)
FLARE / FIRST AID KIT	306634A / 306000A	N/A	(11/19) / (07/20)	(05/23) / (12/23)
FLASH LIGHT / WATER	304526A / 306009A	N/A	(12/17) / (10/18)	(12/37) / (04/24)
ANTI-SEASICKNESS / RB2	306014A / 306499A	N/A	(11/20) / (06/18)	(10/23) / (05/23)

**SECTION 5, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, or ENGINEERING ORDERS ACCOMPLISHED.**

S.B./A.D./E.O. #	DESCRIPTION
N/A	N/A

EXAMINED AND ACCEPTED BY  
 SIGNATURE OF INSPECTOR:  DATE: 22 APRIL 2021



**HRD Aero Systems, Sdn Bhd**  
 Lot# 16683, Jalan Delima 1  
 Kawasan Perindustrian Nilai 3  
 Nilai, Negeri Sembilan Malaysia 71800

FAA CRS# 3HYY536C  
 DCAM AMO/2017/22  
 EASA.145.0732

**TEARDOWN REPORT**

CUSTOMER NAME: GALAXY AEROSPACE		CUSTOMER PO#: PO-21-2685	
HRD WO#: ML 820	MFG P/N: 303017A	S/N: 231	DOM: 05/2010
Reservoir Assy P/N: 45521003	S/N: OL 43265	D.O.M.: 02/2014	Hydrostatic Test Date: 02/2019

**SECTION 1, REMOVAL REPORT.**

Reason for Removal: ANNUAL INSPECTION  Confirmed  Unconfirmed  
 See Section 3  Unit received deployed  Warranty Requested

**SECTION 2, STANDARD TASKS PERFORMED IAW CMM.**

Functional Test  1 Bottle  2 Bottles  N/A  
 PRV Test  Hydro Test  
 Proof Pressure Test / Bulk Head Test  Valve Overhaul  
 Air Retention Test  Valve Flow Test  
 Survival Kit Insp / OH  Hose Pressure Test

**SECTION 3, DETAILS OF WORK PERFORMED BELOW**

**PARTS REPLACED**

**QUANTITY**

SPONGE VISCOSE (expanded) -replaced- / FIRST AID (expired) -replaced	306006A / 306000A	2 / 1
SCREW (used) -replaced- / SCREW (used) -replaced-	V-GB0008 / V-GL0008	4 / 4
WASHER (used) -replaced- / CARD CONTENT (damaged) -replaced-	G-H10038 / 305999A	1 / 1
CLOSING BELT (used) -replaced- / SEAL (used) -replaced-	J-E30003 / 202387A	4 / 1
ANTI SKID (torn) -replaced- / ANTI-SEASICKNESS (expired) -replaced-	A-E70001 / 306014A	1 / 1
RIGHT MECH (broken) -replaced / BREAKING PIN (broken) -replaced-	202905A / 11053009	1 / 1
SCREW (used) -replaced- / SCREW (used) -replaced-	V-GL0005 / V-GB0007	8 / 1
RIGHT FRONTAL PLATE (corroded) -replaced-	314686A	1
AGUSTAWESTLAND P/N: 3G2560V00432, S/N: 231, D.O.M: 05/2010	N/A	N/A
NEXT INSPECTION DUE: 04/2022	N/A	N/A

**SECTION 4, LIFE LIMITED COMPONENTS INSTALLED ON ASSEMBLY**

DESCRIPTION	P/N	S/N	DATE OF MFG	EXP. DATE
CYLINDER / ELT BATT.	L62M / A0696Y	OL 43265 / 118361	(02/14) / (06/18)	(02/29) / (06/23)
FLARE / FIRST AID KIT	306634A / 306000A	N/A	(11/19) / (07/20)	(05/23) / (12/23)
FLASH LIGHT / WATER	304526A / 306009A	N/A	(12/17) / (10/18)	(12/37) / (04/24)
ANTI-SEASICKNESS / RB2	306014A / 306499A	N/A	(11/20) / (06/18)	(10/23) / (05/23)

**SECTION 5, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, or ENGINEERING ORDERS ACCOMPLISHED.**

S.B./A.D./E.O. #	DESCRIPTION
N/A	N/A

EXAMINED AND ACCEPTED BY  
 SIGNATURE OF INSPECTOR: \_\_\_\_\_

DATE: 22 APRIL 2021