

TECHNICAL BULLETINS (AIRFRAME) COMPLIANCE SUMMARY (MANDATORY)

Aircraft Type: AW139

Serial No. : 41356

Aircraft Regn. No.: 9M-YPG

Engine Type: PT6C-67C

Engine # 1 Serial No. : PCE-KB1419

Engine # 2 Serial No.: PCE-KB1432

Section:

No.	BT Reference	Issue Date	Description	Complied at Hrs/Date	Compliance (Yes/No)	Remarks
176	139-311 Rev. B Mandatory	04/Jun/2014	All AB139/AW139 helicopters from 31005 (except S/N 31007) to S/N 31517 (except S/N's 31415, 31431, 31491, 31500, 31508, 31516) and from S/N 41001 to S/N 41356(except S/N 41355). SUBFLOOR FRAME STA2105 RETROMODIFICATION P/N 3G5306P47211, INSTALLATION OF.	Part I (30Hrs/2Mths): 9:18 Hrs dtd 22 May 2014	Part I: YES Refer Agusta BT Status List AQ15-09 pg 16	
				Part I (300Hrs/6Mths): 30:49 Hrs dtd 30 April 2015	Part I: YES Refer: Job No. YPG/15-002 DR No: 356-035	N/A
				Part II: 129:07 Hrs dtd 27-Oct-2016	Part II: YES Refer: Job No: YPG/16-037 DR No: 356-184	
177	139-372 Mandatory	11/Jun/2014	AW139 helicopters up to S/N 31515 and to S/N 41372 included equipped with Kit FIPS P/N 4G3000F00211. FULL ICE PROTECTION SYSTEM (FIPS) TAIL GEARBOX (TGB) FAIRING	N/A	NO Kit FIPS not installed Refer Agusta BT Status List AQ15-09	N/A
178	139-390 Mandatory	08/Sep/2014	All the AB139/AW139 helicopters equipped with rescue hoist P/N 3G2591V01531 (Goodrich P/N 44316-12-101) and P/N 3G2591V01532 (Goodrich P/N 44316-12-104). All the rescue hoists P/N 3G2591V01531 (Goodrich P/N 44316-12-101) and P/N 3G2591V01532 (Goodrich P/N 44316-12-104) in stock. GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	N/A	pg 16 NO Rescue Hoist Not Installed Refer Agusta BT Status List AQ15-09 pg 16	N/A

Page 33

FORM REF: AWM/CAMO/30 ISSUE 1, REV.0 DTD 16 OCT 2016



Section: 6

TECHNICAL BULLETINS (AIRFRAME) COMPLIANCE SUMMARY (MANDATORY)

Aircraft Type: AW139

Serial No. : 41356

Aircraft Regn. No.: 9M-YPG

Engine Type: PT6C-67C

Engine # 1 Serial No. : PCE-KB1419

Engine # 2 Serial No.: PCE-KB1432

No.	BT Reference	Issue Date	Description	Complied at Hrs/Date	Compliance (Yes/No)	Remarks
239	139-520 ALERT	26-Apr-18	ATA 62 - MAIN ROTOR BLADE TIP CAP RECURRENT INSPECTION Further investigation performed after the issuance of Service Bulletin 139-508 has identified an additional batch of potentially affected MRB. This Service Bulletin prescribes a periodic tapping check on the MRB of this batch, until they reach 1200 FH and, depending on findings, the replacement of the component. For the affected MRB revealing debonding above the permitted limits, the removal and new installation of the tip cap is a terminating action of this Service Bulletin.	N/A	No Not Affected by S/N of MRB	N/A
240	139-533 Alert	30-Aug-18	ATA 95 – EFS AFT Float Assy Inflation System Reset Procedure This Service Bulletin is issued to prescribe a one-off reset procedure of the EFS SMA actuation device.	N/A	NO Not Affected	N/A
241	139-498 Recommended compliance	6-Sep-18	ATA 32 - NLG Servicing Plate Replacement This servise bulletin is issued in order to prescribe the replacement of the reference plat P/N 1661-0063 on a specific batch of NLG/ nose landing strut assemblies.	N/A	NO Not affected	N/A
242	139-528 Recommended compliance	6-Nov-18	ATA 62 - Main Rotor Slip Ring Connector Modification. All MR slip rings P/N 4G6220V00151 up to S/N 0144 (included) installed on AW139 helicopters equipped with Kit FIPS. NOTE MR slip rings having letter "T" affixed after the S/N are not affected by this Service Bulletin.	N/A	No Not Affected due to FIPS not installed	N/A

Prepared by: <u>Alyaa Afifah binti Alzailani</u>



Checked By:
Amir Faisal b. Abi





Concurred by: <u>Wan Nazriazmi b. Mohamad Idris</u>





29 NOV 2019

29 NOV 2018

