

[View All]

PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
ETINS - AIRFRAME								
	SB 27-3459 REV 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/09/2021 ↕	24/09/2022 ↕	150 days ↕	Complete ↕

[View All]

PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
ETINS - AIRFRAME							
	MTL-21-02. NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT		-	-	-	-	NOT APPLICABLE ↕
	MTL-32-02 REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT		-	-	-	-	CANCELLED ↕

With Selected

Repetitive SBs [View All]								
PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
	SB 27-3459 REV 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	23/07/2021 ↕	22/07/2022 ↕	86 days ↕	Complete ↕

[View All]

PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
Standard SBs [View All]							
SERVICE BULLETINS - AIRFRAME							
	MTL-21-02. NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT		-	-	-	-	NOT APPLICABLE ↕
	MTL-32-02 REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT		-	-	-	-	CANCELLED ↕

With Selected

Repetitive SBs [View All]								
PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
	SB 27-3459 REV 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	22/10/2021 ↕	21/10/2022 ↕	178 days ↕	Complete ↕

[View All]

PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
Standard SBs [View All]							
SERVICE BULLETINS - AIRFRAME							
	MTL-21-02. NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT		-	-	-	-	NOT APPLICABLE ↕
	MTL-32-02 REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT		-	-	-	-	CANCELLED ↕

With Selected

Repetitive SBs [View All]								
PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
	SB 27-3459 REV 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	30/08/2021 ↕	02/09/2022 ↕	129 days ↕	Complete ↕

[View All]

PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
Standard SBs [View All]							
SERVICE BULLETINS - AIRFRAME							
	MTL-21-02. NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT		-	-	-	-	NOT APPLICABLE ↕
	MTL-32-02 REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT		-	-	-	-	CANCELLED ↕

With Selected

Repetitive SBs [View All]								
PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
	SB 27-3459 REV 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/07/2021	01/08/2022 ↕	97 days ↕	Complete ↕

[View All]

PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
Standard SBs [View All]							
SERVICE BULLETINS - AIRFRAME							
	MTL-21-02. NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT		-	-	-	-	NOT APPLICABLE ↕
	MTL-32-02 REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT		-	-	-	-	CANCELLED ↕