



SERVICES BULLETINS IMPERATIFS ET RECOMMANDES
MANDATORY AND RECOMMENDED SERVICES BULLETINS

APPAREIL TYPE
AIRCRAFT TYPE

EC 120 B

NUMERO DE SERIE
SERIAL NUMBER

1089

SERVICES BULLETINS IMPERATIFS ET RECOMMANDES
MANDATORY AND RECOMMENDED SERVICE BULLETINS

| No SB | Code I/R/T | Modification | Consignes de nav. <i>Airworthiness directives</i> | Objet <i>Object</i> | Application |
|--------|------------|--------------|--|---|---|
| 01.002 | | | | LIMIT.VOL TROMPETTE GTM/BTP & FERRURE SUPPORT GTM FLIGHT RESTRIC. ARM ASSY ENG/MGB & SUPP. FITTING | NON CONCERNE NO CONCERNED |
| 01-001 | I | | 1999-151-001 (A) | BOITE DE TRANSSION ARRIERE TAIL GEAR BOX | NON CONCERNE NOT CONCERNED |
| 05-001 | T | | 1999-349-002(A) R2 | TROMPETTE DE LIASON BTP/GTM COUPLING FLARED ASSY MGB/ENGINE | REFERENCE NON CONCERNE. CHECEP ATER NOT CONCERNED. |
| 05-002 | R | | | POLLUTION DU CIRCUIT CARBURANT FUEL SYSTEM CONTAMINATION | NON CONCERNE APPRES APPAREIL 1048. NO CONCERNED AFTER A-C NUMBER 1048. |
| 65.002 | R | | | PATTES DE FIXATION DU CARTER B.T.A. ATTACH TAB OF T.G.B. HOUSING. | S/O APRES N. DE SERIE M135. NOT CONCERNED AFTER S/N M135. |
| 65-001 | R | | | BTA AVANT BAGUES EN "TORLON". TAIL GEAR BOX WITH "TORLON" SPLIT. | APPLIQUE. APPLIED. |

I = IMPERATIF / MANDATORY
 R = RECOMMANDE / RECOMMENDED
 T = TELEX SERVICE

Visa des Services Qualité

Quality Department's signature



| | | | |
|--------------------------|-------------------------------|-----------------------|---|
| - SB 32-002 c/w 30/7/02. | - SB 05-004 | - SB 28-004 | - SB 67-005 |
| - SB 21-006 | - SB 52-004R1 | - SB 67A008 | - SB 32-002 |
| - SB 71-003 | - SB 63-003 | - SB 62-007 | - SB 67A009 |
| - SB 52-007 c/w 08/10/13 | - SB 67-017 c/w 05.05.2017 | - SB 56-004 <i>lu</i> | SB 26-001 <i>lu</i> JC# HRSB/2020/0319 |



FIN
END