

WORK ORDER



To: LEONARDO MALAYSIA SDN BHD

Address: Lot 1 & 2, Helicopter Centre
 Sultan Abdul Aziz Shah Airport
 Subang
 Malaysia

Attention: Nur Suzana Noor
 Production Planning & Technical Records Manager
 nursuzana.noor@leonardocompany.com

Work Order Number: 2021-5808
Work Pack Reference: 9M-PMF-5808
Date Issued: 05/02/2021
A/C Registration / SN: 9M-PMF/31913
Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	EASA AD No.: 2021-0044 PARA (1) (ASB 139-661) PART I COMPLIANCE - ATA 24 OVERHEAD PANEL INSPECTION - COMPLIANCE <i>Part I Due at 37:50 FH</i>	EASA AD No.: 2021-0044 ASB 139-661 REV. I	_____ (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my

