



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G1000 NXi Textron Aviation Inc. (Beechcraft) King Air model B200, B200C, B200GT, B200CGT, 300, 300LW, B300, and B300C Owner and Operators

DATE: December 10, 2021

SUBJECT: G1000 NXi STC Audio Wiring Update for King Air B200/300/B300 Series Aircraft

CERTIFICATION AUTHORIZATION: STC SA01535WI-D

COMPLIANCE

Mandatory: This STC Service Bulletin must be accomplished no later than November 30, 2022

PURPOSE

This service bulletin provides instructions for a wiring update to correct low audio levels for warnings as described in Garmin Service Alert 21117.

PRODUCTS AFFECTED

Textron Aviation Inc. (Beechcraft) King Air model B200, B200C, B200GT, B200CGT, 300, 300LW, B300, and B300C aircraft equipped with **all** of the following:

- G1000 NXi Integrated Flight Deck per STC SA01535WI-D
- G1000 NXi System Software Version 2286.11, 2286.12, or 2286.13
- GMA 1360 Audio Panel



NOTE

*King Air model A200, A200CT, 200, and 200C aircraft **are not** affected by this Service Bulletin.*

WARRANTY INFORMATION

This Service Bulletin is warranty reimbursable with a deadline of December 31, 2022 after which this upgrade will no longer be reimbursable for labor.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.