



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTX™ 3X5(R) Owner and Operators
DATE: January 7, 2022
SUBJECT: GTX 3X5(R) GPS Software Version 8.2
CERTIFICATION AUTHORIZATION: STC SA01714WI MDL Revision 19

COMPLIANCE

Optional; This STC Service Bulletin may be incorporated at the owner's discretion.

PURPOSE

STC Service Bulletin 22004 provides notification of an update to STC SA01714WI, GTX 3X5(R) with ADS-B AML STC, MDL Revision 19.

Major details of the update are:

- Updated to GTX 3X5 GPS software version 8.2. This software fixes an issue with GPS signal acquisition time and spikes in the velocity vectors when attempting to re-acquire a GPS lock from a momentary drop from certain satellites.
- Added G1000® GDU software version 15.26 for Cirrus Design Corp. SR2X model

There are no new aircraft models or functionality being added to the STC SA01714WI.

PRODUCTS AFFECTED

GTX 3X5(R) units installed using Part 23 ADS-B AML STC SA01714WI are affected.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.