## SERVICE BULLETIN

P&WC S.B. No. 28284R5

# BULLETIN INDEX LOCATOR 72-31-00

TURBOSHAFT ENGINE
DIFFUSER CASE ASSEMBLY - REPLACEMENT OF

MODEL APPLICATION

PW206A, PW206B, PW206B2, PW206C, PW206E, PW207C, PW207D, PW207E, PW207K

Compliance: CATEGORY 7

Summary: The inside diameter of the diffuser case throat area may be over maximum. Introduce

a diffuser case with an increased erosion resistant material.



Aug 02/2006 Revision No. 5: Jun 28/2023 PW200-72-28284 Cover Sheet

#### WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to: VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil,

Quebec J4G 1A1.

Pratt & Whitney Canada Corp. 1000, Marie-Victorin Longueuil, Québec, Canada J4G 1A1 Tél. 450-677-9411



28 June 2023

P&WC S.B. No. 28284R5

## REVISION TRANSMITTAL SHEET TURBOSHAFT ENGINE MODEL PW200

SUBJECT: Pratt & Whitney Canada Service Bulletin No. PW200-72-28284, Rev. No. 5, dated Jun 28/2023 (P&WC S.B. No. 28284R5) DIFFUSER CASE ASSEMBLY - REPLACEMENT OF

Replace your existing copy of this service bulletin with the attached revised bulletin. Destroy the superseded copy.

Please retain this Revision Transmittal Sheet with the revised bulletin.

<u>SUMMARY</u>: This service bulletin is revised to modify the effectivity for the PW207E engines.

### EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT:

None.

NOTE: A black bar in the left margin indicates a change in that line of text or figure.

### **REVISION HISTORY:**

Original Issue: Aug 02/2006 Revision No. 1: Oct 24/2006 Revision No. 2: Feb 13/2007 Revision No. 3: Mar 23/2007 Revision No. 4: Apr 24/2013 Revision No. 5: Jun 28/2023



### PRATT & WHITNEY CANADA **SERVICE BULLETIN**

P&WC S.B. No. 28284R5

### TURBOSHAFT ENGINE DIFFUSER CASE ASSEMBLY - REPLACEMENT OF

### 1. Planning Information

### A. Effectivity

PW206A Engines.

PW206B Engines.

PW206B2 Engines which are before and include Serial No. BJ0495.

PW206C Engines which are before and include Serial No. BC0674.

PW206E Engines which are before and include Serial No. BE0048.

PW207C Engines which are before and include Serial No. BH0159.

PW207D Engines which are before and include Serial No. BF0157.

PW207E Engines which are before and include Serial No. BG0110.

PW207K Engines which are before and include Serial No. BK0036.

### B. Concurrent Requirements

None.

### C. Reason

### (1) Problem

The inside diameter of the diffuser case throat area may be over maximum.

### (2) Cause

The diffuser case throat area can erode.

### (3) Solution

Replace the diffuser case with one with an increased erosion resistant material.

### D. Description

Replace the diffuser case assembly.

### E. Compliance

CATEGORY 7 - You can do this service bulletin when the supply of superseded parts is fully used.

#### F. Approval

The technical content of this document is approved under the authority of the Transport Canada Civil Aviation (TCCA) Design Approval Organization No: DAO #93-Q-01.

### G. Manpower

No more man-hours are necessary to include this service bulletin at overhaul.

P&WC No. D4807D, DCR4123, D4807L, D4807M, EC-0080611.

Aug 02/2006 P&WC Proprietary Information. Subject to the restrictions on the back of the locator Revision No. 5: Jun 28/2023 © 2006 Pratt & Whitney Canada Corp. PRINTED IN CANADA

PW200-72-28284 Page 1 of 3

## SERVICE BULLETIN

P&WC S.B. No. 28284R5

## TURBOSHAFT ENGINE DIFFUSER CASE ASSEMBLY - REPLACEMENT OF

### 1. Planning Information (Cont'd)

### H. Weight and Balance

None.

### I. Electrical Load Data

Not changed.

### J. Software Accomplishment Summary

Not changed.

### K. References

Applicable PW200 Technical Manuals

### L. Publications Affected

Applicable PW200 Technical Manuals

### M. Interchangeability and Intermixability of Parts

Interchangeability - Refer to Para. 2.C.

Intermixability - Not changed.

### 2. Material Information

### A. Industry Support Information

Not applicable.

### B. Material - Cost and Availability

You can get the procurable parts listed in Para. 2.C. from any Pratt & Whitney Canada Parts Distribution Center.

The estimated total cost of new parts needed to replace old parts is \$Quote (US, 2013).

The new parts are available.

 $Aug~02/2006 \\ Power Proprietary Information. Subject to the restrictions on the back of the locator Revision~No.~5: Jun~28/2023$ 

PW200-72-28284 Page 2 of 3

## SERVICE BULLETIN

P&WC S.B. No. 28284R5

## TURBOSHAFT ENGINE DIFFUSER CASE ASSEMBLY - REPLACEMENT OF

### C. Material Necessary for Each Engine

The quantity of materials listed in this section is on a per Engine basis.

New P/N	Keyword	Old P/N	Qty	Est. Unit List Price (\$US, 2013)	Instructions Disposition
NEW F/IN	Reyword	Old F/IN	Qty	2013)	Disposition
3070471-01	Case Assembly, Diffuser	3045126-01	1	78477.00	(A)(B)
3070483-01	<ul> <li>Case Assembly, Diffuser (Welded)</li> </ul>	3123469-01	1	NP	

- (A) TWO WAY INTERCHANGEABLE (ATA 200 Explanation Code 02): The old or the new part can replace the old or the new part.
- (B) Discard the part if it is unserviceable. Return a serviceable part to stock.
  - D. Reidentified Parts

None.

E. Tooling - Price and Availability

Not applicable.

### 3. Accomplishment Instructions

- A. Remove the parts listed under old P/N in Para. 2.C., Material Information, per the applicable overhaul manual instructions.
- B. Install the parts listed under New P/N in Para. 2.C., Material Information, per the applicable overhaul manual instructions.
- C. Write accomplishment of P&WC S.B. No. 28284 in the applicable engine module log book.

### 4. Appendix

A. Refer to Figure 1 for the progression of the part.

Aug 02/2006 Power Proprietary Information. Subject to the restrictions on the back of the locator Revision No. 5: Jun 28/2023

**PW200-72-28284** Page 3 of 3