


Information Notice

SUBJECT: EQUIPMENT AND FURNISHINGS

Change of method for replacing the battery of the KANNAD ELT beacon



APPAREIL(S) CONCERNE(S)	Version(s)	
	Civile(s)	Militaire(s)
EC120	B	
AS350	B, BA, B1, B2, B3	
AS550		C3
AS355	E, F, F1, F2, N, NP	
AS555		SN
EC130	B4, T2	
AS365	N, N1, N2, N3	F, Fs, K
AS565		MA, MB, SA, SB, UB, MBe
EC155	B, B1	
SA330	J	Ba, L, Jm
EC225	LP	
EC725		AP
AS332	C, L, L1, L2	B, B1
AS532		U2, AC, AL, UL
EC175	B	

Effectivity: Any Airbus Helicopters aircraft delivered with a tri-frequency distress beacon KANNAD 406 or INTEGRA whatever type and model.


N° 3848-I-25

Airbus Helicopters would like to inform you through the Orolia Service Letter (see attached document) of the change in the procedure to follow when an aircraft needs to change the ELT beacon battery.

Besides opening the ELT and replacing the battery, the full ELT battery replacement process includes complete testing of the ELT's performance, in order to make sure that your ELT will perform as expected until the next scheduled maintenance operation.

This is why since January 1st 2018, customers are no longer authorized to replace the ELT battery themselves and must contact an approved KANNAD battery replacement center. The Level 2 CMMs are only provided to Kannad Approved Operators and Kannad Approved Battery Replacement Centers.

Here is the Service Letter:



SERVICE LETTER

Kannad Emergency Locator Transmitter

The information and instructions contained in this document have been produced in accordance with Alternative Procedure to DDA EASA AP028.

**KANNAD EMERGENCY LOCATOR TRANSMITTERS (ELTs)
MAINTENANCE / AFTERMARKET POLICY FOR KANNAD ELTs**

1. REASON

This document provides a summary of service items which may be performed on the listed ELTs.
Effective 1st of January 2018, the following policy applies to Kannad ELT service and maintenance.
This Service Letter cancels SL S182X502-25-02, Maintenance Policy for S182X502-XX ELTs and all previous revisions of SL S18XX50X-25-02, Maintenance Policy for Kannad ELTs.

2. EFFECTIVITY

This Service Letter is applicable to the following ELTs manufactured by OROLIA.

KANNAD 406 AP	S1820502-01/-02	STANDARD ELTs
KANNAD 406 AP-H	S1820502-04	
KANNAD 406 AF	S1821502-01/-02	
KANNAD 406 AF (6D)	S1821502-06	
KANNAD 406 AF-H	S1822502-01/-02	
KANNAD 406 AS	S1823502-01/-02	
KANNAD 406 AS-TNC	S1823502-03	
KANNAD 406 SURVIVAL	S1823502-05	
KANNAD 121 AF	S1824502-01/-02	
KANNAD 121 AF-H	S1826502-02	
KANNAD 406 AF-COMPACT	S1840501-01	COMPACT ELTs
KANNAD 406 AF-COMPACT (ER)	S1840501-02	
ELT AP INTEGRA (ER)	S1850501-01	INTEGRA ELTs
ELT AF INTEGRA (ER)	S1851501-01	
ELT AF-H INTEGRA (ER)	S1852501-01	
ELT AP-H INTEGRA (ER)	S1854501-01	
ELT AP INTEGRA	S1850501-02	
ELT AF INTEGRA	S1851501-02	
ELT AF-H INTEGRA	S1852501-02	
ELT AP-H INTEGRA	S1854501-02	
ELT AP INTEGRA (ER-N)	S1850501-03	
ELT AF INTEGRA (ER-N)	S1851501-03	
ELT AF-H INTEGRA (ER-N)	S1852501-03	
ELT AP-H INTEGRA (ER-N)	S1854501-03	

Date: JAN 23/2018
Rev. 04

SL S18XX50X-25-02
Page 1 of 6