





Etc. and Maintenance Release/ C. of M. Issued	Flight Time		No. of Landings	Time Since New		Total Landings	Details of Inspection, Repairs, Etc. and Maintenance Release/ C. of M. Issued
	Hours	Mins		Hours	Mins		

	AIRCRAFT LOG BOOK ENTRY				9M-PEA
	A/C Type	A/C S/N	A/C TT:	A/F Cyc	For details of work performed, refer to Eurocopter Malaysia Work Order no.:
Eurocopter EC 120B	1275	1106:10	1574	2005-386	
The following work performed: Vibration check SB 53-010 - Reinforcement of frame for vibration damper support fitting attachment. Duplicate inspection on dual control for correct locking & correct functioning					
Place and date: Subang, 23 Dec 2005				Sign and stamp: 	

	AIRCRAFT LOG BOOK ENTRY				9M-PEA
	A/C Type	A/C S/N	A/C TT:	A/F Cyc	For details of work performed, refer to Eurocopter Malaysia Work Order no.:
Eurocopter EC 120B	1275	1142:35	1627	2005-423	
The following work performed: 100H/12M inspection. CRS-SMI 2005-423 6M inspection. CRS-SMI 2005-423 Alert Telex 05A006 Rev.0 - Tail Rotor Drive Shaft - Damper Friction Ring on the rear drive shaft Battery Capacity Check s/n K02101 SB 319 72 4003 - FCU AD F-2005-086: Collective torque tube assy Headset jacks cleaned & tested Windshield repaired					
Place and date: Subang, 06 Jan 2006				Sign and stamp: 	

2005-423

--	--	--	--	--	--	--	--