

MODIFICATION

MODIFICATION STATUS LIST

Aircraft Registration:	9M-PMF	Serial No:	31913	Date:	28/02/2023	Page No:	1
Aircraft Hours:	909:10	Landings:	1605.00	Engine 1:	909:10	Engine 2:	909:10

Type	Maintenance Required	Reference	Life At Install	Period	Last Done	Next Due	Remaining
Modifications (Inspection)	MOTOROLA XTL 5000 FM INSTALLATION	MOD. DOC. NO. GAM004/MD REV.4		0 On Condition	-	-	-
Modifications (Inspection)	REMOVAL OF ANCHOR NUT ON RH CIRCUIT BREAKER SIDE PANEL	EOAS/139/21/001		0 On Condition	-	-	-
Modifications (Inspection)	FRAME STA 3120 - SLANTING LONGERON REPAIR	EOAS/139/20/003 Rev.0, SOC NO. SC/2020/106		0 On Condition	-	-	-
Modifications (Inspection)	KIT SOFT LINER INSTALLATION P/N A001A015-K2C935-0	EASA MINOR CHANGE APPROVAL NO. 10066210		0 On Condition	-	-	-
REPETITIVE INSPECTIONS		Reference	Life At Install	Period	Last Done	Next Due	Remaining
Modifications (Inspection)	300H//1Y INSPECTION FWD BULKHEAD INSTALLATION P/N 6AB1AD005-001	EASA STC # 10030342 Rev. 2		300 Airframe Hours	862:55	1162:55	253:45
Modifications (Inspection)	300H//1Y INSPECTION FWD BULKHEAD INSTALLATION P/N 6AB1AD005-001	EASA STC # 10030342 Rev. 2		1 Years	08/12/2022	08/12/2023	278 Days
Modifications (Inspection)	RH CIRCUIT BREAKER SIDE PANEL INSPECTION	SC NO. SC/2021/011, EOAS/139/21/001 REV. 0 PARA E, (PART OF INSPECTION EASA AD 2021-0044, SB139-661 PART II LATEST ISSUED)		300 Airframe Hours	862:55	1162:55	253:45 Hours
Modifications (Inspection)	RH CIRCUIT BREAKER SIDE PANEL INSPECTION	SC NO. SC/2021/011, EOAS/139/21/001 REV. 0 PARA E, (PART OF INSPECTION EASA AD 2021-0044, SB139-661 PART II LATEST ISSUED)		1 Years	06/12/2022	06/12/2023	276 Days
Modifications (Inspection)	EVERY 50FH INSPECTION DEFFERAL FOR REPLACEMENT OF LH AND RH FRAME STA 3120 AND SLANTING LONGERON	SOC NO. SC/2020/080, EOAS/139/20/002		50 Not Applicable	-	-	-
Modifications (Inspection)	DEFFERAL FOR REPLACEMENT OF LH AND RH FRAME STA 3120 AND SLANTING LONGERON	SOC NO. SC/2020/080, EOAS/139/20/002		1200 Not Applicable	-	-	-
Modifications (Inspection)	DEFFERAL FOR REPLACEMENT OF LH AND RH FRAME STA 3120 AND SLANTING LONGERON	SOC NO. SC/2020/080, EOAS/139/20/002		300 Not Applicable	-	-	-
General	INSPECTION ON FRAME STA 3120 REPAIR AREA	TMI-139-533 REV. A DATED 15 DECEMBER 2020		1200 Airframe Hours	347:49	1547:49	638:38 Hours
General	INSPECTION ON FRAME STA 3120 REPAIR AREA	TMI-139-533 REV. A DATED 15 DECEMBER 2020		2 Years	16/02/2022	15/02/2024	347 Days