

ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-YPG	Serial No:	41356	Date:	05/08/2022	Page No:	1
Aircraft Hours:	274:18	Landings:	428.00	Engine 1:	274:18	Engine 2:	274:18

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
ADs						
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL/36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	36	REFER TO TIC-AW139-20-116. APPLICABLE TO 9M-PMA, 9M-PMB,9M-PMD, 9M-PME, 9M-BOC, 9M-BOD. NOT APPLICABLE TO 9M-YPG & 9M-YTL DUE TO COMPONENT NOT FITTED ON AIRCRAFT.
Repetitive ADs	EASA AD 2022-0205 (SB 139-724 REV B) (50FH/6M)	TAIL ROTOR - DAMPER BRACKET - INSPECTION	-	00/00/0000	6	
Repetitive ADs	EASA AD 2022-0205 (SB 139-724 REV B) (50FH/6M)	TAIL ROTOR - DAMPER BRACKET - INSPECTION	0:00	0:00	50	
Repetitive ADs	EASA AD 2015-0226R7 CORRECTION 20 DECEMBER 2021 (SB139-	ATA 25 - EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	0	
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2)(ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	15/04/2021	14/04/2022	12	LAST DONE 9M-YPG-5822 AT 241:49 FH ON 15/04/2021 (AJL 1378)
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2)(ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	241:49	541:49	300	LAST DONE 9M-YPG-5822 AT 241:49 FH ON 15/04/2021 (AJL 1378)
Repetitive ADs	EASA AD 2020-0271 PARA 2 (ASB139-654 PART II)	50FH - ATA 62 MAIN ROTOR SWASHPLATE BOOT INSPECTION	231:57	281:57	50	
Repetitive ADs	2015-0226 REV 7 PARA 3 (SB139-443 REV.A PARA III)	400HL/6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	-	-	400	NOT APPLICABLE TO 9M-YPG DUE TO COMPONENT NOT FITTED ON AIRCRAFT. REFER TO TIC-AW139-20-116.
Repetitive ADs	2015-0226 REV 7 PARA 3 (SB139-443 REV.A PARA III)	400HL/6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	-	-	0	NOT APPLICABLE TO 9M-YPG DUE TO COMPONENT NOT FITTED ON AIRCRAFT. REFER TO TIC-AW139-20-116.
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL/36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	2600	
Repetitive ADs	100FH AD 2018-0112R1 (BT 139-450 REV. D) (PART 6)	MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	223:48	323:48	100	PART B, PARA 9: COMPLIED. REFER JOB NO: YPG/16-054, DR NO: 356-213. TO BE REPETITIVE EVERY 100FH. DUE AT 229:07 HRS