

TIC-AW139-21-0032

EASA AD No.: 2021-0054

ATA 25 - EQUIPMENT / FURNISHINGS - LIFE RAFT RESERVOIR AND ACTUATOR CABLE - REPLACEMENT / INSPECTION.

NOT APPLICABLE DUE TO COMPONENT EMERGENCY FLOATATION KIT P/N 4G9560F00111 OR P/N 4G9560F00211 NOT FITTED ON AIRCRAFT THE APPLICABLE SB: NOT APPLICABLE TO ASB 139-648 AND ASB 139-662

AD/SB ID: 8592

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : ADS Repetitive

Reference/Number: ATA 25 - EQUIPMENT / FURNISHINGS - LIFE RAFT RESERVOIR AND ACTUATOR CABLE - REPLACEMENT / INSPECTION.

Title/Subject: EASA AD No.: 2021-0054 (ASB 139-648 AND ASB 139-662)

Version No:

Reason For Raising:

AD/SB ID: 8592 Close Update Save

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-BFU	Not Applicable	-		0	-	-	Required
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PMA	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PMB	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PMD	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-SAAS	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE