

ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-PMD	Serial No:	31809	Date:	01/09/2022	Page No:	1
Aircraft Hours:	1408:16	Landings:	2486.00	Engine 1:	1408:16	Engine 2:	1408:16

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
ADs						
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	EASA AD 2015-0228 REV 7 PARA 7	2800HL//38M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	0:00	0:00	2600	TIC-AW139-22-0124 DATED 23 MAY 2022. APPLICABLE TO DUE TO COMPONENT GOOGRICH HOIST P/N 44318-12-104 FITTED ON AIRCRAFT. EVERY 39 MONTHS // 2800 HOIST LIFT, OR AT THE NEXT SCHEDULED HOIST OVERHAUL
Repetitive ADs	EASA AD 2015-0228 REV 7 PARA 7	2800HL//38M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	00/00/0000	36	TIC-AW139-22-0124 DATED 23 MAY 2022. APPLICABLE TO DUE TO COMPONENT GOOGRICH HOIST P/N 44318-12-104 FITTED ON AIRCRAFT. EVERY 39 MONTHS // 2800 HOIST LIFT, OR AT THE NEXT SCHEDULED HOIST OVERHAUL
Repetitive ADs	AD 2022-0152-E PARA (7). (SBEA 139-725 REV./ PART IV)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0:00	0:00	0	
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	0:00	0:00	50	TIC-AW139-22-0160 DATED 02 AUGUST 2022 APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLY P/N 3G6420A06131 WITH THE AFFECTED S/N EQUIPPED ON AIRCRAFT.
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	00/00/0000	0	TIC-AW139-22-0160 DATED 02 AUGUST 2022 APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLY P/N 3G6420A06131 WITH THE AFFECTED S/N EQUIPPED ON AIRCRAFT.
Repetitive ADs	EASA AD 2022-0152-E PARA (2)(SBEA 139-725 REV/PART 2)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT(WITHIN 10FH AND EVERY 50FH)	1392:10	1442:10	50	TIC-AW139-22-0157 DATED 27 JULY 2022 9M-PMD-12173 @ 1392:10 FH ON 03.08.2022 (AJL 01149) - 1ST COMPLIANCE
Repetitive ADs	EASA AD 2022-0152 PARA 1 (EASB139-725 REV./ PART1	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT (BFF AND EVERY 10FH)	1405:26	1415:26	10	TIC-AW139-22-0157 27 JULY 2022 9M-PMD-12172 @ 1383:35 FH ON 28.07.2022 (AJL 01145) - 1ST COMPLIANCE
Repetitive ADs	EASA AD 2015-0228R7 CORRECTION 20 DECEMBER 2021 (SB139-	ATA 25 - EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	0	