

ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	05/09/2022	Page No:	1
Aircraft Hours:	140:53	Landings:	236.00	Engine 1:	140:53	Engine 2:	140:53

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
ADs						
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	AD 2022-0152-E PARA (7), (SBEA 139-725 REV./ PART IV)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0:00	2400:00	0	TO BE COMPLIED BEFORE AFFECTED PART REACHED 2400 FH. REFER TIC-AW139-22-0157
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	-	50	TIC-AW139-22-0180 NOT APPLICABLE BY TR DAMPER BRACKET SN (EQUIPMENT LIST REFER). PHYSICAL CX WP NO. 9M-JPM-12189 - NOT APPLICABLE
Repetitive ADs	EASA AD 2022-0152-E PARA (2)(SBEA 139-725 REV/PART 2)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT(WITHIN 10FH AND EVERY 50FH)	-	-	0	NOT APPLICABLE DUE TO AFFECTED PART INSTALLED, HAVING ACCUMULATED LESS THAN 2 400 FH AND THAT HAS NOT BEEN REMOVED AND REINSTALLED ON AN AFFECTED ASSEMBLY. REFER TIC-AW139-22-0157
Repetitive ADs	EASA AD 2022-0152 PARA 1 (EASB139-725 REV./ PART1	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT (BFF AND EVERY 10FH)	-	-	0	NOT APPLICABLE DUE TO AFFECTED PART INSTALLED, HAVING ACCUMULATED LESS THAN 2 400 FH AND THAT HAS NOT BEEN REMOVED AND REINSTALLED ON AN AFFECTED ASSEMBLY. REFER TIC-AW139-22-0157
Repetitive ADs	EASA AD 2015-0226R7 CORRECTION 20 DECEMBER 2021 (SB139-	ATA 25 - EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	0	NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH HOIST. REFER TIC-AW139-22-0124
Repetitive ADs	400HL/6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	2015-0226 REV 7 PARA 3 (SB139-443 REV.A PARA III)	-	-	6	TIC-AW139-21-0138 COMPLIANCE: NOT APPLICABLE. HELICOPTER NOT FITTED WITH HOIST
Repetitive ADs	400HL/6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	2015-0226 REV 7 PARA 3 (SB139-443 REV.A PARA III)	-	-	400	TIC-AW139-21-0120 COMPLIANCE: NOT APPLICABLE, NOT INSTALL WITH GOODRICH HOIST (AIRCRAFT FOR VVIP OPERATION)
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL/36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	36	TIC-AW139-21-0136 COMPLIANCE: NOT APPLICABLE. HELICOPTER NOT FITTED WITH HOIST
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL/36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	2600	TIC-AW139-21-0136 COMPLIANCE: NOT APPLICABLE. HELICOPTER NOT FITTED WITH HOIST