

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

HIGHLIGHT

AMM AMMPM-BB1-HIGHLIGHT

Publication Title **AMM EC155 B-B1
NR012**

Publication Date **2023.02.01**

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE
PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 00-00-00	LIST OF ILLUSTRATIONS	N	2023.02.01			
AMM 05-21-00-214	Inspection - Optional Systems	R	2023.01.12	M	Aircraft build standard changed	Yes
AMM 05-22-00-213B	15-hour or 7-day inspection - MGB POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 05-50-00-222B	Procedure After Vibrations, Resonance or an Abnormal Dynamic Phenomenon - MGB POST 0763C88	R	2022.09.20	I	Information added	No
AMM 05-50-01-213	Measures to be taken after an in-flight collision - MGB POST 0763C88	R	2022.09.20	I	Information added	Yes
AMM 05-50-01-214	Measures to be taken after an MGB overtemperature POST 0763C88	R	2022.09.20	I	Information added	Yes
AMM 05-50-02-221B	Procedure after the Brake is Suddenly Applied to the Main Rotor - MGB POST 0763C88	R	2022.10.27	C	Discrepancy corrected	Yes
AMM 05-50-08-221B	Measures to be taken if there are jerks or jamming of the free wheel - MGB POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 05-50-09-223B	Measures to be taken if lightning strikes the aircraft - MGB POST 0763C88	R	2022.11.10	C	Discrepancy corrected	Yes
AMM 07-00-00-911	General Safety Instructions - Lifting and Hoisting	R	2022.10.21	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 12-30-00-171A	Washing the MGB / TGB for oil change	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 12-30-00-171B	Washing the MGB / TGB for oil change - MGB POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 22-10-00-721B	Functional Tests - Auto-Pilot System After Replacing an Auto-Pilot Module (APM) POST 0722B70	R	2022.10.13	C	Discrepancy corrected	Yes
AMM 22-10-00-811	DELETED	D	2016.09.14			
AMM 22-10-00-812	DELETED	D	2012.09.24			
AMM 23-00-00-991	Location of the radio communication antennas	N	2022.05.03	R	New document unit	Yes
AMM 23-12-03-064	Removal / Installation CCN-955 Control Unit	R	2022.12.19	R	New document unit	Yes
AMM 23-41-02-811	Fault isolation - NAT ICS	N	2022.12.20	F	Form changed	No
AMM 23-92-01-061	Removal / Installation - IRIDIUM GSM Transmitter - Receiver	R	2022.12.19	F	Form changed	No
AMM 24-00-00-761	Measuring the electrical bonding	N	2022.05.09	R	New document unit	Yes
AMM 24-31-01-861	Removal / Installation - Main battery (ALF / BFF)	N	2022.10.11	R	New document unit	Yes
AMM 25-62-01-061	Removal / Installation - Containers	R	2022.10.18	I	Information added	Yes
AMM 25-62-01-062	Removal / Installation - Inflation Cylinders	R	2022.10.18	I	Information added	Yes
AMM 25-63-01-064	Removal / Installation - Shears Squib	R	2022.09.28	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 25-63-01-722	Functional Tests - Hoist Jettison System	R	2022.09.27	C	Discrepancy corrected	Yes
AMM 25-83-01-062	Removal / Installation - Hoisting rings	N	2022.09.29	R	New document unit	Yes
AMM 26-12-00-721	Functional Tests - Baggage Compartment Overheat / Fire Detection System	N	2022.05.06	R	New document unit	Yes
AMM 26-22-01-062	Removal / Installation of the cabin fire extinguisher support POST 0726B30 or POST 0726B32	R	2022.11.30	I	Information added	Yes
AMM 26-22-01-211	Check of cabin fire extinguisher POST 0726B30	R	2022.11.30	I	Information added	No
AMM 26-22-01-212	Check of the cabin fire extinguisher POST 0726B32	N	2022.11.30	R	New document unit	Yes
AMM 26-22-01-222	Weighing of the cabin fire extinguisher POST 0726B30	R	2022.11.30	I	Information added	No
AMM 26-22-01-223	Weighing of the cabin fire extinguisher POST 0726B32	N	2022.11.30	R	New document unit	Yes
AMM 30-41-01-062	Removal / Installation - Windshield-Panel Deicing System Regulator	R	2022.12.19	F	Form changed	No
AMM 30-42-00-061	Removal / Installation - Windshield Wiper Components	R	2022.10.06	I	Information added	No
AMM 30-42-00-721	Functional Tests - Windshield Wipers	R	2022.10.06	I	Information added	No
AMM 30-42-00-821	Adjustment of the windshield wiper brush holder arms POST 0730B40	N	2022.10.06	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 31-60-01-861	VEMD reconfiguration	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 31-60-01-862	Access and Utilization of "MAINT" Mode - CPDS	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 32-40-00-212	Inspection of the half-rims of a wheel	R	2022.06.21	C	Discrepancy corrected	Yes
AMM 32-70-01-061	Removal / Installation - Tail Skid	R	2022.09.29	C	Discrepancy corrected	No
AMM 33-50-03-721	Functional Tests - Helicopter Emergency Exit Lights (HEEL)	R	2023.01.12	M	Aircraft build standard changed	Yes
AMM 34-00-00-991	Location of the radio navigation antennas	N	2022.05.03	R	New document unit	Yes
AMM 34-43-01-061	Removal / Installation - AeroNav series III NCU	R	2022.12.19	C	Discrepancy corrected	No
AMM 34-43-01-063	Removal / Installation AeroNav Series III (GPS) Antenna	R	2022.12.19	C	Discrepancy corrected	No
AMM 34-57-06-721	Functional Tests - EGPWS	N	2022.10.27	R	New document unit	Yes
AMM 34-61-05-721	EURONAV VII functional tests	N	2022.04.29	R	New document unit	Yes
AMM 34-70-00-821	Configuration - Display System	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 34-70-02-721	Functional Tests - Flight Control Display Module	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 45-11-01-721	Functional Test - SSCVFDR	R	2022.09.28	M	Aircraft build standard changed	Yes
AMM 45-11-01-723	Functional test of the water immersion sensor	R	2022.09.28	M	Aircraft build standard changed	Yes
AMM 45-11-01-724	FDR and CVR Data Control	R	2022.09.30	M	Aircraft build standard changed	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 45-11-01-726	Functional Tests - Discrete Signal Checks	R	2022.09.28	M	Aircraft build standard changed	No
AMM 45-11-01-726	Functional Tests - Discrete Signal Checks	R	2022.09.30	M	Aircraft build standard changed	No
AMM 45-11-02-611	Reporting Procedure - Full HUMS	R	2023.01.09	I	Information added	No
AMM 45-11-04-723	DELETED	D	2021.10.28			
AMM 45-11-04-723A	Test of the RIPS module	N	2022.10.06	M	Aircraft build standard changed	No
AMM 45-11-04-723B	Test of the RIPS module POST 0731C04	N	2022.10.12	R	New document unit	Yes
AMM 45-11-04-726	DELETED	D	2021.10.29			
AMM 45-11-04-726A	Functional test of the SSCVFDR - L3COM	N	2022.10.11	M	Aircraft build standard changed	No
AMM 45-11-04-726B	Functional test of the L3COM SSCVFDR POST 0731C04	N	2022.10.12	R	New document unit	Yes
AMM 53-60-00-351	Repair on Frame X6977 of the Tail Boom	R	2022.10.17	C	Discrepancy corrected	Yes
AMM 53-70-00-221	Detailed Inspection - Cabin and Baggage Compartment Floors	R	2022.10.17	C	Discrepancy corrected	Yes
AMM 53-70-00-331	Repairs to Cabin and Cargo-compartment Floor Panels (Aluminum Sheet Honeycomb Sandwich Structure)	R	2022.10.17	I	Information added	Yes
AMM 53-80-00-061	Removal / Installation - Tail Boom	R	2022.10.17	I	Information added	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 53-80-00-331	Repair of a Hole in the Tail Structure Metal Skin with Honeycomb Core	R	2022.04.04	C	Discrepancy corrected	No
AMM 53-80-00-332	Repair of corrosion on front and rear supports of main rotor blades folding poles	R	2022.09.07	C	Discrepancy corrected	Yes
AMM 53-80-00-333	Repair of the lower skin on frame X6630 of the tail boom	R	2022.03.08	C	Discrepancy corrected	Yes
AMM 53-80-00-334	Repair following impact mark on external skin	R	2022.09.07	C	Discrepancy corrected	Yes
AMM 53-80-00-335	Repair following impact mark on internal skin	R	2022.09.07	C	Discrepancy corrected	Yes
AMM 55-10-00-331	Repair of a Hole in the Horizontal Stabilizer	R	2022.09.08	C	Discrepancy corrected	Yes
AMM 55-10-00-332	Repair of Transverse Scores in the Horizontal Stabilizer	R	2022.09.09	C	Discrepancy corrected	Yes
AMM 55-10-00-333	Repair of Longitudinal Scores in the Horizontal Stabilizer	R	2022.09.09	C	Discrepancy corrected	Yes
AMM 55-10-00-334	Repair of a Debonded Joint or Separation of Fabric Plies	R	2022.09.14	C	Discrepancy corrected	Yes
AMM 55-30-00-341	Repair of Debonding in Outboard Fin Main Body (ZONE B)	R	2022.09.14	C	Discrepancy corrected	Yes
AMM 55-30-00-343	Repair of a Perforation on Leading Edge of an Outboard Fin (ZONES A and B)	R	2022.09.15	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 55-30-00-344	Repair of a Perforation in the Body of an Outboard Fin (ZONES B)	R	2022.09.15	C	Discrepancy corrected	Yes
AMM 60-00-00-911	General Safety Instructions - Power Transmission Systems	R	2022.10.18	C	Discrepancy corrected	Yes
AMM 62-23-02-061	Disassembly / Assembly - Swashplates	R	2022.10.18	C	Discrepancy corrected	Yes
AMM 62-24-03-991	Inspection criteria - Blade Horn Assembly	R	2022.11.15	I	Information added	Yes
AMM 62-24-07-991	Inspection Criteria - Spacer Bolt	R	2022.10.13	C	Discrepancy corrected	Yes
AMM 63-00-00-061B	Removal / Installation - MGB / MRH Assembly - MGB POST 0763C88	R	2022.10.28	C	Discrepancy corrected	Yes
AMM 63-10-01-061	Removal / Installation - Coupling Shaft	R	2022.09.20	C	Discrepancy corrected	Yes
AMM 63-10-03-061	Removal / Installation - Drive Flange	R	2022.09.27	I	Information added	No
AMM 63-10-61-061	Removal / Installation - Coupling shaft - MGB POST 0763C88	R	2022.12.06	C	Discrepancy corrected	Yes
AMM 63-10-61-062	Removal / Installation - Links between the rear gimbal joint and the front torque tube - MGB POST 0763C88	N	2022.12.07	R	New document unit	Yes
AMM 63-10-62-991	Inspection criteria for MGB flexible couplings POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-10-63-721	Check of the tightening torque of the drive flange - MGB POST 0763C88	N	2022.07.06	R	New document unit	Yes
AMM 63-10-63-991	Inspection criteria for the drive flange - MGB POST 0763C88	N	2022.07.06	R	New document unit	Yes
AMM 63-10-64-721	Check of the tightening torque on the gimbal joint assembly - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-10-64-991	Inspection criteria - Gimbal joint assembly - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-20-00-553	Storage of the MGB with the bench	N	2023.01.04	R	New document unit	Yes
AMM 63-20-60-061	Removal / Installation - MGB POST 0763C88	R	2022.10.28	C	Discrepancy corrected	Yes
AMM 63-20-60-065	Removal / Installation - Endoscopy plug or equivalent - MGB POST 0763C88	N	2022.12.07	R	New document unit	Yes
AMM 63-20-60-066	Removal / Installation - Pressure port unions and seats - MGB POST 0763C88	N	2022.11.16	R	New document unit	Yes
AMM 63-20-60-213	Inspection after Removal / Installation of the MGB POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 63-20-60-216	General visual inspection of the MGB POST 0763C88 after maintenance work on its lubrication system	R	2022.10.28	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-20-60-219	Visual inspection of the MGB POST 0763C88	R	2022.11.10	C	Discrepancy corrected	Yes
AMM 63-20-60-281	Search for magnetic particles in the bottom of the gear box - MGB POST 0763C88	N	2022.04.12	R	New document unit	Yes
AMM 63-20-60-611	Draining and Filling the MGB POST 0763C88	R	2022.09.28	C	Discrepancy corrected	Yes
AMM 63-20-60-722	Check of the tightening torque of the rotor actuator bracket links and of the epicyclic module links - MGB POST 0763C88	R	2022.09.06	F	Form changed	No
AMM 63-20-60-723	Check of tightening torques - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-20-60-991	MGB visual inspection criteria POST 0763C88 - Leaks and seepage	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-20-60-992	MGB detailed and visual inspection criteria POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-20-60-993	Inspection criteria - General - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-21-02-221	Inspection - Oil Filter	R	2022.04.01	I	Information added	Yes
AMM 63-21-61-721	Check of the tightening torque - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-21-62-061	Removal / Installation of the filtering cartridge - MGB POST 0763C88	R	2022.09.06	F	Form changed	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-21-62-221	Detailed inspection of the oil filter - MGB POST 0763C88	R	2022.11.02	C	Discrepancy corrected	Yes
AMM 63-21-62-721	Check of the tightening torques of the oil filter - MGB POST 0763C88	N	2022.07.07	R	New document unit	Yes
AMM 63-21-62-991	Inspection criteria for the oil filter - MGB POST 0763C88	R	2022.11.02	C	Discrepancy corrected	Yes
AMM 63-21-63-061	Removal / Installation - Oil level indicator - MGB POST 0763C88	R	2022.11.03	C	Discrepancy corrected	Yes
AMM 63-21-64-061	Removal / Installation - Equipped filler cap - MGB POST 0763C88	R	2022.11.03	C	Discrepancy corrected	Yes
AMM 63-22-00-061A	Removal / Installation - Fan Assembly	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 63-22-00-061B	Removal / Installation - Fan Assembly POST 0779B26	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 63-22-00-222A	Check of the clearance between the blade tips of the fan wheel and the internal diameter of the fan rectifier	N	2022.11.16	R	New document unit	Yes
AMM 63-22-00-222B	Check of the clearance between the blade tips of the fan wheel and the internal diameter of the fan rectifier - POST 0779B26	N	2022.11.16	R	New document unit	Yes
AMM 63-22-60-061	Removal / Installation - Fan assembly - MGB POST 0763C88	R	2022.11.16	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-22-60-222	Check of the clearance between the blade tips of the fan wheel and the internal diameter of the fan rectifier - MGB POST 0763C88	N	2022.11.16	R	New document unit	Yes
AMM 63-22-60-991	Inspection criteria - Fan assembly - MGB POST 0763C88	R	2022.12.07	C	Discrepancy corrected	Yes
AMM 63-23-60-061	Removal / Installation - Rotor Brake Assembly POST 0763C86	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 63-23-60-062	Disassembly / Assembly of the Rotor Brake Assembly POST 0763C86	R	2022.09.30	C	Discrepancy corrected	Yes
AMM 63-23-60-211	Visual inspection - Rotor brake POST 0763C86	N	2022.10.28	R	New document unit	Yes
AMM 63-23-60-221	Rotor brake detailed inspection POST 0763C86	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 63-23-60-223	Detailed inspection of the rotor brake with removal - POST 0763C86	N	2022.10.28	R	New document unit	Yes
AMM 63-23-60-821	Adjustment of the rotor brake control POST 0763C86	R	2022.11.10	C	Discrepancy corrected	Yes
AMM 63-23-60-991	Inspection criteria - Rotor brake POST 0763C86	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 63-23-61-061	Removal / Installation - Brake disc POST 0763C86	R	2022.11.02	C	Discrepancy corrected	Yes
AMM 63-23-62-061	Removal / Installation - Brake pads - POST 0763C86	R	2022.11.04	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-24-61-991	Inspection criteria for the tail drive line flange - MGB POST 0763C88	R	2022.11.07	C	Discrepancy corrected	Yes
AMM 63-24-61-992	Inspection criteria for the splines of the tail drive line flange - MGB POST 0763C88	N	2022.07.07	R	New document unit	Yes
AMM 63-24-62-721	Check of the tightening torque - MGB POST 0763C88	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 63-25-60-063	Removal / Installation - Lubrication line and unions of the accessory gear box - MGB POST 0763C95	R	2022.12.06	C	Discrepancy corrected	Yes
AMM 63-25-60-721	Check of the tightening torques of the accessory gear box POST 0763C95	R	2022.10.21	C	Discrepancy corrected	Yes
AMM 63-30-00-211	Inspection - Support Assembly	R	2022.09.28	I	Information added	Yes
AMM 63-40-02-211	Inspection - MGB Electrical Magnetic Plug	R	2022.10.13	I	Information added	No
AMM 63-40-61-991	Inspection criteria for the tachometer generator - MGB POST 0763C88	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 63-40-62-061	Removal / Installation - Electrical Magnetic Plugs - MGB POST 0763C88	R	2022.09.22	F	Form changed	No
AMM 63-40-62-211	Inspection - MGB electrical magnetic plug POST 0763C88	R	2022.12.01	C	Discrepancy corrected	Yes
AMM 64-10-00-221B	Inspection - Tail Rotor Blades with Removal POST 0761B27	R	2022.09.26	C	Discrepancy corrected	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 65-10-00-221	Longitudinal inspection of the tail drive line	N	2022.11.10	R	New document unit	No
AMM 65-10-00-222	DELETED	D	2011.11.09			
AMM 65-20-01-961	Replacement - Tail rotor control shaft bearing	R	2022.07.25	C	Discrepancy corrected	Yes
AMM 65-40-01-211	Inspection - TGB Electrical Magnetic Plug	R	2022.09.28	I	Information added	Yes
AMM 67-11-01-065	Removal / Installation - Right and Left Hinge Yokes and Cycling Coupling Tube	R	2022.09.28	I	Information added	Yes
AMM 67-30-01-061	DELETED	D	2013.05.28			
AMM 67-30-01-061A	Removal / Installation - Main rotor actuator	N	2022.07.07	R	New document unit	No
AMM 67-30-01-061B	Removal / Installation - Main rotor actuator - MGB POST 0763C88	N	2022.07.08	R	New document unit	Yes
AMM 79-20-00-061A	Removal / Installation - Oil Cooler Assembly	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 79-20-00-061B	Removal / Installation - Oil Cooler Assembly	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 79-20-00-061C	Removal / Installation - Equipped oil cooler - MGB POST 0763C88	R	2022.11.16	C	Discrepancy corrected	Yes
AMM 80-10-01-061	Removal / Installation - Starter Generator	R	2022.04.11	I	Information added	Yes
AMM 80-10-01-212	Check of the radial play of the drive shaft of the starter generator	N	2022.04.11	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

© Copyright - Airbus