




HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o Mycopter Aviation Services Sdn. Bhd.
 Helicopter Centre,
 Malaysia International Aerospace Centre (MIAC)
 Sultan Abdul Aziz Shah Airport, 47200 SUBANG
 Selangor, Malaysia

JOB CARD

AIRCRAFT TYPE: EC 120 B	AIRCRAFT: 1089	SERIAL NO 1089	HOURS 3410.70	LDG/CYCLES 4282	NG/N1 CYCLES 1582.05	NF/N2 CYCLES 1479.95	JOB CARD NO HRSB/2020/0048
REGISTRATION: 9M-SBK	ENGINE #1: 34077	ENGINE #2: 34077	HOURS 4531.80				PAGE NO 1 of 1
	APU: N/A		HOURS N/A	LDG/CYCLES N/A			

To Carry Out All Due Inspection I.A.W Aircraft Maintenance Program REF HRSB/AMP/EC120/ISSUE 1/ REVISION 2- ASB 05A020-CHECK FOR CRACK ON TRH

RAISED BY AND DATE:
GABRIEL PILLAI. 29.01.2020

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	INSP. CRS*	DATE
1.	TAIL ROTOR HUB -Check For Crack on TRH Body. MOD: - Condition: - ASB 05A20 R1 – PARA 3.B.1 & 3.B.2	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>aj</i>	<i>A. K.</i> 	29/1/20

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulations for the time being in force and in that respect the aircraft / equipment is considered fit for Release to Service.

HRSB/CAMO/WO
 DATE : 07-JAN-19