

SB INCORPORATED

MSM INTRO

 Modified content

REFERENCE

Documentary Unit

References/Effectivity SB INCORPORATED

Language EN(en)

Issue Date 2023.01.30

EFFECTIVITY

Model EC155

Version B

Serial Number

STATUS

Type of modification R

Description

Reason for update

Maintenance work affected

SB INCORPORATED

Airbus is required to issue Service Bulletins (ASB/SB) subsequent to new events (incidents, etc).

The information contained in the SBs is incorporated in the MSM if, and only if:

The SB contains new periodic checks, or modifies the existing MSM limitations.

The table below specifies for each SB incorporated:

- the number of the SB and its revision number,
- the subject of the SB,
- the ATA chapter/section concerned,
- the date on which the SB is incorporated in the MSM.

| SB N° | Subject | ATA | AD Number | Incorporation Date |
|---------------------------|---|-------|-----------|--------------------|
| 65-001 R0 | Marking a Paint Index Mark on Tail Rotor Drive Shaft Bearing Blocks Nos. 2, 3 and 4 | 65-10 | | 2001.03.31 |
| 65-002 R0 | Replacement of TRH Pitch Control Rod | 65-20 | | 2001.11.30 |
| 04A005 R0 | Tail Rotor Pitch Change Control Rod | 65-20 | | 2003.07.03 |

| | | | | |
|---------------------------|--|-------|-----------|------------|
| 05A006 R1 | Check and Replacement of Baggage Compartment Fire Extinguisher and Engine Fire Extinguishers (ATA 26-21) | 26-23 | | 2005.01.20 |
| 05A007 R0 | Check of the MGB Planet Gear Carrier | 63-20 | | 2005.01.20 |
| 62A006 R0 | Check for Correct Positioning of the Filler Wedge of the Tenon at the Main Rotor Blade Tip | 62-10 | | 2005.01.20 |
| 64-003 R0 | Tail rotor blade protection against sand erosion | 64-10 | | 2005.01.20 |
| 32-005 R0 | Brace Strut Actuator - Maintenance of the Various Components (ATA 32-20) | 32-10 | | 2005.01.20 |
| 05-003 R0 | Readjustment of Door Mechanism Tightening Torques (ATA 52-12) | 52-11 | | 2005.01.20 |
| 05A005 R1 | Check of the Main Gearbox (MGB) Base Plate | 63-20 | | 2005.06.09 |
| 05-008 R0 | Visual Inspection of the RH and LH Engine Oil Return Hoses in the MGB Compartment (ATA 79-00) | 29-12 | | 2005.12.22 |
| 05A011 R0 | Tail Rotor Blade Check | 64-10 | | 2006.11.14 |
| 53-023 R0 | Visual Inspection of the Upper Flanges of the Forward Bottom Structure Longitudinal Beams | 53-10 | | 2007.04.20 |
| 62A014 R0 | MAIN ROTOR - Check of the Rotor Mast / Hub Nut | 62-20 | | 2008.06.27 |
| 05-009 R1 | TIME LIMITS - MAINTENANCE CHECKS - Check of the Hydraulic Hose Routing in the MGB Compartment | 29-10 | | 2008.10.13 |
| 05A007 R2 | Check of the MGB Planet Gear Carrier - This SB revision leads to no change the Maintenance Programme Section. | 63-20 | | 2010.04.08 |
| 25-092 R0 | Container sealing improvement for reduction of quarter-hull life-raft maintenance (SR10 type) - This SB revision leads to no change the Maintenance Programme Section. | 25-69 | | 2010.07.29 |
| 56A003 R0 | WINDOWS - Windows of hinged cabin doors | 56-30 | | 2011.06.09 |
| 32-009 R0 | LANDING GEAR - Skis installation | 32-40 | | 2013.09.12 |
| 24-019 R0 | ELECTRICAL POWER - Electrical Bonding. | 24-00 | | 2013.09.12 |
| 05-024 R0 | CHECKS - FLIGHT CONTROLS - Optimisation of flight controls maintenance | 67-00 | | 2014.05.29 |
| 05-025 R1 | FUSELAGE Optimisation of maintenance effective for the structure of EC155 helicopters | 53-10 | | 2014.05.29 |
| 21-018 R0 | AIR CONDITIONING - Installation of the triple-injector heating kit | 21-41 | | 2014.05.29 |
| 05-026 R0 | Greasing the bolts of the reinforced scissors of the optional ski installation | 32-40 | | 2015.07.30 |
| 63A012 R1 | Inspection of the Shur-Lok nut which retains the tail rotor drive flange of the Main Gearbox | 63-24 | | 2015.07.30 |
| 05-023 R1 | EMERGENCY FLOTATION GEAR - SSCVFDR - Check of the immersion probe | 25-62 | | 2015.07.30 |
| 29-008 R0 | Check of the Hydraulic Pipe Installation | 63-20 | | 2010.01.11 |
| 05-032 R1 | Check for corrosion at the connection between the main landing gear legs and the upper part of the torque links | 32-12 | | 2018.09.10 |
| 05-035 R1 | Reduction of the TBO of the deployment control unit of the CPI 503 beacon (HR SMITH) | 25-66 | | 2021.01.22 |
| 26-004 R0 | FIRE PROTECTION - Obsolescence of cockpit fire extinguisher | 26-22 | | 2021.01.22 |
| 63A013 R1 | MAIN ROTOR DRIVE - Tail rotor drive flange Installation of rear output stop | 63-24 | | 2021.01.22 |
| 05A033 R2 | TIME LIMITS - MAINTENANCE CHECKS - Baggage compartment - Inspection of the baggage compartment skin | 53-10 | 2019-0080 | 2022.02.01 |
| 05-038 R1 | TIME LIMITS - MAINTENANCE CHECKS - Starter generator- Check of the starter generators MP/N 524-031 | 80-10 | | 2023.01.30 |

© Copyright - Airbus

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION