



A/C TYPE: AGUSTA 109E		STATION: AIROD SUBANG				DATE: 31.07.07	
REGN: 9M- <u>BOB</u>		SERIAL NO: 11212				PAGE 9 OF .	
A/F HOURS: 1331.00		WORKSHEET NO: 0475 / BOB				REMARK:	
# 1 ENG. HOURS	# 2 ENG. HOURS	# 1 ENG. ACC. CYC			# 2 ENG. ACC. CYC		
1331.00	1331.00	IMP	CT	PT	IMP	CT	PT
MAF:							
DATE	LBE	ITEM	DEFECTS/WORK TO BE CARRIED OUT	RECTIFICATION/ACTION TAKEN	MECH/LAE	DATE	
31/7	204	1.	BT109EP-79 TO BE COUPLED WITH. (REF: AD NO: 2007-8192 E DTD 13.07.2007). INSPECTION AND REWORK OF THE LOWER SEMICHANNEL ASSEMBLIES P/N. 109-0641-10 -213 OR P/N. 109-0642-01 - 171 OF THE FORWARD FIREWALL.	BT109EP-79 CARRIED OUT AND FOUND THAT THE SAID METALLIC SPACERS IS NOT ^{INSTALLED AND} PRESENT ON THIS AIRCRAFT. THE GASKET WAS INSPECTED FOR CORRECT SEATING. FOUND SATISFACTORY.		31/7/07	

THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IAW WITH THE REQUIREMENTS OF THE MALAYSIAN CIVIL AVIATION REGULATIONS FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT EQUIPMENT IS FIT FOR RELEASE TO SERVICE.

NAME ALEX SHAH SIGNATURE  LIC/APP NO: M2837 DATE: 31/7/07