

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE  
RELEASED BY THE  
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

Translation of "Consigne de Navigabilité  
Ref. : 78-204-2(B)  
In case of any difficulty, reference  
should be made to the French original text.

AEROSPATIALE HELICOPTERS : AS 350, ALL MODELS

CHECKING THE ROTATING STAR DRIVE ADAPTER ON MAIN ROTOR SHAFT ASSEMBLY

Applicable to main rotor shaft assemblies P/N 350 A 37 0003 with serial number lower than M 146.

To check for correct installation of the rotating star drive adapter the inspection called for in Service Bulletin AS 350 n° 65.01 has been rendered mandatory.

This inspection is to be carried out within the 5 hours of flight following the date at which the present Airworthiness Directive has become effective.

NOTE : Work card 65.13.603 which includes the inspection operations detailed in Service Bulletin 65.01 will be incorporated shortly in the maintenance manual to cover any future actions on the rotating star drive adapter.

Reference Aerospatiale Service Bulletin AS 350 n° 65.01

DATE OF EFFECTIVITY : NOVEMBER 14th 1978

Date : 11/6/1978

Material AEROSPATIALE HELICOPTERS  
AS 350

Reference : 78-204-2(B)