

AIRWORTHINESS DIRECTIVE
RELEASED BY THE
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness.

Translation of "Consigne de Navigabilité"
Réf. : 79-12-4 (B)
In case of any difficulty, reference
should be made to the French original text.

AEROSPATIALE HELICOPTERS AS 350 (ECUREUIL AND ASTAR)

BOLTS FOR ATTACHMENT OF THE TAIL GEAR BOX TO THE TAIL BOOM.

To improve the tightening of the tail gear box on the tail boom, it has been decided that replacement of the two rear bolts for attachment of tail gear box P/N 350A.33.1052.20 or 22202 BC 100.023L shall be rendered mandatory in accordance with the directives of AEROSPATIALE Service Bulletin AS 350 No 65.07.

This modification (AMS 350A.07.8517) is to be applied within 50 hours of flight following the date at which the present directive has become effective.

REF. : AEROSPATIALE Service Bulletin AS 350 No 65.07

DATE OF EFFECTIVITY : JANUARY 24th, 1979

Date : JANUARY 17, 1979

Material : AEROSPATIALE HELICOPTERS
AS 350 (ECUREUIL & ASTAR)

Reference : 79-12-4 (B)