

AIRWORTHINESS DIRECTIVE
RELEASED BY THE
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness.

Translation of "Consigne de Navigabilité"
Réf. : 79-133-7(B)
In case of any difficulty, reference
should be made to the French original text.

AEROSPATIALE HELICOPTERS AS 350, ALL MODELS

INSPECTION OF THE LOCKING SYSTEM

ON LH LATERAL BAGGAGE HOLD DOOR (P/N 350A.21.0032.10)

Owing to a possible incorrect positioning of the door latch on the catch at the production stage liable to entail accidental opening of the LH lateral baggage hold door a check for correct positioning of the latch on the catch (with repair action, if required) has been rendered mandatory in accordance with the directives of AEROSPATIALE Service Bulletin AS 350 n° 52.04.

This inspection shall be performed within 8 days following the date at which the present directive has become effective.

Reference : AEROSPATIALE SERVICE BULLETIN AS 350 n° 52.04

DATE OF EFFECTIVITY : JULY 25, 1979

Date : 7/18/1979

Material : AEROSPATIALE HELICOPTERS
AS 350, ALL MODELS

Reference : 79-133-7(B)