

AIRWORTHINESS DIRECTIVE  
RELEASED BY THE  
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness.

Translation of "Consigne de Navigabilité"  
Réf. : 79-174-9(B)  
In case of any difficulty, reference  
should be made to the French original text.

AEROSPATIALE HELICOPTERS AS 350 ALL MODELS  
INCREASE PRE-LOADING OF TIMKEN BEARINGS  
OF THE TAIL GEAR BOX ROTOR SHAFT - MODIFICATION

To preclude the appearance in some cases of flight of resonance phenomena conducting to development of cracks in the tail gear box housing the mandatory incorporation of the subject modification has been decided in accordance with Aerospatiale Sce bulletin AS 350 n° 65-08 rév. 1.

This modification shall be incorporated on 15th september 1979 at the latest.

Ref. : AEROSPATIALE SCE BULLETIN AS 350 n° 65-08 Rev. 1

DATE OF EFFECTIVITY : AUGUST 22nd, 1979

Date : Sept. 26, 1979

Material : AEROSPATIALE HELICOPTERS  
AS 350 ALL MODELS

Reference : 79-174-9(B)