

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 84-17-21(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE HELICOPTERS AS 355 ALL MODELS (ECUREUIL II/TWINSTAR)

HORIZONTAL STABILIZER P/N 355A13.0520.01.01

SERVICE LIFE LIMITATION

From the effective date of the present Airworthiness Directive, and in order to preclude the risk of a failure in service, horizontal stabilizers P/N 355A13.0520.01.01 are subjected to a service life limitation fixed at 700 hours of operation.

For the horizontal stabilizers installed on helicopter on the effective date of the present Airworthiness Directive, the following measure shall be complied with as follows :

- The horizontal stabilizers having accumulated 600 hours of operation and over, shall be withdrawn from service within the 100 operating hours following the effective date of the present Airworthiness Directive.
- The horizontal stabilizers having accumulated less than 600 hours of operation, shall be withdrawn from service before reaching 700 hours of operation.

Ref. : AEROSPATIALE Service Bulletin AS 355 n° 01.01
and approved subsequent revision

EFFECTIVE DATE : FEBRUAR 8, 1984

Dated : 1er/2/1984

**AEROSPATIALE HELICOPTERS AS 355
ALL MODELS (ECUREUIL II/TWINSTAR)**

Ref. : 84-17-21-(B)