BUREAU VERITAS

or

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité' Réf.: 91-164-042(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE AS 355 helicopters

Electric hoist installation

The present Airworthiness Directive applies to AEROSPATIALE AS 350 helicopters, versions E, F, F1, F2 and N, fitted with an AIR EQUIPEMENT hoist P/N 763070.010, -011 and -030.

Further to untimely firing of the hoist squib in service, the following measures are rendered mandatory:

- 1/ Within the next 50 flying hours following the effective date of the present Airworthiness Directive and before October 1, 1991 at the latest, comply with AEROSPATIALE AS 355 Service Bulletin N° 25.30 (unless this has already been done).
- 2/ Every type T inspection (or every 18 months), as well as each time the hoist or the arm are disassembled, for aircraft :
 - a) modified as per paragraph 1C of AS 355 SB N° 25.30
 - b) modified as per the modifications listed in paragraph 1E of AS 355 SB N° 25.30 $\,$

comply with paragraph 1C3 of AS 355 SB N° 25.30.

Ref.: AEROSPATIALE AS 355 Service Bulletin N° 25.30

EFFECTIVE DATE: AUGUST 10, 1991

July 31, 1991 AEROSPATIALE AS 355 helicopters 91-164-042(B)