

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 91-165-058(B) R1  
In case of any difficulty, reference should be made to the French original issue.

## AEROSPATIALE AS 350 helicopters

Electric hoist installation

The present Airworthiness Directive applies to AEROSPATIALE AS 350 helicopters, versions B, B1, B2, D, fitted with an AIR EQUIPEMENT hoist P/N 76370.010, 76370.011 et 76370.030.

Further to untimely firing of the hoist squib in service, the following measures are rendered mandatory :

- 1/ Within the next 50 flying hours following the effective date of the present Airworthiness Directive and before October 1, 1991 at the latest, comply with AEROSPATIALE AS 350 Service Bulletin N° 25.42 R1 (unless this has already been done).
- 2/ Every type T inspection (or every 18 months), as well as each time the hoist or the arm are disassembled, for aircraft :
  - a) modified as per paragraph 1C of AS 350 SB N° 25.42 R1
  - or
  - b) modified as per the modifications listed in paragraph 1E of AS 350 SB N° 25.42 R1comply with paragraph 1C3 of AS 350 SB N° 25.42 R1.

Ref. : AEROSPATIALE AS 350 Service Bulletin N° 25.42 R1

The present revision 1 supersedes AD 91-165-058(B) dated July 31, 1991

### EFFECTIVE DATES :

Original AD : August 10, 1991  
Revision 1 : December 07, 1991

e/W

November 27, 1991	AEROSPATIALE AS 350 helicopters	91-165-058(B) R1
-------------------	------------------------------------	------------------