

A description of the update (description, pages to be removed or inserted) is provided below.

Page modified following update No. 48.

No	Chapter Section Subject	Task	Title	Pages	Date
1.	71-00-06	RPU-801-A01	FAILURES FOUND DURING OPERATION - LIST OF FAILURES OBSERVED DURING ENGINE OPERATION	101 - 104	June 15/2021
2.		812-803-A01	AIR BLEED VALVE CLOSED - TROUBLESHOOTING	101 - 104	
3.		812-811-A01	ABORTED START - FIRST START ABORTED - TROUBLESHOOTING	101 - 104	
4.		813-801-A01	SURGE - TROUBLESHOOTING	101 - 106	
5.		814-804-A01	AIR BLEED VALVE STILL OPEN - TROUBLESHOOTING	101 - 104	
6.		815-803-A01	AIR BLEED VALVE CLOSED - TROUBLESHOOTING	101 - 104	
7.		816-809-A01	INCORRECT OPERATION OF THE BLEED VALVE - TROUBLESHOOTING	101 - 104	
8.		816-814-A01	OIL LEAKAGE BETWEEN M03 AND M04 - TROUBLESHOOTING	101 - 104	
9.		816-827-A01	OIL LEAKAGE OF THE POWER DRIVE OF THE STARTER - TROUBLESHOOTING	101 - 102	
10.		817-955-A01	OVERSPEED PROTECTION FAILURE - TROUBLESHOOTING	101 - 108	

Task Number	Description	Pages to be removed	Pages to be inserted
Title Page	Integration	ALL	1
LAP - 71	Integration	ALL	1 to 8
71-00-06 - FAILURES FOUND DURING OPERATION	Integration	ALL	101 to 104
71-00-06-812-803-A01	Integration	ALL	101 to 104
71-00-06-812-811-A01	Integration	ALL	101 to 104
71-00-06-813-801-A01	Integration	ALL	101 to 106
71-00-06-814-804-A01	Integration	ALL	101 to 104
71-00-06-815-803-A01	Integration	ALL	101 to 104
71-00-06-816-809-A01	Integration	ALL	101 to 104
71-00-06-816-814-A01	Integration	ALL	101 to 104
71-00-06-816-827-A01	Integration	ALL	101 to 102
71-00-06-817-955-A01	Integration	ALL	101 to 108