

## GAM PUBLICATION - GOOGLE DRIVE LINK

<b>GD Link No.</b>	: GDLINK/CAMO/23/035
<b>Subject</b>	: PRATT AND WHITNEY CANADA - PW206C MAINTENANCE MANUAL MANUAL PART NO.: 3043322
<b>Revision No.</b>	: REV. 47
<b>Revision Date</b>	: 05 JUNE 2023

You may click Google Drive link below to view and download the attachment.

1. [PW206C MAINTENANCE MANUAL, REV. 47](#)

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.

## HIGHLIGHTS

Engine Model(s): MODEL(S)PW206C/PW207C

Revision	CH/SE/SU	Pageblock Title	Description of Change
47.0	Front	SERVICE BULLETIN LIST	<a href="#">Service Bulletin list has been updated to add SB28397.</a>
47.0	Front	SERVICE BULLETIN LIST	<a href="#">Service Bulletin list has been updated to add SB28406R2.</a>
47.0	Front	SERVICE BULLETIN LIST	<a href="#">Service Bulletin list has been updated to revise SB28306R3 to SB28306R4.</a>
47.0	Front	SERVICE BULLETIN LIST	<a href="#">Service Bulletin list has been updated to revise SB28197R7 to SB28197R8.</a>
47.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	<a href="#">The service life table has been revised to add the interval for the No. 3 bearing keywasher, No. 4 bearing keywasher and CT disc retaining nut.</a>
47.0	72.00.01 Engine (PW206C) - Fault Isolation	72-00-01 ENGINE, GENERAL (PW206C) - FAULT ISOLATION-2	<a href="#">The High Oil Pressure fault isolation charts have been revised.</a>
47.0	72.00.02 Engine (PW207C) - Fault Isolation	72-00-02 ENGINE, GENERAL (PW207C) - FAULT ISOLATION-2	<a href="#">The High Oil Pressure fault isolation charts have been revised.</a>
47.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187)) (Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	<a href="#">The initial steps of the hot section removal procedure has been updated to add the removal of fuel management module (FMM).</a>
47.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187)) (Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	<a href="#">The final assembly steps of the hot section installation procedure has been updated to add the installation of fuel management module (FMM).</a>
47.0	72.00.31 Hot Section Refurbishment (PW206C (Post-SB28187) and PW207C) (Heavy Maintenance)	72-00-31 HSI (PW206C (Post-SB28187), PW207C) - HEAVY MAINTENANCE	<a href="#">The initial steps of the hot section removal procedure has been updated to add the removal of fuel management module (FMM).</a>
47.0	72.00.31 Hot Section Refurbishment (PW206C (Post-SB28187) and PW207C) (Heavy Maintenance)	72-00-31 HSI (PW206C (Post-SB28187), PW207C) - HEAVY MAINTENANCE	<a href="#">The final assembly steps of the hot section installation procedure has been updated to add the installation of fuel management module (FMM).</a>

<b>Revision</b>	<b>CH/SE/SU</b>	<b>Pageblock Title</b>	<b>Description of Change</b>
47.0	72.00.40 Fits and Clearances	72-00-40 FITS AND CLEARANCES - INSPECTION/CHECK	<a href="#">Service Bulletin 28397 has been incorporated.</a>
47.0	73.21.10 Fuel Management Module (FMM)	73-21-10 FUEL MANAGEMENT MODULE (FMM) - MAINTENANCE PRACTICES	<a href="#">The procedure for FMM auto to manual to auto mode respond check has been revised to update the instructions to do auto mode check for engines one by one and to delete the caution.</a>