


GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/23/055
Subject	PRATT AND WHITNEY CANADA - PW206C MAINTENANCE MANUAL
Revision No.	: REV 48
Revision Date	: 04 DECEMBER 2023

You may click Google Drive link below to view and download the attachment.


1. [PW206C MAINTENANCE MANUAL REV 48 DATED 04.12.2023](#)

MyP&WC POWER Light Mode
Customer First Center | US & CAN: 1-800-288-8000 | INTL: +8000-288-8000 | [Contacts and Locations](#)



MAINTENANCE MANUAL

MODEL(s): PW206C, PW207C
Manual Part No. 3043322, ISSUE NO. 48.0, Dated Dec-04-2023



☰
🏠 📌 🖨️ 🔍 🔄 🔍 ⏪ ⏩ ⏴ ⏵

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
48.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to add SB28404R1.
48.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB28284R3 to SB28284R5.
48.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The steps and guidelines to obtain a recommendation for fleet TBO escalation has been revised to update the TBO request submission in My PWC Power portal, and to delete the TBO evaluation sample request form.
48.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The table for P&WC recommended engine wash interval based on operating environment has been revised to update the maintenance interval in moderate environment condition for compressor performance recovery wash.
48.0	72.00.20 Engine Modules	72-00-20 ENGINE MODULES - MAINTENANCE PRACTICES	The procedure for the removal of the PT shaft retaining nut has been revised to add the caution to prevent damage to the PT disks.
48.0	72.00.20 Engine Modules	72-00-20 ENGINE MODULES - MAINTENANCE PRACTICES	The procedure for the removal of the reduction gearbox module has been revised to add the caution to prevent damage to the PT disks.
48.0	72.00.20 Engine Modules	72-00-20 ENGINE MODULES - MAINTENANCE PRACTICES	The procedure for the installation of the reduction gearbox module has been revised to add the caution to prevent damage to the PT disks.
48.0	72.00.20 Engine Modules	72-00-20 ENGINE MODULES - MAINTENANCE PRACTICES	The procedure for the installation of the PT shaft retaining nut has been revised to add the caution to prevent damage to the PT disks.
48.0	72.00.40 Fits and Clearances	72-00-40 FITS AND CLEARANCES - INSPECTION/CHECK	The table for torques and stretch has been revised to update REF. NO 1302 and REF. NO 3401.
48.0	72.21.00 Air Inlet	72-21-00 AIRINLET - MAINTENANCE PRACTICES	The consumable materials list has been updated.
48.0	72.21.00 Air Inlet	72-21-00 AIRINLET - MAINTENANCE PRACTICES	The procedure for compressor inlet case repair has been deleted.
48.0	72.21.00 Air Inlet	72-21-00 AIRINLET - APPROVED REPAIRS	A new page block has been created for air inlet approved repairs.

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.