

DOCUMENT REVISION AMENDMENT FORM

| | | ATAN BOMBA DAN PENYELAMAT MALAYSIA AW139 AIRCRAFT NTENANCE PROGRAMME JBPM/CAMO/AMP/AW139 ISSUE 2 REV 1 ED 20 SEPTEMBER 2021 | | AMENDME REV. & DA | A STATE OF THE REAL PROPERTY. | TEMPORARY RE | EMPORARY REVISION 1, 08 MAY 2023 | | | | |
|---------|--|---|--|---|-------------------------------|------------------------|--|------|---|--|--|
| ITEM | | AMENDM | ENT DESCRI | PTION | REASON | | | | | | |
| 1 | r 14.0 Page 1 of 1 tem 2: Exterior Marking In | | Implementation of GAM019/ICA, Installation of Exterior Placards and Markings | | | | | | | | |
| 2 | Chapter 17.0 Page 15 of 15 Added item 136: Exterior Marking Inspection | | | | | | Implementation of GAM019/ICA, Installation of Exterior Placards and Markings | | | | |
| Prepare | ed by: | | Verified by: | | Approved By: Accepted By: | | | | | | |
| de | The same of the sa | | DA CANO | v | (| Shy" | A | | | | |
| Name | J. | HSAN MASRI | Name | ZATY NADHIRA | Name | ОМА | R AHMAD | Name | POKE 11 MOHD SANI BIN MAJIO | | |
| Designa | ation | ECHNICAL SERVICES | Designation | CONTINUING AIRWORTHINESS MANAGEMENT MANAGER | Designation | INCOME VENIANCE IN THE | LITY URANCE AGER | | KETLA CAWANGAN KEJUPU TEPAAN PEJAWAT JEPA | | |
| Date | 8 | th MAY 2023 | Date | 8 th MAY 2023 | Date | 8 th M | AY 2023 | Date | | | |

JABATAN BOMBA DAN PENYELAMAT MALAYSIA

| DOCUMENT TITLE: | AIRCRAFT MAINTENANCE PROGRAMME | | | AIRCRAFT TYPE: | LEONARDO HELICOPTER AW139 | | | | |
|--|--------------------------------|------------|---------------------|----------------|---------------------------|-----------|---|--|--|
| PAGE TITLE: RECORD OF TEMPORARY REVISION | | REFERENCE: | JBPM/CAMO/AMP/AW139 | ISSUE: | 2 | REVISION: | 0 | | |
| CHAPTER: | 4.1 | PAGE: | 1 of 1 | DATE: | 01 JULY 2021 | 100 | | | |

RECORD OF TEMPORARY REVISION

| TR NO | CHAPTER AND PAGE NO | ISSUE DATE | INS | ERTED | REMOVED | | |
|-------|--|------------|------------|-------|---------|------|--|
| TRIVO | CHAPTER AND PAGE NO | ISSUE DATE | DATE | NAME | DATE | NAME | |
| 1 | Chapter 14.0 Page 1 of 1 Chapter 17.0 Page 15 of 15 | 08.05.2023 | 02.06.2023 | IHSAN | | | |
| | | | | 03 | | | |
| | | NK | ' 0 | N/ | | | |
| | | | 51 | | | | |
| | 100 | | 15. | | | | |
| | | 00. | | | | | |
| | C. Iv. | | | | | | |
| | | | | | | | |
| | | | | | | | |

| | JABATAN | BOMBA | DAN | PENYELAMAT | MALAYSIA |
|--|----------------|--------------|-----|-------------------|----------|
|--|----------------|--------------|-----|-------------------|----------|

| DOCUMENT TITLE: AIRCRAFT MAINTENANCE PROGRAMME | | | | AIRCRAFT TYPE: | LEONARDO HELICOPTER AW139 | - | | | |
|--|---------------------------------------|-------|------------|---------------------|---------------------------|-----|-----------|---|--|
| PAGE TITLE: | INSPECTION POST MODIFICATION / REPAIR | | REFERENCE: | JBPM/CAMO/AMP/AW139 | ISSUE: | 2 | REVISION: | 1 | |
| CHAPTER: | 14.0 | PAGE: | 1 of 1 | DATE: | 20 SEPTEMBER 2021 | 1 1 | | | |

INSPECTION POST MODIFICATION / REPAIR

| No. | Description | Reference | Item | Inspection | Interval | Remarks |
|-----|--------------------------------|-----------------|-----------------------------|---|------------|--|
| 1 | Upper Panel Assembly Repair | EOAS/139/21/003 | No 1 Damper Attachment Base | Do a GVI for damage and condition. REF: AMP 39-A-65-11-09-00A-720A-A | 300FH | 9M-BOC only |
| 2 | Exterior Marking Inspection | GAM019/ICA | All Placards and Markings | Inspect placards for illegibility, security and cleanliness. Compulsory to change the placard when it has become illegible. Contact Galaxy Aerospace (M) Sdn. Bhd for replacement Inspect placards for illegibility, security and cleanliness. Compulsory to change the placard when it has become illegible. Contact Galaxy Aerospace (M) Sdn. Bhd for replacement | Pre-Flight | Included in Airworthiness Checks |

| JABATAN BOMBA DAN PENYELAMAT MALAYSIA | | | | | | | | | | |
|---------------------------------------|--|-------|------------|---------------------|-------------------|---|-----------|---|--|--|
| DOCUMENT TITLE: | TLE: AIRCRAFT MAINTENANCE PROGRAMME AIRCRAFT TYPE: LEONARDO HELICOPTER AW139 | | | | | | | | | |
| PAGE TITLE: | AIRWORTHINESS CHECKS | | REFERENCE: | JBPM/CAMO/AMP/AW139 | ISSUE: | 2 | REVISION: | 1 | | |
| CHAPTER: | 17.0 | PAGE: | 15 of 15 | DATE: | 20 SEPTEMBER 2021 | | | | | |

| NO. | ITEM | INSPECTION REQUIREMENTS | REMARKS | | | | | |
|---------|--|--|---------|--|--|--|--|--|
| Daily F | Fuel Drain Check | | | | | | | |
| 134. | Fuel Tank Drain Check | Drain 10 to 20cc from each fuel sump water drain valve by activating the relevant push button. Release the pushbutton, confirm that the fuel is free of water and no fuel is dripping from the aircraft drains. REF: AW139 RFM Section 2- External Pre-Flight Check | BFF | | | | | |
| Corros | Corrosion Control Program | | | | | | | |
| 135. | Restoration (Cleaning) of the helicopter external surfaces | Perform a restoration (cleaning) of the helicopter external surfaces and exposed (wetted) areas. REF: 39-A-20-21-01-00A-258A-D, ACCP 00-10 Table 2 Tasks overview | AC | | | | | |
| Inspec | Inspection Post Modification / Repair | | | | | | | |
| 136. | Exterior Marking Inspection | Inspect placards for illegibility, security and cleanliness. Compulsory to change the placard when it has become illegible. Contact Galaxy Aerospace (M) Sdn. Bhd for replacement REF: GAM019/ICA | BFF | | | | | |

Notes:

- 1. If a step on rear fairing is installed on MLG sponson the task can be performed by the pilot prior first flight of the day. It is not necessary to apply this task only if it is performed by the pilot prior first flight of the day.
- 2. Task to be performed by following the instructions contained in the last issue of P&W PT6C-67C Engine Maintenance Manual.