

REVISION TRANSMITTAL

This sheet transmits Revision 1 to MTB-26-01, which:

- A. Extended the effectivity for airplane models B300 and B300C.

NOTE: This revision replaces the original issue of MTB-26-01.

REVISION COMPLIANCE

NO EFFECT. Airplanes previously modified by this service letter are not affected.

LOG OF REVISIONS

Original Issue	June 10, 2022
Revision 1	February 22, 2024

TITLE

FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS

EFFECTIVITY

MODEL	SERIAL NUMBERS
B200GT	BY-1 and On
B200CGT	BZ-1 and On
B300	FL-1 and On
B300C	FM-1 and On

REASON

To replace the Halon Type 1211 portable fire extinguishers with Halotron BrX portable fire extinguishers.

DESCRIPTION

This service document provides parts and instructions to replace the Halon Type 1211 portable fire extinguisher with Halotron BrX portable fire extinguishers.

COMPLIANCE

OPTIONAL. This service document can be accomplished at the discretion of the owner.

A service document published by Textron Aviation may be recorded as *completed* in an aircraft log only when the following requirements are satisfied:

- 1) The mechanic must complete all of the instructions in the service document, including the intent therein.
- 2) The mechanic must correctly use and install all applicable parts supplied with the service document kit. Only with written authorization from Textron Aviation can substitute parts or rebuilt parts be used to replace new parts.
- 3) The mechanic or airplane owner must use the technical data in the service document only as approved and published.
- 4) The mechanic or airplane owner must apply the information in the service document only to aircraft serial numbers identified in the *Effectivity* section of the document.
- 5) The mechanic or airplane owner must use maintenance practices that are identified as acceptable standard practices in the aviation industry and governmental regulations.

No individual or corporate organization other than Textron Aviation is authorized to make or apply any changes to a Textron Aviation-issued service document or flight manual supplement without prior written consent from Textron Aviation.

Textron Aviation is not responsible for the quality of maintenance performed to comply with this document, unless the maintenance is accomplished at a Textron Aviation-owned Service Center.

APPROVAL

Textron Aviation received FAA approval for the technical data in this publication that changes the airplane type design.

Original Issue - June 10, 2022
Revision 1 - February 22, 2024

MTB-26-01
Page 1 of 3

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

FLIGHT CREW OPERATIONS

No Changes

CONSUMABLE MATERIAL

No specialized consumable materials are required to complete this service document.

TOOLING

No specialized tooling is required to complete this service document.

WEIGHT AND BALANCE INFORMATION

Negligible

REFERENCES

Beechcraft

PUBLICATIONS AFFECTED

Beechcraft

ACCOMPLISHMENT INSTRUCTIONS

1. Prepare the airplane for maintenance.
 - A. Make sure that the airplane is electrically grounded.
 - B. Make sure that all switches are in the OFF/NORM position.
 - C. Disconnect electrical power from the airplane.
 - (1) Disconnect external electrical power.
 - (2) Disconnect the airplane battery.
 - D. Attach maintenance warning tags to the battery and external power receptacle that have "**DO NOT CONNECT ELECTRICAL POWER - MAINTENANCE IN PROGRESS**" written on them.

NOTE: Use the references that follow for the removal and installation procedures.

Super King Air B200GT/B200GCT

- 200 Series Maintenance Manual, Chapter 26, Portable Fire Extinguisher - Removal/Installation

Super King Air B300/B300C

- B300/B300C Maintenance Manual, Chapter 26, Portable Fire Extinguisher and Bracket - Removal/Installation

2. Replace the flight compartment halon type 1211 portable fire extinguisher as follows:
 - A. Remove the flight compartment portable fire extinguisher and bracket. Keep bracket mounting hardware.
 - B. Install one P3APP003020C Quick Disconnect Bracket Assembly with the kept mounting bracket hardware.
 - C. Install one P3APP003010D Halotron BrX Fire Extinguisher and connect the latch.
3. Replace the aft cabin halon type 1211 portable fire extinguisher as follows:
 - A. Remove the aft cabin portable fire extinguisher and bracket. Keep bracket mounting hardware.
 - B. Install one P3APP003020C Quick Disconnect Bracket Assembly with the kept mounting bracket hardware.
 - C. Install one P3APP003010D Halotron BrX Fire Extinguisher and connect the latch.

4. Remove the maintenance warning tags and connect the airplane battery.
5. Make an entry in the airplane logbook that states compliance and method of compliance with this service document.

NOTE: Textron Aviation recommends that compliance with all service documents is reported to a maintenance tracking system provider.

- Complete a record of compliance. (Maintenance Transaction Report, Log Book Entry, or other record of compliance.)
- Put a copy of the completed record of compliance in the airplane logbook.
- Send a copy of the completed record of compliance to the maintenance tracking system provider used.

MATERIAL INFORMATION

Order the parts below to install this modification.

NEW P/N	QUAN- TITY	KEY WORD	OLD P/N	INSTRUCTIONS/ DISPOSITION
P3APP003010D	2	Halotron BrX Fire Extinguisher		
P3APP003020C	2	Quick Release Bracket Assembly	Various	

* Please contact your Regional Textron Aviation Parts Distribution Customer Support Team for current cost and availability of parts listed in this service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International).

For more information, please visit the TAPD Support & Aftermarket Account Management website at <https://ww2.txtav.com/Parts/Promos/TAPD>.

Based on availability and lead times, parts may require advanced scheduling.

TITLE

FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS

TO:

Beechcraft Model B200GT, B200CGT, B300, B300C Aircraft Owner

REASON

To replace the Halon Type 1211 portable fire extinguishers with Halotron BrX portable fire extinguishers.

COMPLIANCE

OPTIONAL. This service document can be accomplished at the discretion of the owner.

LABOR HOURS

WORK PHASE	LABOR-HOURS
Modification	As Necessary
Test and Inspection	As Necessary

MATERIAL AVAILABILITY

PART NUMBER	AVAILABILITY	COST
P3APP003010D	*	*
P3APP003020C	*	*

* Please contact a Textron Aviation Authorized Service Facility for current cost and availability of parts listed in this service document.

WARRANTY

None

NOTE: As a convenience, service documents are now available online to all our customers through a simple, free-of-charge registration process. If you would like to sign up, please visit the Customer Access link at support.txtav.com to register.

