

MTB-34-05

MTD 24 0F

TITLE

NAVIGATION - FIELD UPGRADED PROLINE FUSION PHASE 3 TO PHASE 4 SOFTWARE

EFFECTIVITY

MODEL	SERIAL NUMBERS
B200GT	BY-207, BY-239, BY-250 thru BY-323
B200CGT	BZ-1
B300	FL-954, FL-1010, FL-1031 thru FL-1139
B300C	FM-66 thru FM-75

REASON

For aircraft that were upgraded to Phase 3 Software in the field and will be upgraded to Phase 4 Software.

DESCRIPTION

This service document provides parts and instructions to replace the two input/output concentrators (IOCs), and upgrade field aircraft that had Phase 3 Software installed to Fusion Phase 4 Software.

NOTE: The aircraft listed in the effectivity list must have previously complied with the service document SB 34-4171: Proline Fusion Upgrade to Phase 3 Software prior to completing this service document.

COMPLIANCE

DISCRETIONARY. This service document can be accomplished at the discretion of the owner.

A service document published by Textron Aviation may be recorded as *completed* in an aircraft log only when the following requirements are satisfied:

- 1) The mechanic must complete all of the instructions in the service document, including the intent therein.
- 2) The mechanic must correctly use and install all applicable parts supplied with the service document kit. Only with written authorization from Textron Aviation can substitute parts or rebuilt parts be used to replace new parts.
- 3) The mechanic or airplane owner must use the technical data in the service document only as approved and published.
- 4) The mechanic or airplane owner must apply the information in the service document only to aircraft serial numbers identified in the *Effectivity* section of the document.
- 5) The mechanic or airplane owner must use maintenance practices that are identified as acceptable standard practices in the aviation industry and governmental regulations.

No individual or corporate organization other than Textron Aviation is authorized to make or apply any changes to a Textron Aviation-issued service document or flight manual supplement without prior written consent from Textron Aviation.

Textron Aviation is not responsible for the quality of maintenance performed to comply with this document, unless the maintenance is accomplished at a Textron Aviation-owned Service Center.

	IVI I D-34-05
September 16, 2022	Page 1 of 19

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

COPYRIGHT © 2022

Reechcraft Cessna

MTB-34-05

TEXTRON AVIATION

Towke

APPROVAL

Textron Aviation received FAA approval for the technical data in this publication that changes the airplane type design.

FLIGHT CREW OPERATIONS

No Changes

CONSUMABLE MATERIAL

No specialized consumable materials are required to complete this service document.

TOOLING

NAME	NUMBER	MANUFACTURER	USE
Beech King Air Maintenance Test Box	TE79–KS- MAINT/935	Textron Aviation Parts Distribution 7121 Southwest Boulevard Wichita, KS 67215	To be used for loading and activating software on the aircraft.
Field Load Shorting Plug	434–340998–000 3	Textron Aviation Parts Distribution 7121 Southwest Boulevard Wichita, KS 67215	To be used for loading and activating software on the aircraft.
USB Thumb Drive	N/A	Commercially Available	Used to install the software.
Windows Laptop	N/A	Commercially Available	Used for the preparation of the USB thumb drive.

WEIGHT AND BALANCE INFORMATION

Negligible

REFERENCES

Beechcraft Super King Air B200GT/B200GT Fusion Maintenance Manual

Beechcraft Super King Air B300/B300C Fusion Maintenance Manual

PUBLICATIONS AFFECTED

Beechcraft B200GT/B200CGT Illustrated Parts Catalog

Beechcraft B300/B300C Illustrated Parts Catalog

ACCOMPLISHMENT INSTRUCTIONS

- 1. Record the current airplane options strapping prior to updating software.
 - A. Make sure that the airplane is electrically grounded.
 - B. Connect the external electrical power to the aircraft.
 - C. Connect the 434-340998-0003 Field Shorting Plug or the TE79-KA-MAINT/935 Test Box to the maintenance d-sub connector on the aft end of the center pedestal.
 - D. Put the BATT switch to the ON position.

NOTE: On B300/B300C Models, put the EXT PWR Switch to the ON Position.

- E. If the TE79-KA-MAIN/935 Test Box is connected, put the REPORT MODE Switch to the ENABLE Position.
- F. On the Overhead Instrument Panel, put the DATALOAD Switch to the ENABLE position.
- G. Make sure that the "Aircraft Configuration Parameter" Page shows on the Pilot's Primary Flight Display (PFD1), PFD2, and on the Multifunction Display (MFD).

NOTE: On-screen validation is completed with the MFD only.

SERVICE BULLETIN



MTB-34-05

- H. On the MFD, press the down arrow at the top right corner of the screen and select the "Aircraft Option Straps" page.
- I. (Refer to Figure 2, Sheet 1, 2, and 3.) Record the optional strap configuration of items 1 through 36 as installed on the aircraft.

NOTE: Recording the optional strap configuration will make it easier to make sure the Aircraft Personality Module (APM) after the new software has been installed on the aircraft.

- J. Put the DATALOAD Switch to the OFF position.
- K. If the TE79-KA-MAINT/935 Test Box is connected, put the REPORT MODE Switch to the OFF position.

NOTE: On B300/B300C Models, put the EXT PWR Switch to the OFF Position.

- L. Make sure that all switches are in the OFF/NORM position.
- M. Disconnect electrical power from the airplane.
 - (1) Disconnect external electrical power.
 - (2) Disconnect the airplane battery.
- N. Attach maintenance warning tags to the battery and external power receptacle that have **"DO NOT CONNECT ELECTRICAL POWER MAINTENANCE IN PROGRESS"** written on them.
- 2. Install the Proline Fusion 4 hardware as follows:
 - A. Remove the two 822-1361-622 IOCs from the aircraft.
 - (1) For all King Air 200 Models, refer to the Super King Air B200GT/B200CGT Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Removal/Installation.
 - (2) For all King Air 300 Models, refer to the Super King Air B300/B300C Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Removal/Installation.
 - B. Install the two 822-1361-623 IOCs into the aircraft.
 - (1) For all King Air 200 Models, refer to the Super King Air B200GT/B200CGT Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Removal/Installation.
 - (2) For all King Air 300 Models, refer to the Super King Air B300/B300C Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Removal/Installation.
- 3. Connect an external power cart to the aircraft.
- 4. Set the external power cart switch to the ON position.
- 5. Using the list below make sure the following circuit breakers are engaged.
 - AVIONICS MASTER (CB90)
 - MKP (CB27)
 - AVIONICS BUS TPL FED (CB91)
 - AVIONICS BUS L GEN (CB92)
 - AVIONICS BUS R GEN (CB93)
 - PFD 1 (CB111)
 - CCP (CB112)
 - MFD (CB101)
 - PFD 2 (CB105)
 - CCP 2 (CB106)
 - EQPT COOLING (CB69)
 - DC CONV 1 (CB74)
 DC CONV 2 (CD72)
 - DC CONV 2 (CB76)
- 6. Put the BATT, EXT PWR, and the AVIONICS MASTER POWER Switches to the ON position.
- 7. Make sure that none of the circuit breakers from the list above have tripped.



TEXTRON AVIATION

MTB-34-05

Tawker

- 8. Prepare a USB thumb drive with the Field Loadable software.
 - A. Using AFD Field Loadable Software, Part Number: 130M310006-0007, available for download on txtavsupport.com use the procedure from the following maintenance manuals:
 - (1) For all King Air 200 Models, refer to the Super King Air B200GT/B200GT Fusion Maintenance Manual, Chapter 31, Adaptive Flight Display (AFD-3700) Maintenance Practices.
 - (2) For all King Air 300 Models, refer to the Super King Air B300GT/B300GT Fusion Maintenance Manual, Chapter 31, Adaptive Flight Display (AFD-3700) Maintenance Practices.

NOTE: The Aircraft Maintenance Manual (AMM) contains all steps for USB creation. The zip files downloaded form txtavsupport.com will only need to be unzipped into the top level directory of the thumbdrive.

- 9. Do the software installation procedure using the prepped USB thumb drive as follows:
 - A. For all King Air 200 Models, refer to the Super King Air B200GT/B200GT Fusion Maintenance Manual, Chapter 31, Adaptive Flight Display (AFD-3700) Maintenance Practices.
 - B. For all King Air 300 Models, refer to the Super King Air B300GT/B300GT Fusion Maintenance Manual, Chapter 31, Adaptive Flight Display (AFD-3700) Maintenance Practices.
 - C. (Refer to Figure 1, Sheets 1 through 7.) For expected electronic nameplates to be seen during the verification steps of the applicable AMM procedures.
- 10. Make sure that the AFD software has been loaded as follows:
 - **NOTE:** During the verification procedures, each AFD software configuration in each AFD must be correct. If the software is not correctly loaded, then repeat Step 9.
 - A. Make sure that all three AFD-3700 Displays by setting the PFD1, PFD2, and MFD Display Reversion Switches are put to the NORM position.

NOTE: The switches are located on the Reversionary Panel.

- B. Select "Home".
- C. Select "Maint" (Maintenance) format on the center display.
- D. Select "Done".
- E. Select "Adv" (Advanced) Mode.
- F. Select "System".

NOTE: The "IMA Sys" Tab will be selected by default.

G. After some time, the status will change to a green "Pass" condition.

NOTE: This may take up to 5 seconds for the format to update. If the system is configured correctly, the IMA system area will report a status of "Pass" for all three AFD-3700 units.

- H. Select the "i" icon for a display next to the LEFT display.
- I. (Refer to Figure 1, Sheet 1 and 2.) Make sure that the ICIT electronic nameplate contents correctly align with Figure 1, Sheet 1 and 2.
- J. Select "X" to close out.
- K. Select the "i" icon for a display next to the RIGHT display.
- L. (Refer to Figure 1, Sheet 3 and 4.) Make sure that the ICIT electronic nameplate contents correctly align with Figure 1, Sheet 3 and 4.
- M. Select "X" to close out.
- N. Select the "i" icon for a display next to the CENTER display.

SERVICE BULLETIN



MTB-34-05

- O. (Refer to Figure 1, Sheet 5, 6, and 7.) Make sure that the ICIT electronic nameplate contents correctly align with Figure 1, Sheet 5, 6, and 7.
- P. Select "X" to close out.
- Q. Put the Avionics Master Power Switch to the OFF position.
- R. Put the External Power Switch to the OFF position.
- S. Put the Battery Switch to the OFF position.
- 11. Do the aircraft personality module (APM) software and validation procedure.
 - A. For all King Air 200 Models, refer to the Super King Air B200GT/B200GT Fusion Maintenance Manual, Chapter 31, Aircraft Personality Module (APM-5000) Maintenance Practices.
 - B. For all King Air 300 Models, refer to the Super King Air B300GT/B300GT Fusion Maintenance Manual, Chapter 31, Aircraft Personality Module (APM-5000) Maintenance Practices.
- 12. Do the SMS key installation as follows:
 - NOTE: The installation of electric standard keys will be completed on the MFD only.
 - **NOTE:** If the user does not have the 810-0165-001 Enable Key, then the user must contact Rockwell Collins.
 - A. Get the certificate of the software product authenticity for TLAF-5000 P/N 810-0165-001.
 - B. Put the BAT Switch to the ON position.
 - C. Put the EXT PWR Switch to the ON position.
 - D. Put the AVIONICS MASTER Switch to the ON position.
 - E. On the Reversionary Panel, make sure that the PFD1, PFD2, and MFD Reversion Switches are in the NORM position.
 - F. On the CCP, push the MFD button.

NOTE: The cursor shows on the center AFD.

G. Push the Menu button.

NOTE: The Format Selection Page shows on the MFD.

H. On the Format Selection page, select a MFD 1/2 page format icon from the top menu bar.

NOTE: The selected MFD 1/2 page format shows on the Format Selection Page.

- I. Push the MAINT (Maintenance) icon.
- J. Push the Done button.
- K. On the Maintenance Menu, select the License icon.

NOTE: The Application License Management page shows on the MFD.

- L. Make sure the APM-5000 serial number shown on the Application License Management page matches the APM serial number listed on the certification of software product authenticity.
- 13. Do the SMS Key Validation as follows:
 - A. On the CCP, push the MFD button.

NOTE: The cursor shows on the MFD.

B. Push the Menu button.

NOTE: The Format Selections Page shows on the MFD.

SERVICE BULLETIN



MTB-34-05

C. On the Format Selections Page, select a MFD 1/2 page format icon from the top menu bar.

NOTE: The selected MFD 1/2 page format shows on the Format Selection Page.

- D. Select the MAINT (Maintenance) icon.
- E. Push the DONE button.
- F. On the Maintenance Menu, select the License icon.

NOTE: The Application License Management page shows on the MFD.

- G. On the Application License Management page, use the CCP to position the cursor over the scrolling bar such that the scrolling icons turn cyan.
- H. Rotate the CCP Knob to scroll through the list.
- I. (Reference Figure 3, Sheet 1.) Make sure the keys and their statuses are shown in green.
- 14. Do the takeoff and landing awareness key activation (TLAF-5000) as follows:
 - A. On the Application License Management page, push the Activation Key button.
 - B. Select the Activation Key data field.

NOTE: The Activation Key Data Field should be highlighted.

- C. With the use of the MKP, type in the Takeoff and Landing Awareness Key Authorization code number listed in the certificate of the software product authenticity.
- D. Push the ENTER button.

NOTE: On the Application License Management page, the annunciation "Processing" shows if a valid EAK is entered.

E. Using the table below, make sure that the key and the status shown are in green.

Standard Key Installation Requirement			
Description	P/N	Quantity	Status
TLAF-5000 Takeoff and Landing Awareness Key	810-0165-001	1	Enabled

- 15. Do the Periodic Database Field Procedure.
 - A. For all King Air 200 Models, refer to the Super King Air B200GT/B200CGT Fusion Maintenance Manual, Chapter 31, Adaptive Flight display (AFD-3700) Maintenance Practices.
 - B. For all King Air 300 Models, refer to the Super King Air B300/B300C Fusion Maintenance Manual, Chapter 31, Adaptive Flight display (AFD-3700) Maintenance Practices.
- 16. Do the Input/Output Concentrator (IOC-3100) Test.
 - A. For all King Air 200 Models, refer to the Super King Air B200GT/B200CGT Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Adjustment/Test.
 - B. For all King Air 300 Models, refer to the Super King Air B300/B300C Fusion Maintenance Manual, Chapter 31, Input/Output Concentrator (IOC-3100) Adjustment/Test.

٠

SERVICE BULLETIN



MTB-34-05

- 17. Make an entry in the airplane logbook that states compliance and method of compliance with this service document.
 - **NOTE:** Textron Aviation recommends that compliance with all service documents is reported to a maintenance tracking system provider.
 - Complete a record of compliance. (Maintenance Transaction Report, Log Book Entry, or other record of compliance.)
 - Put a copy of the completed record of compliance in the airplane logbook.
 - Send a copy of the completed record of compliance to the maintenance tracking system provider used.

Reechcraft

Hawker

MTB-34-05

TEXTRON AVIATION

E76240

Electronic Nameplates for the Left I	Display
Type No: AFD-3700 Position: Left PNR 822-3065-001	
Type AFDR-3700 FAA TSO C113b DO-178B LEVEL A/D PNR 810-0346-003 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 8A471E74	MFR 0EFD0 DMF 2019-12-18
Type APCT-3700 FAA TSO C113a SEE INST MNL DO-178C Level A PNR 810-0422-007 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 28200E4E	MFR 0EFD0 DMF 2021-08-04
Type FDSA-6500 FAA TSO C113 SEE INST MNL DO-178B Level A PNR 810-0234-1H0006 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 E6209A77	MFR 0EFD0 DMF 2021-08-18
130M310006-0007 ICIT-130M310006-0007 BLACK LABEL ICIT ASSEMBLY 130M310006-0007 FUSION SOFTWARE PHASE 4+ CRC-32 CAFAC705	
Type IMAT-3700 FAA TSO C113a SEE INST MNL DO-178B Level A PNR 810-0352-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 D5BBAD7B	MFR 0EFD0 DMF 2017-04-11

Figure 1. Electronic Nameplates (Sheet 1)

Reechcraft Cessna Zarwker

MTB-34-05

Electronic Nameplates for the Left Displ	ay
Type No: AFD-3700 Position: Left PNR 822-3065-001	
Type FSA-6000 FAA TSO C165 SEE INST MNL DO-178B Level D PNR 810-0072-304 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 6C157BAD	MFR 0EFD0 DMF 2018-09-04
Type ECDA-8000 FAA TSO C113a SEE INST MNL DO-178B Level B PNR 810-0233-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 4C3CA1E6	MFR 0EFD0 DMF 2014-08-21
Type EICAS-6000 FAA TSO C113 SEE INST MNL DO-178B Level B PNR 810-0245-1H0025 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 A383A915	MFR 0EFD0 DMF 2021-08-11
Type RTSA-6000 FAA TSO C169a SEE INST MNL DO-178B Level B PNR 810-0048-702 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 74160978	MFR 0EFD0 DMF 2017-02-21
Type ATF-3510 FAA TSO C151c Class A DO-178C Level C PNR 810-0391-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 7E0D3428	MFR 0EFD0 DMF 2019-11-20
Type FMSA-8010 FAA TSO C148c Class Gamma 3 SEE INST MNL DO-178B Level B PNR 810-0163-1R0001 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 5B829061	MFR 0EFD0 DMF 2016-09-19
Type PMA-8000 FAA TSO C148c Class Delta 4 SEE INST MNL DO-178B Level B PNR 810-0192-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 C163C528	MFR 0EFD0 DMF 2014-10-20

Reechcraft

MTB-34-05

TEXTRON AVIATION

Electronic Nameplates for the Right Display		
Type No: AFD-3700 Position: Right PNR 822-3065-001		
Type AFDR-3700 FAA TSO C113b DO-178B LEVEL A/D PNR 810-0346-003 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 8A471E74	MFR 0EFD0 DMF 2019-12-18	
Type APCT-3700 FAA TSO C113a SEE INST MNL DO-178C Level A PNR 810-0422-007 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 28200E4E	MFR 0EFD0 DMF 2021-08-04	
Type FDSA-8500 FAA TSO C113 SEE INST MNL DO-178B Level A PNR 810-0234-1H0008 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 E6209A77 130M310008-0007 ICIT-130M310008-0007 BLACK LABEL ICIT ASSEMBLY 130M310008-0007 FUSION SOFTWARE PHASE 4+ CRC-32 CAFAC705	MFR 0EFD0 DMF 2021-08-18	
Type IMAT-3700 FAA TSO C113a SEE INST MNL DO-178B Level A PNR 810-0352-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 D5BBAD7B	MFR 0EFD0 DMF 2017-04-11	

Reechcraft Cessna Zarwker

MTB-34-05

Electronic Nameplates for the Right Displ	ay
Type No: AFD-3700 Position: Right PNR 822-3065-001	
Type FSA-8000 FAA TSO C185 SEE INST MNL DO-178B Level D PNR 810-0072-304 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 6C157BAD	MFR 0EFD0 DMF 2018-09-04
Type ECDA-6000 FAA TSO C113a SEE INST MNL DO-178B Level B PNR 810-0233-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 4C3CA1E6	MFR 0EFD0 DMF 2014-08-21
Type EICAS-6000 FAA TSO C113 SEE INST MNL DO-178B Level B PNR 810-0245-1H0025 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 A383A915	MFR 0EFD0 DMF 2021-08-11
Type RTSA-8000 FAA TSO C169a SEE INST MNL DO-178B Level B PNR 810-0048-702 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 74160978	MFR 0EFD0 DMF 2017-02-21
Type ATF-3510 FAA TSO C151c Class A DO-178C Level C PNR 810-0391-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 7E0D3428	MFR 0EFD0 DMF 2019-11-20
Type FMSA-6010 FAA TSO C146c Class Gamma 3 SEE INST MNL DO-178B Level B PNR 810-0163-1R0001 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 5B829061	MFR 0EFD0 DM/ 2016-09-19
Type PMA-8000 FAA TSO C148c Class Delta 4 SEE INST MNL DO-178B Level B PNR 810-0192-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 C163C526	MFR 0EFD0 DMF 2014-10-20

Reechcraft

MTB-34-05

TEXTRON AVIATION

E76480

Electronic Nameplates for the Center I	Display
Type No: AFD-3700 Position: Center PNR 822-3065-001	
Type AFDR-3700 FAA TSO C113b DO-178B LEVEL A/D PNR 810-0346-003 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 8A471E74	MFR 0EFD0 DMF 2019-12-18
Type APCT-3700 FAA TSO C113a SEE INST MNL DO-178C Level A PNR 810-0422-007 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 28200E4E Type FDSA-8500 FAA TSO C113 SEE INST MNL DO-178B Level A PNR 810-0234-1H0006 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US	MFR 0EFD0 DMF 2021-08-04 MFR 0EFD0 DMF 2021-08-18
CRC-32 E6209A77 130M310006-0007 ICIT-130M310006-0007 BLACK LABEL ICIT ASSEMBLY 130M310006-0007 FUSION SOFTWARE PHASE 4+ CRC-32 CAFAC705 Type IMAT-3700	
FAA TSO C113a SEE INST MNL DO-178B Level A PNR 810-0352-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 D5BBAD7B	MFR 0EFD0 DMF 2017-04-11

Figure 1. Electronic Nameplates (Sheet 5)

Reechcraft **Zarwker** TEXTRON ÀVIATION



Electronic Nameplates for the Center D	isplay
Type No: AFD-3700 Position: Center PNR 822-3065-001	
Type FSA-6000 FAA TSO C165 SEE INST MNL DO-178B Level D PNR 810-0072-304 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 6C157BAD	MFR 0EFD0 DMF 2018-09-04
Type ECDA-8000 FAA TSO C113a SEE INST MNL DO-178B Level B PNR 810-0233-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 4C3CA1E8	MFR 0EFD0 DMF 2014-08-21
Type EICAS-6000 FAA TSO C113 SEE INST MNL DO-178B Level B PNR 810-0245-1H0025 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 A383A915	MFR 0EFD0 DMF 2021-08-11
Type ODLA-3500 FAA TSO C113a SEE INST MNL DO-178B Level D PNR 810-0345-1R0001 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 937FF091	MFR 0EFD0 DMF 2016-09-07
Type OMSA-6000 FAA TSO C113a SEE INST MNL DO-178B Level C/D PNR 810-0106-251 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 2137DB81	MFR 0EFD0 DMF 2017-03-15
Type OMST-6000 FAA TSO C113a SEE INST MNL DO-178C Level C/D PNR 810-0099-1H0004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 014B1D30	MFR 0EFD0 DMF 2019-12-17
Type RTSA-6000 FAA TSO C169a SEE INST MNL DO-178B Level B PNR 810-0048-702 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 74160978	MFR 0EFD0 DMF 2017-02-21

Reechcraft

Tarwker

MTB-34-05


TEXTRON AVIATION

E76482

Electronic Nameplates for the Center Display		
Type No: AFD-3700 Position: Center PNR 822-3065-001		
Type ATF-3510 FAA TSO C151c Class A DO-178C Level C PNR 810-0391-004 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 7E0D3428	MFR 0EFD0 DMF 2019-11-20	
Type FMSA-6010 FAA TSO C146c Class Gamma 3 SEE INST MNL DO-178B Level B PNR 810-0163-1R0001 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 5B829061	MFR 0EFD0 DMF 2016-09-19	
Type PMA-6000 FAA TSO C146c Class Delta 4 SEE INST MNL DO-178B Level B PNR 810-0192-100 Rockwell Collins, Inc. Cedar Rapids, IA 52498 US CRC-32 C163C526	MFR 0EFD0 DMF 2014-10-20	

Figure 1. Electronic Nameplates (Sheet 7)

Reechcraft Cessna **Zarwker** TEXTRON AVIATION



E76318

	CAircr	aft Option Straps	V
	Pre	v 1 thru 1	2 of 252 Next
MAINTEN	ANCE	DF 2 Installed	C No 🔛
	TA T	TT/HDG 3 Installed	C No 👳
FDSA : 072-0840 MAY 19 20		ata Link Installed	
I/0 :	DF	F 1 installed	C No 🤝
	00 00000000 DH	ME 2 Installed	
0000000	60000000 FD	DR Installed	
WXR : O	GP	PS 2 Installed	C No 💎
	GP	PS 3 Installed	C No 🤝
	HF	F 1 Installed	
	IM	MS 1 Installed	
		DS Installed	C No 🤝
	та	ACAN 1 Installed	C No 💎
	AC Ser	ial Number	- AC Reg Number
	AC Sub	type 00 Invalid Sub-T	уре
		Last Saved: Thu Oct	26 13:16:03 2017
	Save Te	Cancel Change	s (Restore To Defaults)

Figure 2. Aircraft Straps (Sheet 1)

Reechcraft

MTB-34-05

TEXTRON AVIATION

E76246





Figure 2. Aircraft Straps (Sheet 2)

Reechcraft Cessna **Zarwker**



E76247

		CAircraft Option Straps		
		Prev 25 thru 36 of 251 Next		
	MAINTENANCE	Digital Pressurization		
MAINTENANCE		Third VHF Voice Installed CNo 💎		
FDSA	: 811-8063-1H0004D NOV 11 2019 14:21:05	Third VHF Data Installed		
1/0	:	TAWS Alt Callout Ctrl (CDisabled 👳		
DISCRETE		TAWS Voice Ctri CDisabled 💎		
A429 RCV		TAWS Steep Appr Ctrl (CDisabled 💎		
WXR	: •	Eng Caution Alert Callout CNo 💎		
		PED Vspeeds		
		SELCAL Char 1		
		SELCAL Char 2		
		SELCAL Char 3		
		SELCAL Char 4		
		AC Serial Number [] AC Reg Number []		
		AC Subtype 00		
		Last Saved: Mon Dec 2 15:35:47 2019		
		(Save To APM) (Cancel Changes) (Restore To Defaults)		

Figure 2. Aircraft Straps (Sheet 3)

Reechcraft

MTB-34-05

TEXTRON AVIATION

STANDARD KEY INSTALLATION REQUIREMENT				
Description	P/N	Quantity	Status	
ECH-3500 Electronic Charts Key	810-0361-001	1	Enabled	
FSAX-3500 FSA Extension (EDS IFIS)	810-0354-001	1	Enabled	
OVL-3500 Enhanced Maps Overlays Key	810-0360-001	1	Enabled	
TAWK-3510 Integrated Terrain Awareness &	810-0571-001	1	Enabled	
Warning System (iTAWS) Key				
CHTX-3500	810-0476-001	1	Enabled	
IFIS (Integrated Flight Information System) Chart				
Extension				
XMWX-3500	810-0355-001	1	Enabled	
XM Weather Software Kev			1	

SERVICE BULLETIN

Reechcraft **Tawke**



MATERIAL INFORMATION

Order the parts below to install this modification.

NEW P/N	QUAN- TITY	KEY WORD	OLD P/N	INSTRUCTIONS/ DISPOSITION
822-1361-623	2	Input/Output Concentrator (IOC)	822-1361-622	Return to Textron Aviation.

NOTE: Please contact Textron Aviation Parts Distribution for upgrade.

Contact the Textron Aviation Parts Distribution Repair Team to schedule your unit at citationrepair@txtav.com available 8:00 - 4:30 CST weekdays. Advance notification and coordination is required for Textron Aviation Parts Distribution Repair Team to effectively schedule units, ship to supplier and arrange return. A Customer Repair Request Form is available online at ww2.txtav.com/Parts that is required to ship with every repair. The expected turn time for the supplier supporting this service document is 21 days.

* Please contact your Regional Textron Aviation Parts Distribution Customer Support Team for current cost and availability of parts listed in this service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International).

For more information, please visit the TAPD Support & Aftermarket Account Management website at https://ww2.txtav.com/Parts/Promos/TAPD.

Based on availability and lead times, parts may require advanced scheduling.





TITLE

NAVIGATION - FIELD UPGRADED PROLINE FUSION PHASE 3 TO PHASE 4 SOFTWARE

TO:

Beechcraft B200 and B300 Model Aircraft Owners

REASON

For aircraft that were upgraded to Phase 3 Software in the field and will be upgraded to Phase 4 Software.

NOTE: The aircraft listed in the effectivity list must have previously complied with the service document SB 34-4171: Proline Fusion Upgrade to Phase 3 Software prior to completing this service document.

COMPLIANCE

DISCRETIONARY. This service document can be accomplished at the discretion of the owner.

LABOR HOURS

WORK PHASE		LABOR-HOURS	
Modification		8	
MATERIAL AVAILABILITY			
PART NUMBER	AVAILABILITY	COST	
822-1361-623REP	*	*	

NOTE: Please contact Textron Aviation Parts Distribution for upgrade.

Contact the Textron Aviation Parts Distribution Repair Team to schedule your unit at citationrepair@txtav.com available 8:00 - 4:30 CST weekdays. Advance notification and coordination is required for Textron Aviation Parts Distribution Repair Team to effectively schedule units, ship to supplier and arrange return. A Customer Repair Request Form is available online at ww2.txtav.com/Parts that is required to ship with every repair. The expected turn time for the supplier supporting this service document is 21 days.

* Please contact your Regional Textron Aviation Parts Distribution Customer Support Team for current cost and availability of parts listed in this service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International).

For more information, please visit the TAPD Support & Aftermarket Account Management website at https://ww2.txtav.com/Parts/Promos/TAPD.

Based on availability and lead times, parts may require advanced scheduling.

In cases where the required part(s) are approved as exchange, order the exchange part and, upon completion, expedite the return of the removed part to avoid return penalties. Contact the Textron Aviation Parts Distribution Sales Desk for availability of exchange parts.

WARRANTY

Eligible airplanes exhibiting conditions described in this service document may demonstrate improved operation by incorporation of the work described herein. This service document is to be accomplished at

September	16,	2022
-----------	-----	------

MTB-34-05 Page 1 of 2

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

COPYRIGHT © 2022

OWNER ADVISORY

Reechcraft

EXTRON AVIATION

MTB-34-05

the *discretion* of the owner. Eligible airplanes may qualify for parts and labor coverage to the extent noted in the *Labor Hours* and *Material Availability* sections of this document.

- **Eligibility:** Airplanes identified within the serial number effectivity of this service document must have active Airframe warranty coverage on the original issue date of this document and the coverage must be active on the day the work is accomplished.
- **Parts Coverage:** Textron Aviation-owned and Textron Aviation-authorized Service Facilities, operators, or other maintenance facilities may submit a claim for the parts required to accomplish this service document as defined in the *Material Availability* section of this document.
- **Labor Coverage:** Textron Aviation-owned and Textron Aviation-authorized Service Facilities rated to perform maintenance on the specific model of Breechcraft Aircraft may submit a claim for the labor necessary to accomplish this service document as defined in the *Labor Hours* section of this document.
 - **Credit** After this service document has been accomplished, a claim must be submitted to Textron **Application:** Aviation within 30 days of the service document completion. Claims for compliance of this service document are to be filed as a W4 type claim.

Please submit your claim form online at *ww2.txtav.com/Parts* or email the completed Textron Aviation Claim Form to *warranty@txtav.com*. If submitted on-line a Return Authorization will be provided. If a paper claim is submitted your claim will be entered into the system and a Return Authorization will be sent to you.

The Return Authorization must accompany any required return parts (see *Material Availability*), to the point of purchase.

Parts to be returned to Textron Aviation Parts Distribution should be forwarded to:

Textron Aviation Parts Distribution Warranty Administration 285 South Greenwich Road Bldg B89, Docks 1-4 Wichita, KS 67206 USA

Expiration: September 16, 2024 (after this date the owner/operator assumes the responsibility for compliance costs)

Textron Aviation reserves the right to void continued airplane warranty coverage for the parts affected by this service document until the service document is accomplished.

NOTE: As a convenience, service documents are now available online to all our customers through a simple, free-of-charge registration process. If you would like to sign up, please visit the Customer Access link at www.txtavsupport.com to register.