### **PRATT & WHITNEY CANADA**

## **SERVICE BULLETIN**

P&WC S.B. No. 41028R1

# BULLETIN INDEX LOCATOR 72-30-05

TURBOSHAFT ENGINE
CENTRIFUGAL IMPELLER - REPLACEMENT OF


MODEL APPLICATION

PT6C-67C

Compliance: CATEGORY 10

Summary: This service bulletin introduces a new impeller with an initial lower recommended

service life for a limited number of engines.



Jan 24/2007 Revision No. 1: May 05/2008 PT6C-72-41028 Cover Sheet

24-Hour Global Service <b>HELP DESK</b>	USA & CANADA1-800-268-8000 International(IAC*)+8000-268-8000	Other1-450-647-8000 Fax1-450-647-2888
Toll free where available (SIL GEN-027)	* International Access Code	Web Site www.pwc.ca

#### WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:

VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Pratt & Whitney Canada Corp. 1000, Marie-Victorin Longueuil, Québec, Canada J4G 1A1 Tél. 450-677-9411



05 May 2008

P&WC S.B. No. 41028R1

## REVISION TRANSMITTAL SHEET TURBOSHAFT ENGINE MODEL PT6C

SUBJECT: Pratt & Whitney Canada Service Bulletin No. PT6C-72-41028, Rev. No. 1, dated May 05/2008 (P&WC S.B. No. 41028R1) CENTRIFUGAL IMPELLER - REPLACEMENT OF

Replace your existing copy of this service bulletin with the attached revised bulletin. Destroy the superseded copy.

Please retain this Revision Transmittal Sheet with the revised bulletin.

#### SUMMARY: This revision is issued to:

- correct the engine effectivity in para. 1.A.,
- · change the compliance code in para. 1. E.,
- · remove material information in para. 2. B.,
- remove manpower information in para. 2. C.,
- delete P/N 3072642-01 in para. 2.D. which was cancelled before entering into service,
- change part interchangeability in para. 2.D., and
- remove disposition instruction in para. 2.D.

#### EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT:

None.

NOTE: A black bar in the left margin indicates a change in that line of text or figure.

#### **REVISION HISTORY:**

Original Issue: Jan 24/2007 Revision No. 1: May 05/2008

### PRATT & WHITNEY CANADA **SERVICE BULLETIN**

P&WC S.B. No. 41028R1

### TURBOSHAFT ENGINE CENTRIFUGAL IMPELLER - REPLACEMENT OF

#### 1. Planning Information

#### Α. Effectivity

Revised service life impeller introduced in production for PT6C-67C Engines Serial No. PCE-KB0189 thru PCE-KB0220 and PCE-KB0225 thru PCE-KB0236 inclusive.

#### B. Concurrent Requirements

None.

#### C. Reason

#### (1) Problem

The centrifugal impeller with the current recommended service life is not available.

#### (2) Cause

The centrifugal impeller has properties within the material specification but not within the current P&WC engineering tolerance band.

#### (3) Solution

Introduce a new impeller with an initial lower recommended service life.

#### D. Description

Replace the centrifugal impeller.

#### E. Compliance

CATEGORY 10 - For information and configuration purposes only.

#### Approval

D.O.T./D.A.A. approved.

#### G. Weight and Balance

None.

#### H. Electrical Load Data

Not changed.

#### Software Accomplishment Summary Ι.

Not applicable.

P&WC No. D8754B, D8754C, D8754D, D8754E, D8754L, D8754B/1 P&WC Proprietary Information. Subject to the restrictions on the back of the locator. Jan 24/2007

© 2007 Pratt & Whitney Canada Corp. Revision No. 1: May 05/2008 PRINTED IN CANADA

## SERVICE BULLETIN

P&WC S.B. No. 41028R1

## TURBOSHAFT ENGINE CENTRIFUGAL IMPELLER - REPLACEMENT OF

- Planning Information (Cont'd)
  - J. References

Applicable PT6C Technical Manuals

K. Publications Affected

Applicable PT6C Technical Manuals

L. Interchangeability and Intermixability of Parts

Interchangeability - Refer to Para. 2.D.

Intermixability - Not changed.

- 2. Material Information
  - A. Industry Support Information

Not applicable.

B. Material - Cost and Availability

Not applicable.

C. Manpower

Not applicable.

D. Material Necessary for Each Engine

The quantity of materials listed in this section is on a per engine basis.

Est. Unit List Price (\$US, Instructions New P/N Keyword Old P/N Qty 2008) Disposition 3072641-01 Impeller, Centrifugal 3055309-01 1 NP (A)

- (A) TWO WAY INTERCHANGEABLE (ATA 200 Explanation Code 02): The old or the new part can replace the old or the new part.
  - E. Reidentified Parts

None.

F. Tooling - Price and Availability

Not applicable.

P&WC Proprietary Information. Subject to the restrictions on the back of the locator. Jan 24/2007 Revision No. 1: May 05/2008

**PT6C-72-41028** Page 2 of 3

# SERVICE BULLETIN

P&WC S.B. No. 41028R1

## TURBOSHAFT ENGINE CENTRIFUGAL IMPELLER - REPLACEMENT OF

### 3. Accomplishment Instructions

- A. Write accomplishment of P&WC S.B. No. 41028 in the applicable engine module log book.
- 4. Appendix

Not applicable.

**PT6C-72-41028** Page 3 of 3

Revision No. 1: May 05/2008