

TASK CARD

Sub-Task NUMBER		REFERENCE	DEFECT/WORK REQUIRED	RECTIFICATION DETAILS		Performed By:	Released (CRS) By:
292722861		SB 292 72 2861	SB 292 72 2861, ACCESSORY GEARBOX FRONT COVER. DETECTION OF WEAR ON THE 41- OR 42-TOOTH GEAR FRONT BEARING HOUSING.	PERFORMED SB 292 72 2861, ACCESSORY GEARBOX FRONT COVER DETECTION OF WEAR ON THE 41- OR 42- TOOTH GEAR FRONT BEARING HOUSING. FOUND BOTH LH + RH FOLLOWING INSPECTION RESULTS COMPLIANT (≤ 0.15mm), REFER ATTACHED COMPLIANT CERTIFICATE. REMOVED ITEMS P/N & S/N : N/A INSTALLED ITEMS P/N & S/N : N/A REMARK: N/A NON SERIAL ITEMS USED P/N : N/A		PS	PS
292732822		SB 292 73 2822	SB 292 73 2822, VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) DRIVE-LINK SPLINES.	PERFORMED SB 292 73 2822, VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) DRIVE LINK SPLINES. FOUND BOTH HMU SPLINES COMPLIANT. REFER ATTACHED COMPLIANT CERTIFICATE. REMOVED ITEMS P/N & S/N 0292 861 920 SN: 40140 (LH) 0292 861 920 SN: 33001 (RH) INSTALLED ITEMS P/N & S/N 0292 861 920 SN: 40140 (LH) 0292 861 920 SN: 33001 (RH) REMARK: N/A NON SERIAL ITEMS USED P/N : N/A		PS	PS
292732869		SB 292 73 2869	SB 292 73 2869, CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER.	CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER CARRIED OUT. N.A. W/SB 292 73 2869 FOUND SATIS. REMOVED ITEMS P/N & S/N : N/A INSTALLED ITEMS P/N & S/N P/N: JAD0592A 1. LH. S/N: 10999 2. RH S/N: 11091 REMARK: N/A NON SERIAL ITEMS USED P/N : N/A		PS	PS

The work recorded above has been carried out in accordance with the requirement of the FAA airworthiness regulations for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.