

SERVICE BULLETIN No. 319 73 4850

Version: C

Date: 6 June 2023

Reason for update: This SB expired as a result of:
 - The end of the 6-month applicability period issued in version A on July 2022
 - The publication of the corrective action as specified in SB no. 319 73 4852 (Fuel system - Replacement of the preference injector)

Modification

Periodical action

One-off action

Applicable from:

“Upon receipt of this SB”

Subject:

Preventive flame-out check via the preference injector valve test.

| APPLICABLE ENGINE / VARIANT(S) | EFFECTIVITY CODE | MAINTENANCE LEVEL | CONDITION OF APPLICATION | OPERATIONAL EFFECT |
|--------------------------------|------------------|-------------------|--------------------------|--------------------|
| ARRIUS 2 F | S | 1 | SB expired | |
| | | 2, 3, 4 | SB expired | |

This SB must be done in full compliance with manufacturer instructions. Refer to the Effectivity Code found in the table above.