


## SAFETY INFORMATION NOTICE

**SUBJECT:** GENERAL – Suspension Lug MS3314

Note on Non-Conformity of Batch DFT11K005-085



| AIRCRAFT CONCERNED | Version(s)   |                            |
|--------------------|--|----------------------------|
|                    | Civil  | Military                   |
| EC120              | B  | –                          |
| AS350              | B, BA, BB, B1, B2, B3, D   | L1                         |
| AS550              | –  | A2, C2, C3, U2             |
| AS355              | E, F, F1, F2, N, NP  | –                          |
| AS555              | –  | AF, AN, SN, UF, UN, (AP)   |
| EC130              | B4, T2   | –                          |
| SA365 / AS365      | C, C1, C2, C3, N, N1, N2, N3   | F, Fs, Fi, K, K2           |
| AS565              | –  | MA, MB, SA, SB, UB, MBe    |
| SA366              | G1   | GA                         |
| EC155              | B, B1  | –                          |
| SA330              | J  | Ba, L, Jm, S1, Sm          |
| SA341              | G  | B, C, D, E, F, H           |
| SA342              | J  | L, L1, M, M1, Ma           |
| ALOUETTE II        | 313B, 3130, 318B, 318C, 3180   | –                          |
| ALOUETTE III       | 316B, 316C, 3160, 319B   | –                          |
| LAMA               | 315B   | –                          |
| EC225              | LP   | –                          |
| EC725              | –  | AP                         |
| AS332              | C, C1, L, L1, L2   | B, B1, F1, M, M1           |
| AS532              | –  | A2, U2, AC, AL, SC, UE, UL |
| EC175              | B  | –                          |
| (EC339)            | –  | (KUH/Surion)               |
| H160               | B  | –                          |
| BO105              | C (C23, CB, CB-4, CB-5), D (DB, DBS, DB-4, DBS-4, DBS-5), S (CS, CBS, CBS-4, CBS-5), LS A-3, LS A-3 Superlifter      | E-4                        |
| MBB-BK117          | A-1, A-3, A-4, B-1, B-2, C-1, C-2, C-2e, D-2, D-2m, D-3, D-3m  | D-2m, D-3m                 |
| EC135              | T1, T2, T2+, T3, P1, P2, P2+, P3, EC635 T1, EC635 T2+, EC635 T3, EC635 P2+, EC635 P3, T3H, P3H, EC635 T3H, EC635 P3H | –                          |

## No. 3887-S-00

Airbus Helicopters was informed that an in-service suspension lug MS3314 (Fig. 1) failed on an aircraft. Further investigations by the supplier showed a manufacturing issue resulting in fatigue failure of this component. This non-conformity is **limited to batch** DFT11K005-085.

Airbus Helicopters herewith affirms that affected suspension lugs MS3314 of batch DFT11K005-085 **were neither installed** on helicopters at delivery **nor delivered** to customers by Airbus Helicopters.

Nevertheless, equipment not supplied by Airbus Helicopters may be affected and may endanger safe operation of any aircraft or people on ground.

**NOTE** This suspension lug MS3314 is installed on the following specific mountings but not limited to:

- Rocket Launcher FZ220, FZ225, FZ231, FZ233
- Gun Pod HMP400
- Ingwe Missile Launcher
- Rocket Launcher M-159 2-1/A
- Cannon Pod NC621 V16, NC621 V18.




Fig. 1: Affected Suspension Lug with P/N and batch number (schematic view – order of data may vary)