



HELICOPTERS DIVISION

## TECHNICAL INFORMATION LETTER

TIL N° T-139-22-010

DATE: October 05, 2022

REV.: /

---

To: Leonardo Helicopters products  
Owners / Operators / Service Centres

**SUBJECT: AW139 – Forward Cabin Roof Ceiling Harness Inspection  
(STA 3120 – 3340) – Release of Alert SB139-731**

Helicopters Affected: AB/AW139

Dear Customer,

With the present letter Leonardo Helicopters (LH) is providing information in advance on Alert Service Bulletin (ASB) ASB139-731 under release, applicable to all AB/AW139 helicopters.

Based on recent reporting and related analysis performed, LH decided to publish the Alert Service Bulletin (ASB) ASB139-731 in order to prescribe a one-off inspection of the Forward Cabin Roof Ceiling Harnesses and its installation in the area between STA 3120 and 3340. The ASB will also prescribe to verify the clearance of the harnesses from the surrounding components and provide instruction on how to restore it if necessary.

Should you need any additional information, please do not hesitate to refer to LH Engineering Support team ([engineering.support.lhd@leonardo.com](mailto:engineering.support.lhd@leonardo.com)).

Yours Sincerely,

A handwritten signature in black ink that reads "Gabriele Bordino".

---

Gabriele Bordino  
Head of Product Support Engineering

---