



## TECHNICAL INFORMATION LETTER

TIL N° T-139-23-003  
DATE: April 12, 2023  
REV.: /

To: Leonardo Helicopters products  
AB/AW139 Owners / Operators / Service Centres

**SUBJECT: Life Raft Inflation System Replacement**

Helicopters Affected: AB/AW139 helicopters

Dear Customer,

With the present letter Leonardo Helicopters (LH) would like to inform you about the upcoming issuance of the Alert Service Bulletin (ASB) ASB139-734 concerning the Helicopters equipped with the life raft kits:

- KIT EMERGENCY FLOTATION SYSTEM AND LIFE RAFTS P/N 3G9560F00111;
- KIT EMERGENCY FLOTATION SYSTEM AND LIFE RAFTS P/N 3G9560F00112;
- KIT LIFE RAFTS P/N 4G2560F00811.

An event was reported of a valve of a spare inflation system that was found broken after shipment due to an inappropriate packaging. The ASB139-734, that will be endorsed by an EASA Airworthiness Directive, will be released to provide the instructions for the replacement of a limited batch of life raft inflation systems P/N 202402A (RFD P/N 45521002) and P/N 202256A (RFD P/N 45521003) that have been shipped with the same packaging conditions.

Customers should contact [product-support@sekur.aero](mailto:product-support@sekur.aero) or Leonardo Helicopters in order to receive a life raft inflation system, providing evidence about S/N of the affected item to be replaced.

Should you need any additional information, please do not hesitate to refer to your usual contact within LH Engineering Support team.

Yours Sincerely,

A handwritten signature in black ink, appearing to read "Marco D'Adamo", written over a horizontal line.

Marco D'Adamo  
Head of Product Support Engineering