



LOG OF TEMPORARY CHANGES

**Super King Air® 350, 350i & 350C
(Models B300 & B300C)**

(FL-493, FL-500 and After; FM-14 and After)

**Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235

October, 2023

Temporary Changes to this manual must be in the airplane for all flight operations.

PART NUMBER	SUBJECT	DATE
130-590031-235TC1	Not yet issued.	---
130-590031-235TC2	Not yet issued.	---
130-590031-235TC3	Incorporated into the 130-590031-235A4 revision. Please discard all 130-590031-235TC3 pages: 1 of 4 thru 4 of 4.	Incorporated
130-590031-235TC4	Incorporated into the 130-590031-235A4 revision. Please discard all 130-590031-235TC4 pages: 1 of 4 thru 4 of 4.	Incorporated
130-590031-235TC5	Not yet issued.	---
130-590031-235TC6	Incorporated into the 130-590031-235A6 revision. Please discard all 130-590031-235TC6 pages: 1 of 6 thru 6 of 6.	Incorporated
130-590031-235TC7	Add additional Lighting Systems description for Cabin Lights (350 & 350C) in Section 7 - SYSTEMS DESCRIPTION.	October, 2010
130-590031-235TC8	Incorporated into the 130-590031-235A6 revision. Please discard all 130-590031-235TC8 pages: 1 of 6 thru 6 of 6.	Incorporated

Log Of Temporary Changes (Cont'd)

P/N 130-590031-235

Revised October, 2023

PART NUMBER	SUBJECT	DATE
130-590031-235TC9	Add information for airplanes with Rockwell Collins, Inc. TCAS II System (Version 7.1) installed to Section 7 - SYSTEMS DESCRIPTION.	March, 2012
130-590031-235TC10	Not yet issued.	---
130-590031-235TC11	Changed Maximum Continuous Power definition in Section 1 - GENERAL.	October, 2023
130-590031-235TC12	Added Hartzell propeller blade model number in Section 2 - LIMITATIONS.	October, 2017
130-590031-235TC13	Added FMS Limitations for Temperature Compensations Section 2 - LIMITATIONS.	June, 2021

NOTE: This page should be filed in the front of the manual immediately in front of the *Log Of Revisions* page(s). This page replaces any *Log Of Temporary Changes* page dated prior to the date of this Log.

Hawker Beechcraft Corporation
Model B300/B300C

**Temporary Change
to the
Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235TC7

Publication Affected: Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (P/N 130-590031-235, Issued August, 2006 or Subsequent)

Airplane Serial Numbers Affected: FL-493, FL-500 and After; FM-14 and After

Description of Change: Adds additional Lighting Systems description for Cabin Lights (350 & 350C) in Section 7 - SYSTEMS DESCRIPTION.


Filing Instructions: Remove *Log of Temporary Changes* dated December, 2009 and insert the new *Log of Temporary Changes* dated October, 2010.

Insert Pages 1 of 4 and 2 of 4 into the Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual immediately following the *Log of Temporary Changes*.

Insert Pages 3 of 4 and 4 of 4 immediately following Page 7-58 in Section 7 - SYSTEMS DESCRIPTION.

Retain the temporary change pages until rescinded or replaced.

FAA Approved
by: _____

for 

Randolph Shields, ODA Lead Administrator
Hawker Beechcraft Corporation
ODA-230339-CE

THIS PAGE INTENTIONALLY LEFT BLANK

**Temporary Change
to the
Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235TC9

Publication Affected: Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (P/N 130-590031-235, Issued August, 2006 or Subsequent)

Airplane Serial Numbers Affected: FL-493, FL-500 and After; FM-14 and After

Description of Change: Add information for airplanes with Rockwell Collins, Inc. TCAS II System (Version 7.1) installed to Section 7 - SYSTEMS DESCRIPTION.

Filing Instructions: Remove *Log of Temporary Changes* dated November, 2011 and insert the new *Log of Temporary Changes* dated March, 2012.


Insert Pages 1 of 6 and 2 of 6 into the Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual immediately following the *Log of Temporary Changes*.

Insert Pages 3 of 6 and 4 of 6 immediately following Page 7-132 in Section 7 - SYSTEMS DESCRIPTION.

Insert Pages 5 of 6 and 6 of 6 immediately following Page 7-134 in Section 7 - SYSTEMS DESCRIPTION.

Retain the temporary change pages until rescinded or replaced.

FAA Approved
by: _____



Randolph Shields, ODA Lead administrator
Hawker Beechcraft Corporation
ODA-230339-CE

THIS PAGE INTENTIONALLY LEFT BLANK

**Temporary Change
to the
Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235TC11

Publication Affected: Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (P/N 130-590031-235, Issued August, 2006 or Subsequent).

Airplane Serial Numbers Affected: FL-493, FL-500 and After, FM-14 and After.

Description of Change: Changed Maximum Continuous Power definition.

Filing Instructions: Remove *Log of Temporary Changes* dated June, 2021 and insert the new *Log of Temporary Changes* dated October, 2023.

Insert Pages 1 of 4 and 2 of 4 into the Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual immediately following the *Log of Temporary Changes*.

Insert Pages 3 of 4 and 4 of 4 immediately following Page 1-18 in Section 1 - GENERAL.

Retain the temporary change pages until rescinded or replaced.



Chad Groene, ODA Deputy Administrator

APPROVED BY _____
Textron Aviation Inc.
Organization Designation Authorization ODA-100129-CE
FAA Approved Under 14 CFR Part 183 Subpart D


THIS PAGE INTENTIONALLY LEFT BLANK

**Temporary Change
to the
Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235TC12

Publication Affected:	Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (P/N 130-590031-235, Issued August, 2006)
Airplane Serial Numbers Affected:	FL-493, FL-500 thru FL-1030, except FL-954 and FL-1010; FM-14 thru FM-65.
Description of Change:	Adds Hartzell propeller blade model number in Section 2 - LIMITATIONS.
Filing Instructions:	Remove <i>Log of Temporary Changes</i> dated March, 2013 and insert the new <i>Log of Temporary Changes</i> dated October, 2017. Insert Pages 1 of 4 and 2 of 4 into the Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual immediately following the <i>Log of Temporary Changes</i> . Insert Pages 3 of 4 and 4 of 4 immediately following Page 2-12 in Section 2 - LIMITATIONS. Retain the temporary change pages until rescinded or replaced.

FAA Approved by:



Larry Menestrina, ODA administrator
Textron Aviation Inc.
ODA-100129-CE

THIS PAGE INTENTIONALLY LEFT BLANK

**Temporary Change
to the
Pilot's Operating Handbook
and
FAA Approved Airplane Flight Manual**

P/N 130-590031-235TC13

Publication Affected:	Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (P/N 130-590031-235, Issued August, 2006)
Airplane Serial Numbers Affected:	FL-493, FL-500 thru FL-1030, except FL-954 and FL-1010; FM-14 thru FM-65.
Description of Change:	Adds FMS Limitations in Section 2 - LIMITATIONS.
Filing Instructions:	<p>Remove <i>Log of Temporary Changes</i> dated March, 2013 and insert the new <i>Log of Temporary Changes</i> dated June, 2021.</p> <p>Insert Pages 1 of 4 and 2 of 4 into the Model B300/B300C Pilot's Operating Handbook and FAA Approved Airplane Flight Manual immediately following the <i>Log of Temporary Changes</i>.</p> <p>Insert Pages 3 of 4 and 4 of 4 immediately following Page 2-22 in Section 2 - LIMITATIONS.</p> <p>Retain the temporary change pages until rescinded or replaced.</p>

FAA Approved by:



Stephen Gielisch, Lead ODA Administrator
Textron Aviation Inc.

Organization Delegation Authorization ODA-100129-CE
FAA Approved Under 14 CFR Part 183 Subpart D

THIS PAGE INTENTIONALLY LEFT BLANK