

TIC-A109E-22-0009

AD/SB ID: 7944 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: SB109EP-173 PART I (EVERY 100FH)(EASA AD NO.: 2020-0256)

Title/Subject: ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPE

AD/SB ID: 7944 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Task#	Job#	Title	Budget/Actual	Average	Priority
22180	-	SB109EP-173 PART I ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION AND REPAIR OF	0.00	0.00	

Task #: 89493 Created: 12/11/2020 Modified: 23/03/2022 Template ID: 22180 Save to template Close Update Save

General Accounts Production Time Allocations Documents ATA List History

Task Number: 0 Task ID: 89493

Job: 0 #0 Search Parent: 0 Search

Start Date: 12 11 2020 Created By: Continuing Airworthiness Manager

Due Date: 14 11 2020 Modified By: CAMO JBPM; Mohd Fikri

Defects/Title: SB109EP-173 PART I ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT Priority: Low

Reference/IAW: Status: WIP

Category:

Details/Rectification:

TO PERFORM INSPECTION TO DETECT CRACKS IN THE CENTER FUSELAGE AT INTERSECTION OF LATERAL PYLON (LH AND RH SIDE) WITH FLOOR SPAR

NOTES: THE HELICOPTERS POSTS THAT HAVE BEEN REPAIRED IN ACCORDANCE WITH PART II (LH SIDE) OR PART III (RH SIDE) OF THIS SERVICE BULLETIN, OR IN ACCORDANCE WITH REPAIR DRAWING P/N 109-0952-67-117 (LH SIDE) OR P/N 109-0952-67-102 (RH SIDE). SHALL BE INSPECTED IN ACCORDANCE WITH PART I AFTER THEY HAVE ACCUMULATED MORE THAN 1000 FH OF 3500 LANDINGS SINCE REPAIR

NOTES: PART II AND PART III SHOULD BE CARRIED OUT BEFORE THE NEXT FLIGHT AFTER THE CRACKS ARE FOUND DURING COMPLIANCE WITH PART I OF THE SERVICE BULLETIN.

REFERENCE: SB109EP-173 ERRATA CORRIGE

REMARKS: